Claim Audit

	AUDIT	TRAIL		
No.		Audit	Remarks	Ву
1	2020	Clm Veh Model Changed		[] Merimen Administrator
2	08 Dec 2020 00:47	Clm Created	Reg No: SDB7377J. Acct Date: 2020/12/02. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Lt d. (SG). Ins.Status => Notification. Created from SAS:SP0R20C40004	[I] Merimen Administrator
3		Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] Nivitha Govindasamy
4	14:48	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] Nivitha Govindasamy
5	14:48	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasamy
6	2020 14:48	Changed	Next Rpt:Final Rpt.Due Date:2020/12/17	[A] Nivitha Govindasamy
7	14:48	Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
8	14:48	Registration Modified	Rep:1137->200611.	[A] Nivitha Govindasamy
9	2020	Clm Veh Model Changed	(205109) AUDI A3 999cc TFSI S-TRONIC (A).	[A] Nivitha Govindasamy
10	2020 14:48	Adjuster Assigned	[None] -> MOHD RASUL	[A] Nivitha Govindasamy
11	16:05	Adj Rpt Initiated Insured		[A] HUEY YON
12	2020 16:05	Phone No Updated	[6593889556] -> [+656593889556]	[A] HUEY YON
13	16:05	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] HUEY YON
14	16:05	Clm Dtl Modified	JPJ Reg. Date: -> 2019/08/27.	[A] HUEY YON
15	16:05	Clm Details Notified Adj Im.		[A] HUEY YON
16	2020	Advice Submitted	Next Rpt:Final Rpt.Due Date:2020/12/17	[A] SHIAU CHAN
17	2020	Mandate Request	Cur.Req:25045.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN [I] Abu
18	2020	Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	Kassim, Noor Mariesa [A] Merimen
19	16:48	Label Added Adj Next	(20226):Coverage Confirmed. Next Rpt:Final Rpt.Due Date:2020/12/17. Mandate Remarks: Vehicle may commence repair. Labour no.	Administrator
20	2020	Rpt Changed	2 to have photos taken for the job carried out. Checked and Supplementary items to resurvey with CLEA R photos for damage and consistency. New gearbox photos Approved:21768.00:Vehicle may commence repair. Labour no. 2 to have photos taken for the job carried	[I] Lim, Kok- Chong
	20:36 15 Dec	Adj Im.	out. Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. New gearbox photos to be taken after installed to ve	Chong [A] SHIAU
22	10:15 15 Dec	-	Next Rpt:Final Rpt.Due Date:2020/12/17 Cur.Req:29767.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEM	CHAN [A] SHIAU
23		Mandate Request	ENTARY.	CHAN

3/2020	Wermen e-dams				
□ AUDIT TRAIL					
No. On Audit	Remarks	Ву			
15 Dec Adj Next 24 2020 Rpt 10:45 Changed 15 Dec Adj	2020 Rpt the job carried out. Checked and Supplementary items to resurvey with CLEAR photos for damage onsistency. New gearbox photos to be taken after instal				
25 2020 Mandate 10:45 Set	ary items to resurvey with CLEAR photos for damage and consistency. New gearbox photos to be taken a fter installed to vehicle and Old gearbox to be t				
Date From	■ Date To ■ ■ Audit Type None ➤	Go			
ACTIVITY					

ACTIVITY No record

Merimen Billing for this case - Transaction History													
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount					
2652512	08 Dec 2020 16:05:09	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SDB7377J		11.00					