

Borneo Motors



TOYOTA

Reg No. : 196700086Z
ST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			Account No. S1000003 / ICCI1		Customer Details M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518			
Document No. 0			Document Date 02/12/2020					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JHDFS1EKNXXX10048		E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: DMCVSNA00005742000 ACC DATE:26.11.2020 TOW IN:26.11.2020 EXCESS: DATE-IN:27.11.2020 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:						50 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)						300 500.00
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP						149.60
4	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR						880.00
5	B	BP-LAB2 R/I DASHBOARD ASSY TO FAC REPAIR						1760.00
6	B	BP-LAB2 R/I FRONT WINDSCREEN GLASS						880.00
7	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST						149.60
8	B	BP-LAB2 R/I AC CON BLOWER ASSY TO FAC REPAIR & R EGAS						880.00
9	B	BP-LAB2 R/I WIREHARNESS ASSY TO FAC REPAIR						880.00
10	B	BP-LAB2 R/I BRAKE BOOSTER SYSTEM TO FAC REPAIR						880.00
11	B	BP-LAB2 REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR						880.00
12	B	BP-LAB2 R/I ROOF LINING TO FAC REPAIR						1760.00
13	B	BP-LAB2 RESET ECU AND REPROGRAMME						220.00
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Company Copy



Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226	
		Document No. 0		
		Document Date 02/12/2020	Work: 64812518	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	S	BP-SUBLET REPLACE ACC DAMAGED PARTS @880 AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				4400 8800.00
15	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS @660				3960 6600.00
16	1	H52101-E0K21 BUMPER SUB-ASSY, FR bt	1.00	2265.00		2265.00
17	2	H52103-E0460 EXTENSION SUB-ASSY, FR BUMPER, LH bt	1.00	237.10		237.10
18	3	H53036-E0050 BRACKET SUB-ASSY, HE bt	1.00	202.60		202.60
19	4	HS8116-E0010 STAY, HEADLAMP, NO.2 mis	1.00	49.30		49.30
20	5	HS5218-81090 GARNISH, BUMPER, LH dis	1.00	172.10		172.10
21	6	HS5218-81100 GARNISH, BUMPER, LH X	1.00	154.90		154.90
22	7	H52713-E0010 MOULDING, FR BUMPER dis	1.00	17.00		17.00
23	8	HS5218-21010 REINFORCE, FR BUMPER bt	1.00	267.00		267.00
24	9	HS5219-81120 BRACKET, GRILLE bt	1.00	29.50		29.50
25	0	H53102-E0060 GRILLE SUB-ASSY, RAD mis	1.00	1023.10		1023.10
26	1	HS5052-E0160 STAY SUB-ASSY, FR UN	2.00	282.30		564.60
27	2	HS5110-E0121 MEMBER, ENGINE COVER dis bt	1.00	895.90		895.90
28	3	HS5066-E0071 STAY SUB-ASSY, STEP	1.00	155.40		155.40
29	4	HS510V-E0100 SUPPORT SUB-ASSY, ST bt	1.00	711.60		711.60
30	5	H94151-81201 NUT nec	6.00	1.90		11.40
31	6	HS5107-72381 STAY SUB ASSY, STEP bt	1.00	94.70		94.70

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Borneo Motors



TOYOTA

Reg No. : 196700086Z
ST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518		
			Document No.				
			0				
			Document Date				
			02/12/2020				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
32	7	H51771-E0050 BRACKET, TILT CAB ST <i>car/bt</i>	1.00	285.00		285.00
33	8	HS7917-01100 LEVER ASSY, LID LOCK <i>dis</i>	1.00	33.00		33.00
34	9	H81580-E0020 REFLECTOR ASSY, REFLE <i>bro</i>	1.00	17.00		17.00
35	0	HS506K-E0011 LID SUB-ASSY, STEPOP <i>bt</i>	1.00	114.20		114.20
36	1	HS506N-E0010 CONTROLOPENER SUBASS <i>cut</i>	1.00	89.70		89.70
37	2	HS51Q2-E0222 COVER, STEP, LH <i>de</i>	1.00	384.70		384.70
38	3	HSZ148-08001 SCREW, HEX LOBULAR <i>re</i>	8.00	3.60		28.80
39	4	HSZ178-05002 NUT, FLANGE <i>re</i>	2.00	1.50		3.00
40	5	HS7622-12050 HOLDER MUDGUARD ?	1.00	33.00		33.00
41	6	HS51QE-E0151 APRON, STEP, LH ?	1.00	146.20		146.20
42	7	HS51QH-E0130 MUDGUARD, STEP ?	1.00	47.50		47.50
43	8	H94151-80800 NUT <i>re</i>	1.00	1.50		1.50
44	9	HS691-20820 BOLT <i>re</i>	1.00	5.30		5.30
45	0	H55700-E0120 COWL <i>but</i>	1.00	2385.90		2385.90
46	1	H55101-E0100 PANEL SUB-ASSY, DASH <i>repair</i>	1.00	1970.30		1970.30
47	2	H52211-E0010 CUSHION, BODY MOUNT ?	2.00	8.80		17.60
48	3	H55701-E0040 PANEL SUB-ASSY, COWL ?	1.00	1130.70		1130.70
49	4	HS6114-61010 GUSSET, FR BODY PILL <i>for X</i>	1.00	57.50		57.50
50	5	H61164-E0011 PILLAR, FR BODY, LWR <i>bt</i>	1.00	316.20		316.20
51	6	HS6118-21010 BRACKET, INSTRUMENT <i>re</i>	1.00	8.80		8.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	

Company Copy

Borneo Motors



No. : 196700086Z
Reg No. : MR-8500000-9
PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No. 0 Document Date 02/12/2020	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
52	7	HS7630-71010 REINFORCEMENT SUB AS X	1.00	107.40		107.40
53	8	HS7630-71010 REINFORCEMENT SUB AS X	1.00	107.40		107.40
54	9	H53111-E0130 GRILLE, RADIATOR ?	1.00	2121.70		2121.70
55	0	HS7653-11460 EMBLEM X	1.00	211.60		211.60
56	1	HS7653-11460 EMBLEM ?	1.00	211.60		211.60
57	2	H55246-E0010 SEAL, FR PANEL, LWR X	1.00	99.90		99.90
58	3	HS7681-11160 WEATHERSTRIP, FR CRNE ne	1.00	54.20		54.20
59	4	HS7682-11300 WEATHERSTRIP, FR CORN ne	1.00	226.60		226.60
60	5	HS5337-81400 MEMBER, HOOD X	1.00	50.50		50.50
61	6	HS7682-11310 WEATHERSTRIP, FR CORN X	1.00	82.70		82.70
62	7	HS7686-11010 SEAL, FR PANEL, LWR RH X	1.00	103.40		103.40
63	8	HS7686-21010 SEAL, FR PANEL, LWR LH X	1.00	103.50		103.50
64	9	HS5339-01010 STRIKER ASSY, HOOD P X	2.00	17.30		34.60
65	0	HS7639-01051 STAY ASSY, DUMPER X	1.00	151.70		151.70
66	1	HS7918-01331 LOCK ASSY, LID X	2.00	90.70		181.40
67	2	HS7918-21010 HANDLE, LID LOCK X	2.00	24.00		48.00
68	3	H53804-E0010 REINFORCE SUB-ASSY, X	1.00	261.80		261.80
69	4	H53814-E0460 EXTENSION, FR FENDER X	1.00	648.00		648.00
70	5	HS5571-41010 PANEL, FR CORNER, LWR X	1.00	14.50		14.50
71	6	HSZ950-39050 RETAINER X	6.00	1.40		8.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Company Copy

Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226	
		Document No. 0		
		Document Date 02/12/2020	Work: 64812518	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
72	7	H55712-E0390 PANEL, COWL TOP, OUT	1.00	677.60		677.60
73	8	H75315-EW040 ORNAMENT, RADIATOR G	1.00	276.30		276.30
74	9	H75338-E0030 ORNAMENT, HOOD, LWR	1.00	185.10		185.10
75	0	H75353-E0160 ORNAMENT, FR FENDER,	1.00	113.70		113.70
76	1	H75425-E0580 ORNAMENT, FR DOOR, R	1.00	239.80		239.80
77	2	HS5701-71960 CROSSMEMBER SUB ASSY	1.00	167.60		167.60
78	3	HS5730-81010 BRACKET SUB ASSY, CTR	1.00	103.50		103.50
79	4	HS5813-E0030 BRACKET, CTR SEAT, F	1.00	121.20		121.20
80	5	HS5741-81010 BRACKET, FOOT REST	1.00	17.00		17.00
81	6	HS5741-91010 BRACKET, BRACE, LH	1.00	17.00		17.00
82	7	HS5767-11010 PLATE, FIRE EXTING U	2.00	8.30		16.60
83	8	HS5767-51010 PLATE, CTR SEAT GRIP	1.00	18.50		18.50
84	9	HS5767-61011 PLATE, CTR SEATBACK S	1.00	54.00		54.00
85	0	HS5785-22210 STIFFENER, FLOOR BOAR	1.00	515.00		515.00
86	1	HS5811-34611 PANEL, FLOOR, CENTER	1.00	861.20		861.20
87	2	H58207-E0090 CLAMP SUB-ASSY, PARK	1.00	54.20		54.20
88	3	H58319-E0010 RETAINER, JACK COVER	1.00	33.00		33.00
89	4	H57487-E0040 REINFORCEMENT, FLOOR SIDE MBR, NO.1 LH	1.00	320.00		320.00
90	5	H57420-E0053 MEMBER ASSY, FLOOR SIDE, LH	1.00	742.80		742.80
91	6	HS5716-41010 MEMBER, SEAT SET FR,	1.00	131.90		131.90

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Company Copy

Borneo Motors



TOYOTA

Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 6,2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226	
		Document No. 0		
		Document Date 02/12/2020	Work: 64812518	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
92	7	HS5717-21010 MEMBER, SEAT SET RR, ?	1.00	128.70		128.70
93	8	HS5742-31010 BRACKET, BED SET ?	1.00	19.30		19.30
94	9	HS5767-21010 PLATE, WASHER TANK S ?	1.00	8.30		8.30
95	0	H58242-E0040 GUS SET, WHEELHOUSE ?	1.00	729.10		729.10
96	1	HS5835-81150 SPLASHBOARD, FR, LH ?	1.00	111.90		111.90
97	2	H67002-E0360 PANEL SUB-ASSY, FR DOOR, LH <i>due</i>	1.00	2875.20		2875.20
98	3	HS6927-01310 HINGE ASSY, DOOR, ?	2.00	189.90		379.80
99	4	H67124-E0010 BRACKET, FR DOOR OUT ?	1.00	149.90		149.90
100	5	HS6802-E0040 GARNISH SUB-ASSY, DO ?	1.00	250.00		250.00
101	6	HSZ950-43029 STOPPER <i>new</i>	1.00	7.80		7.80
102	7	HS656-20620 BOLT <i>new</i>	5.00	1.60		8.00
103	8	HSK210-00612 SCREW <i>new</i>	1.00	1.60		1.60
104	9	HSK210-00616 SCREW <i>new</i>	1.00	1.40		1.40
105	0	H61132-E0120 PILLAR, FR BODY, UPR <i>bt</i>	1.00	603.50		603.50
106	1	H61612-E0030 PANEL, QUARTER, LH ?	1.00	1046.30		1046.30
107	2	H65622-E0010 PANEL, SIDE GATE, LH ?	1.00	107.50		107.50
108	3	H61107-E0021 PILLAR SUB-ASSY, FR, LH ?	1.00	260.60		260.60
109	4	H61136-E0020 REINFORCEMENT, FR BODY PILLAR, UPR LH ?	1.00	80.50		80.50
110	5	H61416-E0011 EXTENSION, ROCKER, OUTER LH ?	1.00	260.60		260.60
111	6	HS7981-12550 INSULATOR, BODY ?	1.00	3.10		3.10

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Company Copy

Borneo Motors



Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518		
			Document No.				
			0				
			Document Date				
			02/12/2020				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
112	7	H61109-E0011 REINFORCEMENT SUB-AS ?	1.00	249.10		249.10
113	8	HS6119-31300 STIFFENER, FIXTURE ?	1.00	14.30		14.30
114	9	HS6119-51200 BRACKET, FIXTURE ?	1.00	12.80		12.80
115	0	H61232-E0020 RAIL, ROOF SIDE, INN ?	1.00	143.70		143.70
116	1	HS6124-61010 REINFORCEMENT, ROOF ?	1.00	57.50		57.50
117	2	H61314-E0040 REINFORCEMENT, DOOR LOCK STRIKER, LH ?	1.00	198.40		198.40
118	3	HS6143-71010 PANEL, VENTILATER CO ?	1.00	19.00		19.00
119	4	HS6155-71160 REINFORCEMENT, DOOR L ?	1.00	5.30		5.30
120	5	H61618-E0042 PANEL, QUARTER, INNE ?	1.00	443.60		443.60
121	6	H61709-E0021 REINFORCEMENT SUB-AS ?	1.00	378.40		378.40
122	7	H67862-E0010 WEATHERSTRIP, FR DOO ?	1.00	217.60		217.60
123	8	HSZ105-08077 BOLT, WASHER BASED H ?	4.00	6.30		25.20
124	9	H74103-E0020 DOOR SUB-ASSY, FR AS ?	1.00	111.20		111.20
125	0	H67606-E0150 PANEL SUB-ASSY, FR D ?	1.00	677.90		677.90
126	1	H74202-E0021 PANEL SUB-ASSY, FR A ?	1.00	75.20		75.20
127	2	H74232-E0010 PANEL, FR DOOR ARMRE ?	1.00	125.40		125.40
128	3	H74220-E0010 ARMREST ASSY, DOOR, ?	1.00	47.50		47.50
129	4	H74640-E0020 GRIP ASSY, DOOR ASSI ?	1.00	118.90		118.90
130	5	HSZ950-39242 RETAINER ?	1.00	4.00		4.00
131	6	HS6921-01091 LINK ASSY, DOOR CHECK ?	1.00	93.50		93.50

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less Amount Due
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	

Company Copy

Borneo Motors



Reg No. : 196700086Z
ST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226	
		Document No. 0		
		Document Date 02/12/2020	Work: 64812518	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
132	7	H69320-E0032 LOCK ASSY, DOOR, LH Jam	1.00	201.80		201.80
133	8	HS6942-21010 LINK, DOOR LOCK, LH ?	1.00	14.00		14.00
134	9	HS6946-01150 STRIKER ASSY, DOOR, ?	1.00	29.50		29.50
135	0	H67801-E0010 COVER SUB-ASSY, FR D ?	1.00	7.80		7.80
136	1	H69820-E0051 REGULATOR ASSY, FR D ?	1.00	790.00		790.00
137	2	H67914-E0020 PLATE, DOOR SCUFF, L ?	1.00	52.50		52.50
138	3	H51774-E0130 COVER, STEP PLATE, L ?	1.00	332.00		332.00
139	4	HSZ148-08001 SCREW, HEX LOBULAR nee	1.00	3.60		3.60
140	5	HSZ166-06001 SCREW, HEX LOBULAR T nee	3.00	1.80		5.40
141	6	HSZ950-31015 NUT, SPRING nee	3.00	3.30		9.90
142	7	HSZ950-31021 NUT, SPRING nee	2.00	4.00		8.00
143	8	HSZ950-39347 RETAINER nee	4.00	3.30		13.20
144	9	H61454-E0130 COVER, FR STEP, LH Ca	1.00	410.60		410.60
145	0	HSZ950-39347 RETAINER X	4.00	3.30		13.20
146	1	HSZ950-44156 CUSHION X	3.00	1.40		4.20
147	2	SHH656-20620 BOLT X	3.00	1.60		4.80
148	3	H51771-E0050 BRACKET, TILT CAB ST Lt	1.00	285.00		285.00
149	4	H51772-E0020 PLATE, STEP, LH Ca	1.00	257.80		257.80
150	5	SHH653-20830 BOLT X	3.00	2.10		6.30
151	6	HS5571-61010 STAY, FR CORNER PANEL 3 Lt	1.00	19.00		19.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Company Copy

Borneo Motors



Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518			
			Document No. 0					
			Document Date 02/12/2020					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JHDFS1EKNXXX10048		E13CAT10536	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
152	7	H57036-E0010 PANEL SUB-ASSY, FR S <i>dis</i>			1.00	355.40		355.40
153	8	HS5704-E0010 SUPPORT SUB-ASSY, FR			1.00	323.20		323.20
154	9	HS5832-21080 COVER, STEP LWR, LH			1.00	135.40		135.40
155	0	HSZ178-08001 NUT, FLANGE <i>X</i>			3.00	1.00		3.00
156	1	H76621-E0041 MUDGUARD, FR FENDER			1.00	81.20		81.20
157	2	H76912-E0010 MUDGUARD, SIDE, LH <i>dis</i>			1.00	240.10		240.10
158	3	HSZ950-39274 RETAINER <i>X</i>			14.00	1.70		23.80
159	4	HSZ950-39275 RETAINER <i>X</i>			6.00	4.80		28.80
160	5	HS5830-91040 SPLASHBOARD SUB ASSY <i>?</i>			1.00	532.30		532.30
161	6	HSH656-20826 BOLT <i>X</i>			4.00	1.90		7.60
162	7	HS5370-52450 BRACKET SUB ASSY, FR <i>?</i>			1.00	142.90		142.90
163	8	HS5370-52480 BRACKET SUB ASSY, FR <i>?</i>			1.00	61.20		61.20
164	9	H53832-E0370 PANEL, FR FENDER SID <i>?</i>			1.00	394.90		394.90
165	0	HSZ108-08005 BOLT, SQUARE <i>X</i>			5.00	7.60		38.00
166	1	HSZ178-08001 NUT, FLANGE <i>X</i>			7.00	1.00		7.00
167	2	HSZ950-31021 NUT, SPRING <i>X</i>			3.00	4.00		12.00
168	3	HSH656-20822 BOLT <i>X</i>			2.00	7.30		14.60
169	4	HS5370-51240 BRACKET SUB ASSY, FR <i>X</i>			1.00	57.70		57.70
170	5	HS5372-21290 LINER, FR, FENDER, LH <i>?</i>			1.00	163.40		163.40
171	6	HS5740-21010 BRACKET SUB ASSY, SEA <i>X</i>			1.00	36.50		36.50
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total	
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Company Copy

Borneo Motors



Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No. 0 Document Date 02/12/2020	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
172	7	HSZ178-08001 NUT, FLANGE X	3.00	1.00		3.00
173	8	HS656-20822 BOLT X	1.00	7.30		7.30
174	9	HS5530-12091 PANEL SUB ASSY, INSTR	1.00	1240.80		1240.80
175	0	H55835-E0070 DUCT, HEATER TO REGI	1.00	253.30		253.30
176	1	H55844-E0030 DUCT, HEATER TO REGI	1.00	101.70		101.70
177	2	HS8724-41090 DUCT, HEATER TO FOOT	1.00	64.50		64.50
178	3	H55330-E0061 REINFORCEMENT ASSY,	1.00	849.00		849.00
179	4	H55990-E0030 NOZZLE ASSY, DEFROST	1.00	267.30		267.30
180	5	HS8727-42240 HOSE, DEF ?	1.00	45.30		45.30
181	6	HS8727-42250 HOSE, DEF ?	1.00	45.30		45.30
182	7	HSZ950-39161 RETAINER ?	2.00	2.10		4.20
183	8	HS5337-81400 MEMBER, HOOD ?	1.00	50.50		50.50
184	9	HS7682-11310 WEATHERSTRIP, FR CORN ?	1.00	82.70		82.70
185	0	HS7686-11010 SEAL, FR PANEL, LWR RH ?	1.00	103.40		103.40
186	1	HS7686-21010 SEAL, FR PANEL, LWR LH ?	1.00	103.50		103.50
187	2	H87094-E0590 STAY SUB-ASSY, OUT R ?	1.00	603.40		603.40
188	3	HS87C2-E0070 STAY, OUTER RR VIEW ?	1.00	89.70		89.70
189	4	H56121-E0031 MOULDING ne ✓	1.00	457.10		457.10
190	5	T21000-20 SIKA 182010 SIKA TACK GO! (BLA ne ✓	2.00	108.00		216.00
191	6	T21000-22 SIKA 207. G+P ADHESIVE PRIMER ne ✓	2.00	200.00		400.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Company Copy



Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	M/S Double-Trans Pte Ltd
	Document No. 0	4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
	Document Date 02/12/2020	Work: 64812518

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
192	7	H62220-E0040 GARNISH ASSY, FR PILLAR, LH ?	1.00	98.20		98.20
193	8	H62512-E0091 BOARD, QUARTER TRIM, ?	1.00	236.80		236.80
194	9	H73135-E0030 COVER, SHOULDER BELT ?	1.00	38.30		38.30
195	0	H62312-E0012 WEATHERSTRIP, FR DOOR ?	1.00	292.30		292.30
196	1	H74603-E0030 GRIP SUB-ASSY, ASSIS ?	1.00	156.40		156.40
197	2	H74604-E0030 GRIP SUB-ASSY, INSTR ?	1.00	139.20		139.20
198	3	H74612-E0060 COVER, ASSIST GRIP ?	2.00	8.30		16.60
199	4	HSH656-20826 BOLT X	2.00	1.90		3.80
200	5	HSH691-10816 BOLT X	2.00	5.30		10.60
201	6	H87010-E0171 UNITASSY, AIR CONDIT ?	1.00	2126.20		2126.20
202	7	H87130-E0120 BLOWER ASSY ?	1.00	838.50		838.50
203	8	H88703-E0050 HOSE SUB-ASSY, DISCH ?	1.00	426.10		426.10
204	9	HS8870-41770 TUBE SUB ASSY, LIQUID ?	1.00	298.30		298.30
205	0	H88704-E0010 HOSE SUB-ASSY, SUCTI ?	1.00	390.70		390.70
206	1	HS8871-44100 TUBE, LIQUID ?	1.00	86.20		86.20
207	2	H88704-E0010 HOSE SUB-ASSY, SUCTI ?	1.00	390.70		390.70
208	3	HS8871-44100 TUBE, LIQUID ?	1.00	86.20		86.20
209	4	HS8841-21930 BRACKET, CONDENSER ?	1.00	57.70		57.70
210	5	H88460-E0101 CONDENSER ASSY 5/8	1.00	1898.90		1898.90
211	6	HS8850-32170 BRACKET SUB ASSY, COOL 5/8	1.00	107.20		107.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Company Copy



Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1183

ESTIMATE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518			
			Document No.					
			0					
			Document Date					
			02/12/2020					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JHDFS1EKNXXX10048		E13CAT10536	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
212	7	H82214-E0150 WIRE, HEATER CONTROL <i>cut</i>			1.00	51.50		51.50
213	8	H81110-E0682 HEADLAMP ASSY <i>X</i>			1.00	750.30		750.30
214	9	H81150-E0682 HEADLAMP ASSY, LH <i>cm</i>			1.00	750.30		750.30
215	0	H81360-E0090 LAMP ASSY, CORNERING <i>X</i>			1.00	148.70		148.70
216	1	H81390-E0090 LAMP ASSY, CORNERING <i>?</i>			1.00	148.70		148.70
217	2	HSZ950-39072 RETAINER <i>X</i>			4.00	2.40		9.60
218	3	HSK541-04016 SCREW, BINDING TAPPI <i>X</i>			4.00	2.30		9.20
219	4	H81510-E0091 LAMP ASSY, FR TURN S <i>X</i>			1.00	156.40		156.40
220	5	H81520-E0091 LAMP ASSY, FR TURN S <i>mb</i>			1.00	156.40		156.40
221	6	H81730-E0081 LAMP ASSY, SIDE TURN <i>?</i>			1.00	93.20		93.20
222	7	H51701-E0300 COVER SUB-ASSY, SIDE <i>?</i>			1.00	1101.90		1101.90
223	8	H51702-E0200 COVER SUB-ASSY, STEP <i>?</i>			1.00	1061.70		1061.70
224	9	H54960-E0282 SPRING ASSY, TILT CA <i>?</i>			1.00	2875.20		2875.20
225	0	HS500Q-E0040 BRACKET SUB-ASSY, TI <i>?</i>			1.00	525.50		525.50
226	1	HS500R-E0040 BRACKET SUB-ASSY, TI <i>?</i>			1.00	525.50		525.50
227	2	HS5032-E0051 LEVER SUB-ASSY, TILT <i>?</i>			1.00	3423.40		3423.40
228	3	HS50A0-E0140 ABSORBER ASSY, CAB F <i>?</i>			2.00	181.00		362.00
229	4	HS50C0-E0020 SPRING ASSY, CAB FR <i>?</i>			2.00	394.90		789.80
230	5	HS50B0-E0190 ABSORBER ASSY, CAB R <i>?</i>			2.00	262.80		525.60
231	6	HS50B0-E0190 ABSORBER ASSY, CAB R <i>?</i>			2.00	262.80		525.60
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd								
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Borneo Motors



Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11		M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518			
		Document No.					
		0					
		Document Date					
		02/12/2020					

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
232	7	HS50D0-E0010 SPRING ASSY, CAB RB ?	2.00	448.60		897.20
233	8	HS4736-11950 CLAMP, BRAKE PIPE ?	1.00	5.50		5.50
234	9	H54807-E0180 BRACKET SUB-ASSY, TILT CAB PUMP ?	1.00	230.60		230.60
235	0	H54870-E0011 PUMP ASSY, TILT CAB ?	1.00	2909.10		2909.10
236	1	H45302-E0071 BRACKET SUB-ASSY, ST ?	1.00	944.40		944.40
237	2	H51201-E0103 CROSSMEMBER SUB-ASSY ?	1.00	739.30		739.30
238	3	HS5052-E0140 STAY SUB-ASSY, FR UN ?	1.00	1747.60		1747.60
239	4	HS744L-E0040 BRACKET, HOOK SUPPOR ?	1.00	309.20		309.20
240	5	H53035-E0070 BRACKET SUB-ASSY, HE ?	1.00	202.60		202.60
241	6	H53036-E0050 BRACKET SUB-ASSY, HE ?	1.00	202.60		202.60
242	7	HS8112-E0020 STAY, HEADLAMP, NO.2 ?	1.00	49.30		49.30
243	8	HS8116-E0010 STAY, HEADLAMP, NO.2 ?	1.00	49.30		49.30
244	9	H51980-E0020 HOOK ASSY, PINTLE ?	1.00	667.10		667.10
245	0	H17706-E0190 STAY SUB-ASSY AIR CL ?	1.00	172.90		172.90
246	1	H17700-E0C10 CLEANER ASSY, AIR ?	1.00	1436.60		1436.60
247	2	HS5331-E0230 PLATE, FENDER APRON, ?	1.00	21.00		21.00
248	3	H53706-E0020 MEMBER SUB-ASSY, FR ?	1.00	550.50		550.50
249	4	HS53A2-E0061 SPLASHBOARD, SIDE, L ?	1.00	178.10		178.10
250	5	HS7621-15330 MUDGUARD ?	1.00	48.50		48.50
251	6	HS7935-36410 SEAL, ENG ROOM ?	1.00	67.00		67.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Company Copy

Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1158

ESTIMATE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518			
			Document No. 0					
			Document Date 02/12/2020					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JHDFS1EKNXXX10048		E13CAT10536	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
252	7	HS5305-E0090 HOLDER SUB-ASSY, FR MUDGUARD ?			1.00	91.70		91.70
253	8	HS51B1-E0010 BOLT, CAB MOUNTING			2.00	65.70		131.40
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ <i>Resue</i> <i>Hp 9000068</i> <i>14 days</i> <i>08/12/2020 @1500</i> <i>EXCESS: TBA</i> <i>Revert</i> <i>Resurvey before paint</i>								
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 102,249.30	
			Please acknowledge receipt of vehicle		Parts 76,930.10 Labour 9,919.20 Sublet 15,400.00 Lubrication/Fluid 0.00 Others 0.00		GST 7.00% 7,157.45 Less 0.00 Amount Due 109,406.75	

Company Copy