



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518
	Document No. 0	
	Document Date 02/12/2020	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--	0.00 --/-- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: DMCVSNA00005742000 ACC DATE:26.11.2020 TOW IN:26.11.2020 EXCESS: DATE-IN:27.11.2020 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				300 580.00
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP				149.60
4	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				880.00
5	B	BP-LAB2 R/I DASHBOARD ASSY TO FAC REPAIR				1760.00
6	B	BP-LAB2 R/I FRONT WINDSCREEN GLASS				880.00
7	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST				149.60
8	B	BP-LAB2 R/I AC CON BLOWER ASSY TO FAC REPAIR & R EGAS				880.00
9	B	BP-LAB2 R/I WIREHARNESS ASSY TO FAC REPAIR				880.00
10	B	BP-LAB2 R/I BRAKE BOOSTER SYSTEM TO FAC REPAIR				XAN? 880.00
11	B	BP-LAB2 REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR				880.00
12	B	BP-LAB2 R/I ROOF LINING TO FAC REPAIR				XAN? 1760.00
13	B	BP-LAB2 RESET ECU AND REPROGRAMME				220.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Company Copy



Borneo Motors



TOYOTA

Reg No. : 196700086Z
ST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/S Double-Trans Pte Ltd
	Document No. 0	4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
	Document Date 02/12/2020	Work: 64812518

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	0.00	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	S	BP-SUBLET REPLACE ACC DAMAGED PARTS @880 AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				4400 8800.00
15	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS @660				3960 6600.00
16	1	H52101-E0K21 BUMPER SUB-ASSY, FR bt	1.00	2265.00	✓	2265.00
17	2	H52103-E0460 EXTENSION SUB-ASSY, FR BUMPER, LH bt	1.00	237.10	✓	237.10
18	3	H53036-E0050 BRACKET SUB-ASSY, HE bt	1.00	202.60	✓	202.60
19	4	HS8116-E0010 STAY, HEADLAMP, NO.2 mis	1.00	49.30	✓	49.30
20	5	HS5218-81090 GARNISH, BUMPER, LH dis	1.00	172.10	✓	172.10
21	6	HS5218-81100 GARNISH, BUMPER, LH Xave	1.00	154.90	✓	154.90
22	7	H52713-E0010 MOULDING, FR BUMPER dis (protection)	1.00	17.00	✓	17.00
23	8	HS5218-21010 REINFORCE, FR BUMPER bt	1.00	267.00	✓	267.00
24	9	HS5219-81120 BRACKET, GRILLE bt	1.00	29.50	✓	29.50
25	0	H53102-E0060 GRILLE SUB-ASSY, RAD mis	1.00	1023.10	✓	1023.10
26	1	HS5052-E0160 STAY SUB-ASSY, FR UN ? bt	1.00	282.30	✓	282.30
27	2	HS5110-E0121 MEMBER, ENGINE COVER dis bt (protector any FR UN) 1pc	1.00	895.90	✓	895.90
28	3	HS5066-E0071 STAY SUB-ASSY, STEP ? bt	1.00	155.40	✓	155.40
29	4	HS510V-E0100 SUPPORT SUB-ASSY, ST bt	1.00	711.60	✓	711.60
30	5	H94151-81201 NUT rec	6.00	1.90	✓	11.40
31	6	HS5107-72381 STAY SUB ASSY, STEP bt	1.00	94.70	✓	94.70

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due



Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
	Document No. 0	Work: 64812518
	Document Date 02/12/2020	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	0.00	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
32	7	HS1771-E0050 BRACKET, TILT CAB ST <i>cab/bt (plate step)</i>	1.00	285.00	✓	✓ 285.00
33	8	HS7917-01100 LEVER ASSY, LID LOCK <i>dis</i>	1.00	33.00	✓	✓ 33.00
34	9	H81580-E0020 REFLECTOR ASSY, REFLE <i>bro</i>	1.00	17.00	✓	✓ 17.00
35	0	HS506K-E0011 LID SUB-ASSY, STEPOP <i>bt</i>	1.00	114.20	✓	✓ 114.20
36	1	HS506N-E0010 CONTROLOPENER SUBASS <i>cut</i>	1.00	89.70	✓	✓ 89.70
37	2	HS51Q2-E0222 COVER, STEP, LH <i>de</i>	1.00	384.70	✓	✓ 384.70
38	3	HSZ148-08001 SCREW, HEX LOBULAR <i>rec</i>	8.00	3.60	✓	✓ 28.80
39	4	HSZ178-05002 NUT, FLANGE <i>rec</i>	2.00	1.50	✓	✓ 3.00
40	5	HS7622-12050 HOLDER MUDGUARD <i>? rec</i>	1.00	33.00	✓	✓ 33.00
41	6	HS51QE-E0151 APRON, STEP, LH <i>? bt</i>	1.00	146.20	✓	✓ 146.20
42	7	HS51QH-E0130 MUDGUARD, STEP <i>? em</i>	1.00	47.50	✓	✓ 47.50
43	8	H94151-80800 NUT <i>rec</i> (nut flange)	1.00	1.50	✓	✓ 1.50
44	9	HSH691-20820 BOLT <i>rec</i>	1.00	5.30	✓	✓ 5.30
45	0	H55700-E0120 COWL <i>blue</i>	1.00	2385.90	✓	✓ 2385.90
46	1	H55101-E0100 PANEL SUB-ASSY, DASH <i>repair</i>	1.00	1970.30		1970.30
47	2	H52211-E0010 CUSHION, BODY MOUNT <i>? xsuc</i>	2.00	8.80		17.60
48	3	H55701-E0040 PANEL SUB-ASSY, COWL <i>? xsuc</i>	1.00	1130.70		1130.70
49	4	HS6114-61010 GUSSET, FR BODY PILL <i>? xsuc</i>	1.00	57.50		57.50
50	5	H61164-E0011 PILLAR, FR BODY, LWR <i>bt</i>	1.00	316.20	✓	✓ 316.20
51	6	HS6118-21010 BRACKET, INSTRUMENT <i>rec</i>	1.00	8.80	✓	✓ 8.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
	Document No. 0	Work: 64812518
	Document Date 02/12/2020	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
52	7	HS7630-71010 REINFORCEMENT SUB AS <i>Xsu</i>	1.00	107.40		107.40
53	8	HS7630-71010 REINFORCEMENT SUB AS <i>Xsu</i>	1.00	107.40		107.40
54	9	H53111-E0130 GRILLE, RADIATOR <i>? cm</i>	1.00	2121.70	✓	2121.70
55	0	HS7653-11460 EMBLEM <i>? Xnn</i>	1.00	211.60		211.60
56	1	HS7653-11460 EMBLEM <i>? fan</i>	1.00	211.60		211.60
57	2	H55246-E0010 SEAL, FR PANEL, LWR <i>Xnn</i>	1.00	99.90		99.90
58	3	HS7681-11160 WEATHERSTRIP, FR CRNE <i>nee</i>	1.00	54.20	✓	54.20
59	4	HS7682-11300 WEATHERSTRIP, FR CORN <i>nee</i>	1.00	226.60	✓	226.60
60	5	HS5337-81400 MEMBER, HOOD <i>Xsu</i>	1.00	50.50		50.50
61	6	HS7682-11310 WEATHERSTRIP, FR CORN <i>Xsu</i>	1.00	82.70		82.70
62	7	HS7686-11010 SEAL, FR PANEL, LWR RH <i>Xnn</i>	1.00	103.40		103.40
63	8	HS7686-21010 SEAL, FR PANEL, LWR LH <i>Xnn</i>	1.00	103.50		103.50
64	9	HS5339-01010 STRIKER ASSY, HOOD P <i>Xnn</i>	2.00	17.30		34.60
65	0	HS7639-01051 STAY ASSY, DUMPER <i>Xsu</i>	1.00	151.70		151.70
66	1	HS7918-01331 LOCK ASSY, LID <i>Xsu</i>	2.00	90.70		181.40
67	2	HS7918-21010 HANDLE, LID LOCK <i>Xsu</i>	2.00	24.00		48.00
68	3	H53804-E0010 REINFORCE SUB-ASSY, <i>Xbt</i>	1.00	261.80	✓	261.80
69	4	H53814-E0460 EXTENSION, FR FENDER <i>Xca</i> (PANEL SIDE LH FR)	1.00	648.00	✓	648.00
70	5	HS5571-41010 PANEL, FR CORNER, LWR <i>Xca</i> (PANEL SIDE LH FR)	1.00	14.50	✓	14.50
71	6	HSZ950-39050 RETAINER <i>Xca</i> (PANEL SIDE LH FR)	6.00	1.40	✓	8.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/S Double-Trans Pte Ltd
	Document No. 0	4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
	Document Date 02/12/2020	Work: 64812518

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--	0.00	--/--	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
72	7	H55712-E0390 PANEL, COWL TOP, OUT <i>Xsu</i>	1.00	677.60		677.60
73	8	H75315-EW040 ORNAMENT, RADIATOR G <i>Ne</i>	1.00	276.30	✓	276.30
74	9	H75338-E0030 ORNAMENT, HOOD, LWR <i>Ne</i>	1.00	185.10	✓	185.10
75	0	H75353-E0160 ORNAMENT, FR FENDER, <i>Ne</i>	1.00	113.70	✓	113.70
76	1	H75425-E0580 ORNAMENT, FR DOOR, R <i>Ne</i>	1.00	239.80	✓	239.80
77	2	HS5701-71960 CROSSMEMBER SUB ASSY <i>? xsu</i>	1.00	167.60		167.60
78	3	HS5730-81010 BRACKET SUB ASSY,CTR <i>? xsu</i>	1.00	103.50		103.50
79	4	HS5813-E0030 BRACKET, CTR SEAT, F <i>? xsu</i>	1.00	121.20		121.20
80	5	HS5741-81010 BRACKET, FOOT REST <i>? xsu</i>	1.00	17.00		17.00
81	6	HS5741-91010 BRACKET, BRACE, LH <i>? xsu</i>	1.00	17.00		17.00
82	7	HS5767-11010 PLATE, FIRE EXTING U <i>? xsu</i>	2.00	8.30		16.60
83	8	HS5767-51010 PLATE, CTR SEAT GRIP <i>? xsu</i>	1.00	18.50		18.50
84	9	HS5767-61011 PLATE, CTR SEATBACK S <i>? xsu</i>	1.00	54.00		54.00
85	0	HS5785-22210 STIFFENER, FLOOR BOAR <i>? xsu</i>	1.00	515.00		515.00
86	1	HS5811-34611 PANEL, FLOOR, CENTER <i>? xsu</i>	1.00	861.20		861.20
87	2	H58207-E0090 CLAMP SUB-ASSY, PARK <i>? xsu</i>	1.00	54.20		54.20
88	3	H58319-E0010 RETAINER, JACK COVER <i>? xsu</i>	1.00	33.00		33.00
89	4	H57487-E0040 REINFORCEMENT, FLOOR SIDE MBR, NO.1 LH <i>? bt</i>	1.00	320.00	✓	320.00
90	5	H57420-E0053 MEMBER ASSY, FLOOR SIDE, LH <i>? bt</i>	1.00	742.80	✓	742.80
91	6	HS5716-41010 MEMBER, SEAT SET FR, <i>? bt</i>	1.00	131.90	✓	131.90

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no : 6631 1188

ESTIMATE

Account Details		Account No.		Customer Details				
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11		M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518				
		Document No. 0						
				Document Date 02/12/2020				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JHDFS1EKNXXX10048		E13CAT10536	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
92	7	HS5717-21010	MEMBER, SEAT SET RR,	1.00	128.70	✓	✓128.70	
93	8	HS5742-31010	BRACKET, BED SET	1.00	19.30	✓	✓19.30	
94	9	HS5767-21010	PLATE, WASHER TANK S	1.00	8.30	✓	✓8.30	
95	0	H58242-E0040	GUS SET, WHEELHOUSE	1.00	729.10	✓	✓729.10	
96	1	HS5835-81150	SPLASHBOARD, FR, LH	1.00	111.90	✓	✓111.90	
97	2	H67002-E0360	PANEL SUB-ASSY, FR DOOR, LH	1.00	2875.20	✓	✓2875.20	
98	3	HS6927-01310	HINGE ASSY, DOOR,	2.00	189.90	✓	✓379.80	
99	4	H67124-E0010	BRACKET, FR DOOR OUT	1.00	149.90	✓	✓149.90	
100	5	HS6802-E0040	GARNISH SUB-ASSY, DO	1.00	250.00	✓	✓250.00	
101	6	HSZ950-43029	STOPPER	1.00	7.80	✓	✓7.80	
102	7	HS656-20620	BOLT	5.00	1.60	✓	✓8.00	
103	8	HSK210-00612	SCREW	1.00	1.60	✓	✓1.60	
104	9	HSK210-00616	SCREW	1.00	1.40	✓	✓1.40	
105	0	H61132-E0120	PILLAR, FR BODY, UPR	1.00	603.50	✓	✓603.50	
106	1	H61612-E0030	PANEL, QUARTER, LH	1.00	1046.30	✓	✓1046.30	
107	2	H65622-E0010	PANEL, SIDE GATE, LH	1.00	107.50	✓	✓107.50	
108	3	H61107-E0021	PILLAR SUB-ASSY, FR, LH	1.00	260.60	✓	✓260.60	
109	4	H61136-E0020	REINFORCEMENT, FR BODY PILLAR, UPR LH	1.00	80.50	✓	✓80.50	
110	5	H61416-E0011	EXTENSION, ROCKER, OUTER LH	1.00	260.60	✓	✓260.60	
111	6	HS7981-12550	INSULATOR, BODY	1.00	3.10	✓	✓3.10	
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total		
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 126462, Tel no. : 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	M/S Double-Trans Pte Ltd	
		Document No. 0	4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226	
		Document Date 02/12/2020	Work: 64812518	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
112	7	H61109-E0011 REINFORCEMENT SUB-AS ? <i>fsu</i>	1.00	249.10		249.10
113	8	HS6119-31300 STIFFENER, FIXTURE ? <i>fsu</i>	1.00	14.30		14.30
114	9	HS6119-51200 BRACKET, FIXTURE ? <i>fsu</i>	1.00	12.80		12.80
115	0	H61232-E0020 RAIL, ROOF SIDE, INN ? <i>fsu</i>	1.00	143.70		143.70
116	1	HS6124-61010 REINFORCEMENT, ROOF ? <i>fsu</i>	1.00	57.50		57.50
117	2	H61314-E0040 REINFORCEMENT, DOOR LOCK STRIKER, LH ? <i>fsu</i>	1.00	198.40		198.40
118	3	HS6143-71010 PANEL, VENTILATER CO ? <i>fsu</i>	1.00	19.00		19.00
119	4	HS6155-71160 REINFORCEMENT, DOOR ? <i>fsu</i>	1.00	5.30		5.30
120	5	H61618-E0042 PANEL, QUARTER, INNE ? <i>fsu</i>	1.00	443.60		443.60
121	6	H61709-E0021 REINFORCEMENT SUB-AS ? <i>fsu</i>	1.00	378.40		378.40
122	7	H67862-E0010 WEATHERSTRIP, FR DOO ? <i>fsu</i>	1.00	217.60		217.60
123	8	HSZ105-08077 BOLT, WASHER BASED HX ? <i>fsu</i>	4.00	6.30		25.20
124	9	H74103-E0020 DOOR SUB-ASSY, FR AS ? <i>fsu</i>	1.00	111.20		111.20
125	0	H67606-E0150 PANEL SUB-ASSY, FR D ? <i>fsu</i>	1.00	677.90		677.90
126	1	H74202-E0021 PANEL SUB-ASSY, FR A ? <i>fsu</i>	1.00	75.20		75.20
127	2	H74232-E0010 PANEL, FR DOOR ARMRE ? <i>fsu</i>	1.00	125.40		125.40
128	3	H74220-E0010 ARMREST ASSY, DOOR, ? <i>fsu</i>	1.00	47.50		47.50
129	4	H74640-E0020 GRIP ASSY, DOOR ASSI ? <i>fsu</i>	1.00	118.90		118.90
130	5	HSZ950-39242 RETAINER ? <i>fsu</i>	1.00	4.00		4.00
131	6	HS6921-01091 LINK ASSY, DOOR CHECK ? <i>fsu</i> <i>bf</i>	1.00	93.50	✓	93.50

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Reg No. : 196700085Z
 T Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details						
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	M/S Double-Trans Pte Ltd						
		Document No. 0	4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226						
		Document Date 02/12/2020	Work: 64812518						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JHDFS1EKNXXX10048		E13CAT10536	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
132	7	H69320-E0032	LOCK ASSY, DOOR, LH <i>Jam</i>			1.00	201.80	✓	201.80
133	8	HS6942-21010	LINK, DOOR LOCK, LH <i>? Xsu</i>			1.00	14.00		14.00
134	9	HS6946-01150	STRIKER ASSY, DOOR, <i>? Xsu</i>			1.00	29.50		29.50
135	0	H67801-E0010	COVER SUB-ASSY, FR D <i>? Xsu</i>			1.00	7.80		7.80
136	1	H69820-E0051	REGULATOR ASSY, FR D <i>? Xsu</i>			1.00	790.00		790.00
137	2	H67914-E0020	PLATE, DOOR SCUFF, L <i>? bt</i>			1.00	52.50	✓	52.50
138	3	H51774-E0130	COVER, STEP PLATE, L <i>? bt</i>			1.00	332.00	✓	332.00
139	4	HSZ148-08001	SCREW, HEX LOBULAR <i>neu</i>			1.00	3.60	✓	3.60
140	5	HSZ166-06001	SCREW, HEX LOBULAR T <i>neu</i>			3.00	1.80	✓	5.40
141	6	HSZ950-31015	NUT, SPRING <i>neu</i>			3.00	3.30	✓	9.90
142	7	HSZ950-31021	NUT, SPRING <i>neu</i>			2 1	4.00		8.00
143	8	HSZ950-39347	RETAINER <i>neu Xsu</i>			4.00	3.30		13.20
144	9	H61454-E0130	COVER, FR STEP, LH <i>neu</i>			1.00	410.60	✓	410.60
145	0	HSZ950-39347	RETAINER <i>neu</i>			4 1	3.30		13.20
146	1	HSZ950-44156	CUSHION <i>neu</i>			3.00	1.40		4.20
147	2	HSZ656-20620	BOLT <i>neu</i>			3.00	1.60		4.80
148	3	H51771-E0050	BRACKET, TILT CAB ST <i>lt (plate step) (21)</i>			1.00	285.00	✓	285.00
149	4	H51772-E0020	PLATE, STEP, LH <i>neu</i>			1.00	257.80	✓	257.80
150	5	HSZ653-20830	BOLT <i>X neu</i>			3.00	2.10		6.30
151	6	HS5571-61010	STAY, FR CORNER PANEL <i>3 bt</i>			1.00	19.00	✓	19.00
For & on behalf of		Customer's Signature		Charge Summary		Total			
Borneo Motors (Singapore) Pte Ltd									
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less			
						Amount Due			

Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
	Document No. 0	Work: 64812518
	Document Date 02/12/2020	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--	0.00	--/--	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
152	7	H57036-E0010 PANEL SUB-ASSY, FR S <i>dis</i>	1.00	355.40	✓	✓355.40
153	8	HS5704-E0010 SUPPORT SUB-ASSY, FR <i>2.5t</i>	1.00	323.20	✓	✓323.20
154	9	HS5832-21080 COVER, STEP LWR, LH <i>7 cm</i>	1.00	135.40	✓	✓135.40
155	0	HSZ178-08001 NUT, FLANGE <i>new</i>	3.00	1.00	✓	✓3.00
156	1	H76621-E0041 MUDGUARD, FR FENDER, <i>new</i>	1.00	81.20	✓	✓81.20
157	2	H76912-E0010 MUDGUARD, SIDE, LH <i>de</i>	1.00	240.10	✓	✓240.10
158	3	HSZ950-39274 RETAINER <i>new</i>	14.00	1.70		1.70 23.80
159	4	HSZ950-39275 RETAINER <i>new</i>	6.00	4.80		4.80 28.80
160	5	HS5830-91040 SPLASHBOARD SUB ASSY <i>? for VC</i>	1.00	532.30		532.30
161	6	HSH656-20826 BOLT <i>new</i>	4.00	1.90		7.60
162	7	HS5370-52450 BRACKET SUB ASSY, FR <i>7.5t</i>	1.00	142.90	✓	✓142.90
163	8	HS5370-52480 BRACKET SUB ASSY, FR <i>7.5t</i>	1.00	61.20	✓	✓61.20
164	9	H53832-E0370 PANEL, FR FENDER SID <i>7.5t</i>	1.00	394.90	✓	✓394.90
165	0	HSZ108-08005 BOLT, SQUARE <i>new</i>	5.00	7.60		7.60 38.00
166	1	HSZ178-08001 NUT, FLANGE <i>new</i>	7.00	1.00		7.00
167	2	HSZ950-31021 NUT, SPRING <i>new</i>	3.00	4.00		12.00
168	3	HSH656-20822 BOLT <i>new</i>	2.00	7.30	✓	✓14.60
169	4	HS5370-51240 BRACKET SUB ASSY, FR <i>new</i>	1.00	57.70	✓	✓57.70
170	5	HS5372-21290 LINER, FR, FENDER, LH <i>cut</i>	1.00	163.40	✓	✓163.40
171	6	HS5740-21010 BRACKET SUB ASSY, SEA <i>new</i>	1.00	36.50	✓	✓36.50

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Reg No. : 196700086Z
 T Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details						
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	M/S Double-Trans Pte Ltd						
		Document No. 0	4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226						
		Document Date 02/12/2020	Work: 64812518						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JHDFS1EKNXXX10048		E13CAT10536	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
172	7	HSZ178-08001	NUT, FLANGE <i>Xm</i>			3.00	1.00		3.00
173	8	HSH656-20822	BOLT <i>X ^</i>			1.00	7.30		7.30
174	9	HS5530-12091	PANEL SUB ASSY, INSTR <i>? xsv</i>			1.00	1240.80		1240.80
175	0	H55835-E0070	DUCT, HEATER TO REGI <i>? xsv</i>			1.00	253.30		253.30
176	1	H55844-E0030	DUCT, HEATER TO REGI <i>? xsv</i>			1.00	101.70		101.70
177	2	HS8724-41090	DUCT, HEATER TO FOOT <i>? xsv</i>			1.00	64.50		64.50
178	3	H55330-E0061	REINFORCEMENT ASSY. <i>? xsv</i>			1.00	849.00		849.00
179	4	H55990-E0030	NOZZLE ASSY, DEFROST <i>? xsv</i>			1.00	267.30		267.30
180	5	HS8727-42240	HOSE, DEF <i>? xsv</i>			1.00	45.30		45.30
181	6	HS8727-42250	HOSE, DEF <i>? xsv</i>			1.00	45.30		45.30
182	7	HSZ950-39161	RETAINER <i>? xsv</i>			2.00	2.10		4.20
183	8	HS5337-81400	MEMBER, HOOD <i>? xsv</i>			1.00	50.50		50.50
184	9	HS7682-11310	WEATHERSTRIP, FR CORN <i>? xsv</i>			1.00	82.70		82.70
185	0	HS7686-11010	SEAL, FR PANEL, LWR RH <i>? xsv</i>			1.00	103.40		103.40
186	1	HS7686-21010	SEAL, FR PANEL, LWR LH <i>? xsv</i>			1.00	103.50		103.50
187	2	H87094-E0590	STAY SUB-ASSY, OUT R <i>ARM FR W, PER RH (99)</i>			1.00	603.40	✓	603.40
188	3	HS87C2-E0070	STAY, OUTER RR VIEW <i>Sub stay outside RR (100)</i>			1.00	89.70	✓	89.70
189	4	H56121-E0031	MOULDING <i>See weather's trip</i>			1.00	457.10	✓	457.10
190	5	T21000-20	SIKA 182010 SIKA TACK GO! (BLA <i>see</i>)			2.00	108.00	✓	216.00
191	6	T21000-22	SIKA 207. G+P ADHESIVE PRIMER <i>see</i>			2.00	200.00	✓	400.00
For & on behalf of		Customer's Signature		Charge Summary		Total			
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less			
						Amount Due			

Reg No. : 196700086Z
 T Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no : 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	M/S Double-Trans Pte Ltd	
		Document No. 0	4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226	
		Document Date 02/12/2020	Work: 64812518	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
192	7	H62220-E0040 GARNISH ASSY, FR PILLAR LH <i>? xsv</i>	1.00	98.20		98.20
193	8	H62512-E0091 BOARD, QUARTER TRIM, <i>? xsv</i>	1.00	236.80		236.80
194	9	H73135-E0030 COVER, SHOULDER BELT <i>? xsv</i>	1.00	38.30		38.30
195	0	H62312-E0012 WEATHERSTRIP, FR DOOR <i>? xsv</i>	1.00	292.30	✓	292.30
196	1	H74603-E0030 GRIP SUB-ASSY, ASSIS <i>? xsv</i>	1.00	156.40		156.40
197	2	H74604-E0030 GRIP SUB-ASSY, INSTR <i>? xsv</i>	1.00	139.20		139.20
198	3	H74612-E0060 COVER, ASSIST GRIP <i>? xsv</i>	2.00	8.30		16.60
199	4	HSH656-20826 BOLT <i>xnn</i>	2.00	1.90		3.80
200	5	HSH691-10816 BOLT <i>xnn</i>	2.00	5.30		10.60
201	6	H87010-E0171 UNITASSY, AIR CONDIT <i>? xsv</i>	1.00	2126.20		2126.20
202	7	H87130-E0120 BLOWER ASSY <i>? xsv</i>	1.00	838.50		838.50
203	8	H88703-E0050 HOSE SUB-ASSY, DISCH <i>? bt</i>	1.00	426.10	✓	426.10
204	9	HS8870-41770 TUBE SUB ASSY, LIQUID <i>? bt</i>	1.00	298.30	✓	298.30
205	0	H88704-E0010 HOSE SUB-ASSY, SUCTI <i>? bt</i>	1.00	390.70	✓	390.70
206	1	HS8871-44100 TUBE, LIQUID <i>? bt</i>	1.00	86.20		86.20
207	2	H88704-E0010 HOSE SUB-ASSY, SUCTI <i>? xsv</i>	1.00	390.70		390.70
208	3	HS8871-44100 TUBE, LIQUID <i>? bt</i>	1.00	86.20	✓	86.20
209	4	HS8841-21930 BRACKET, CONDENSER <i>? bt</i>	1.00	57.70	✓	57.70
210	5	H88460-E0101 CONDENSER ASSY <i>5/2</i>	1.00	1898.90	✓	1898.90
211	6	HS8850-32170 BRACKET SUB ASSY, COOL <i>5/2</i>	1.00	107.20	✓	107.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Borneo Motors



Reg No. : 196700086Z
 AT Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518
	Document No. 0	
	Document Date 02/12/2020	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
212	7	H82214-E0150 WIRE, HEATER CONTROL <i>Cut</i>	1.00	51.50	✓	✓ 51.50
213	8	H81110-E0682 HEADLAMP ASSY <i>X svt</i>	1.00	750.30		750.30
214	9	H81150-E0682 HEADLAMP ASSY, LH <i>cm</i>	1.00	750.30	✓	✓ 750.30
215	0	H81360-E0090 LAMP ASSY, CORNERING <i>X svt</i>	1.00	148.70		148.70
216	1	H81390-E0090 LAMP ASSY, CORNERING <i>? cm</i>	1.00	148.70	✓	✓ 148.70
217	2	HSZ950-39072 RETAINER <i>2 nu</i>	1.00	2.40		2.40
218	3	HSK541-04016 SCREW, BINDING TAPPI <i>2 nu</i>	1.00	2.30		2.30
219	4	H81510-E0091 LAMP ASSY, FR TURN S <i>X svt</i>	1.00	156.40		156.40
220	5	H81520-E0091 LAMP ASSY, FR TURN S <i>nu</i>	1.00	156.40	✓	✓ 156.40
221	6	H81730-E0081 LAMP ASSY, SIDE TURN <i>? svt</i>	1.00	93.20		93.20
222	7	H51701-E0300 COVER SUB-ASSY, SIDE <i>? svt</i>	1.00	1101.90		1101.90
223	8	H51702-E0200 COVER SUB-ASSY, STEP <i>? svt</i>	1.00	1061.70		1061.70
224	9	H54960-E0282 SPRING ASSY, TILT CA <i>? svt</i>	1.00	2875.20		2875.20
225	0	HS500Q-E0040 BRACKET SUB-ASSY, TI <i>? svt</i>	1.00	525.50		525.50
226	1	HS500R-E0040 BRACKET SUB-ASSY, TI <i>? svt</i>	1.00	525.50		525.50
227	2	HS5032-E0051 LEVER SUB-ASSY, TILT <i>? svt</i>	1.00	3423.40		3423.40
228	3	HS50A0-E0140 ABSORBER ASSY, CAB E <i>? svt</i>	2.00	181.00		362.00
229	4	HS50C0-E0020 SPRING ASSY, CAB FR <i>? svt</i>	2.00	394.90		789.80
230	5	HS50B0-E0190 ABSORBER ASSY, CAB R <i>? svt</i>	2.00	262.80		525.60
231	6	HS50B0-E0190 ABSORBER ASSY, CAB R <i>? svt</i>	2.00	262.80		525.60

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	Amount Due

Reg No. : 196700086Z
 T Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
	Document No. 0	Work: 64812518
	Document Date 02/12/2020	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
232	7	HS50D0-E0010 SPRING ASSY, CAB RB ? xsvc	2.00	448.60		897.20
233	8	HS4736-11950 CLAMP, BRAKE PIPE ? xsvc	1.00	5.50	✓	5.50
234	9	H54807-E0180 BRACKET SUB-ASSY, TILT CAB PUMP ? bt	1.00	230.60	✓	230.60
235	0	H54870-E0011 PUMP ASSY, TILT CAB ? xsvc	1.00	2909.10	✓	2909.10
236	1	H45302-E0071 BRACKET SUB-ASSY, ST ? xsvc	1.00	944.40		944.40
237	2	H51201-E0103 CROSSMEMBER SUB-ASSY ? xsvc	1.00	739.30		739.30
238	3	HS5052-E0140 STAY SUB-ASSY, FR UN ? xsvc	1.00	1747.60		1747.60
239	4	HS744L-E0040 BRACKET, HOOK SUPPOR ? xsvc	1.00	309.20		309.20
240	5	H53035-E0070 BRACKET SUB-ASSY, HE ? xsvc	1.00	202.60		202.60
241	6	H53036-E0050 BRACKET SUB-ASSY, HE ? xsvc X SVC	1.00	202.60		202.60
242	7	HS8112-E0020 STAY, HEADLAMP, NO.2 ? xsvc	1.00	49.30		49.30
243	8	HS8116-E0010 STAY, HEADLAMP, NO.2 ? xsvc X SVC	1.00	49.30		49.30
244	9	H51980-E0020 HOOK ASSY, PINTLE ? xsvc	1.00	667.10		667.10
245	0	H17706-E0190 STAY SUB-ASSY AIR CL ? xsvc	1.00	172.90		172.90
246	1	H17700-E0C10 CLEANER ASSY, AIR ? xsvc	1.00	1436.60		1436.60
247	2	HS5331-E0230 PLATE, FENDER APRON ? xsvc	1.00	21.00		21.00
248	3	H53706-E0020 MEMBER SUB-ASSY, FR ? xsvc	1.00	550.50		550.50
249	4	HS53A2-E0061 SPLASHBOARD, SIDE, L ? xsvc	1.00	178.10		178.10
250	5	HS7621-15330 MUDGUARD ? xsvc	1.00	48.50		48.50
251	6	HS7935-36410 SEAL, ENG ROOM ? xsvc	1.00	67.00		67.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Reg No. : 196700086Z
 IT Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
	Document No. 0	Work: 64812518
	Document Date 02/12/2020	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	FS1EKND	KAS	23/01/2020	XE5495L	0	58441	72/UL/XE5495L
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
252	7	HS5305-E0090 HOLDER SUB-ASSY, FR MUDGUARD	1.00	91.70		91.70
253	8	HS51B1-E0010 BOLT, CAB MOUNTING	2.00	65.70		131.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Handwritten notes:
 7.5%
 RABU
 Hp 90010068
 14 days + 6 days = 20 days
 08/12/2020 @ 1500
 excess: TBA
 Revert
 Resurvey before paint

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts 76,930.10 Labour 9,919.20 Sublet 15,400.00 Lubrication/Fluid 0.00 Others 0.00	102,249.30
		GST 7.00% 7,157.45 Less 0.00 Amount Due 109,406.75	