

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19, SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

07-12-2020

OUR REF NO. SKH 1350K

HALAWATI BINTE SALLEH
BLK 481, SEMBAWANG DRIVE,
#03-479
SINGAPORE 750481

ESTIMATE BILL FOR VEHICLE NO. SKH 1350L
MODEL : TOYOTA ESTIMA HYBRID 2.4X A

LIST ITEM

1) REAR WINDSCREEN MOULDING (TOP)		\$ 87.00	x ny
2) REAR WINDSCREEN MOULDING (BOTTOM)		\$ 168.00	x ny
3) BOOT LID		\$ 1,694.00	Ry
4) BOOT LID HINGE	2PCS @\$216.86	\$ 433.72	x ny
5) BOOT LID DAMPER	2PCS @\$457.22	\$ 914.44	x ny
6) BOOT LID LOGO		\$ 58.70	ny
7) BOOT LID EMBLEM "ESTIMA"		\$ 49.10	ny
8) BOOT LID EMBLEM "E-FOUR X"		\$ 54.90	ny
9) BOOT LID EMBLEM "HYBRID SYNERGY DRIVE"		\$ 55.70	ny
10) BOOT LID OUTER CHROME MOULDING		\$ 292.96	x ny
11) BOOT LID INNER TRIMBOARD		\$ 427.20	x ny
12) BOOT LID INNER TRIMBOARD CLIPS	10PCS @\$8.90	\$ 89.00	x
13) BOOT LID LOCK		\$ 409.30	x
14) BOOT LID LOCK COVER		\$ 65.25	x
15) BOOT LID STRIKER		\$ 79.04	x
16) BOOT LID LOCK ACTUATOR		\$ 284.00	ny
17) BOOT LID STOPPER	2PCS @\$34.25	\$ 68.50	x
18) BOOT LID WEATHERSTRIPE		\$ 280.00	x
19) REAR BUMPER	1230	\$ 1,411.80	der
20) REAR BUMPER CLIPS	10PCS @\$8.90	\$ 89.00	ny

30

21) REAR BUMPER SIDE ATTACHEMENT (SHORT)	2PCS @ ⁶⁰ \$89.56	\$ 170.12 ¹²⁰ ? <i>am</i> ✓
22) REAR BUMPER SIDE ATTACHEMENT (LONG)	2PCS @\$96.85	\$ 193.70 <i>am</i>
23) REAR BUMPER REFLECTOR	2PCS @\$89.20	\$ 178.40 <i>am</i>
24) REAR BUMPER TOWING COVER	2PCS @\$49.80	\$ 99.60 <i>am</i>
25) REAR BUMPER SPONGE		\$ ²⁵² 484.60 <i>am</i> ✓
26) END PANEL OUTER		\$ 781.62 ⁶⁵⁴ ? <i>am</i> ✓
27) END PANEL INNER		\$ 471.40 <i>Rp</i>
28) END PANEL TOP GARNISH		\$ 284.00 ? <i>am</i> ✓ 25319
29) END PANEL TOP GARNISH CLIPS	8PCS @\$8.90	\$ 71.20 ? <i>am</i> ✓
30) END PANEL LOWER GARNISH		\$ 228.00 <i>am</i> ✓ ^{de-175.77}
31) END PANEL LOWER GARNISH CLIPS	4PCS @\$8.90	\$ 35.60 <i>am</i>
32) REAR ANTENNA SENSOR		\$ 328.00 <i>am</i>
33) REAR COMPARTMENT PANEL		\$ 894.00 X
34) REAR COMPARTMENT TRIMBOARD COVER		\$ 783.00 X
35) REAR COMPARTMENT INNER TRIM		\$ 395.17 X
		\$ 12,419.02
LESS DISCOUNT - 25%		\$ 3,104.76
		\$ 9,314.27

SPECIAL NETT ITEM

1) REAR WINDSCREEN GUM	\$ 60.00 X	} <i>am</i>
2) REAR WINDSCREEN INNERSEAL	\$ 60.00 X	
3) REAR LICENCE PLATE EMBOSS	\$ 55.00 X	
4) REVERSE CAMERA WITH CONTROL UNIT	\$ 450.00 X	
5) REVERSE SENSOR WITH CONTROL UNIT	\$ 250.00 ²⁰⁰ <i>am</i>	} <i>am</i>
6) REAR COMPARTMENT INSULATOR CLOTH	\$ 380.00 X	
7) END PANEL SEALANT	\$ 60.00 X	
8) REAR COMPARTMENT SEALANT	\$ 60.00 X	
		\$ 1,475.00

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM	\$ 60.00	30.
2) TO APPLY UNDERSEALING ON AFFECTED AREAS	\$ 120.00	X
3) TO REMOVE AND REFIX REAR WINDSCREEN	\$ 280.00	X
4) TO REMOVE AND REFIX BOOT LID FIXING AND REALIGNMENT	\$ 280.00	X
5) TO REMOVE AND REFIX REVERSE CAMERA WITH CONTROL UNIT	\$ 120.00	X
6) TO REMOVE AND REFIX IN CAR CAMERA WIRING SYSTEM AND RESET	\$ 280.00	X
7) TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT	\$ 120.00	30.
8) TO REMOVE AND REFIX CUSHION, FLOOR BOARD, ROOF LINNING, TRIM, GARNISH, UPHOLSTERY ETC	\$ 220.00	60.
9) TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC	\$ 1,760.00	500
10) TO RESPRAY ON AFFECTED AREAS	\$ 880.00	500 1320
		\$ 4,120.00
GRAND TOTAL :		<u>\$ 14,909.27</u>

Tanpin 97415749
'WP' 9/12/20 @ 1645
c/s Resurvey after repair
Tanpin @ Maintenance
3-4 days.

2253.42
1320
3 573.42.
1/s \$ 2850 #
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: