

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MUCHI LEASING PTE LTD
421 TAGORE INDUSTRIAL AVE #01-21
SINGAPORE 787805

Contact : 97876633, 82686829

TP 111.
Jasper.

ESTIMATE

Repair Code : CLM16586

Date in : 07/12/2020

Vehicle Num. : SJS7710U

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053ZEE106154229/3ZZ4927483

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>torn</i>	1	581.70	✓ 581.70
FRONT BUMPER RH FOGLAMP <i>3 items</i>	1	310.40	+ 310.40
FRONT BUMPER RH FOGLAMP GARNISH	1	82.80	+ 82.80
FRONT BUMPER SIDE RETAINER L/R <i>RH Dmg</i>	2	63.40	63.40 126.80
FRONT BUMPER TOP RUBBER SEAL <i>new</i>	1	54.80	+ 54.80
FRONT RH FENDER <i>Dented</i>	1	712.10	585 712.10
FRONT RH FENDER 'VVT-I' EMBLEM <i>new</i>	1	44.10	✓ 44.10
FRONT RH FENDER INNER BRACKET <i>new</i>	1	80.70	+ 80.70
FRONT RH FENDER INNER SHIELD <i>torn</i>	1	196.50	✓ 196.50
FRONT RH HEADLAMP <i>cracked</i>	1	608.70	✓ 608.70
FRONT RH KNUCKLE ARM <i>new</i>	1	628.40	+ 628.40
FRONT RH KNUCKLE ARM BEARING <i>Dmg</i>	1	120.60	✓ 120.60
FRONT RH LOWER ARM <i>Bent</i>	1	732.50	375 732.50
FRONT RH SHOCK ABSORBER <i>new</i>	1	438.30	+ 438.30
FRONT RH SHOCK ABSORBER TOP MOUNTING <i>new</i>	1	217.70	+ 217.70
FRONT RH SPORT RIM <i>at</i>	1	427.70	✓ 427.70
FRONT RH STABILIZER LINK <i>3 items</i>	1	237.10	+ 237.10
FRONT RH TIE ROD END	1	186.70	+ 186.70

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MUCHI LEASING PTE LTD
421 TAGORE INDUSTRIAL AVE #01-21
SINGAPORE 787805

Contact : 97876633, 82686829

ESTIMATE

Repair Code : CLM16586

Date in : 07/12/2020

Vehicle Num. : SJS7710U

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053ZEE106154229/3ZZ4927483

FRONT WASHER TANK <i>HEMU</i>	3002.70	1	145.80	X	145.80
	2252.02				Subtotal before discount
Percentage discount 25%					1,483.35
					Sub-total 1
					4,450.05
FRONT BUMPER CLIPS - SET <i>HEMU</i>		1	50.00	30	50.00
FRONT RH 1965/65R15 TYRE <i>HEMU</i>	60	1	380.00	X	380.00
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>HEMU</i>		1	50.00	30	50.00
					Subtotal before discount
					480.00
Percentage discount 0%					0.00
					Sub-total 2
					480.00
					Parts-total
					4,930.05

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

30 60.00
180 280.00
1130 80 100.00
400 700.00
400 600.00
40 60.00

Labour Total

1,800.00

Parts & Labour Total

6,730.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a *** This is a computer-generated document which requires no signature.***
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3442.02
L/S: 2.7k.

05 Days.