

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0965/2020/NS
DATE : 9-Dec-20
WIP : 61548

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SJY 4620 J

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian

3 days - ok - jb - 19 Feb 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS CHUA SU SHUA SOPHIA
ADDRESS : 3 LORONG HOW SUN
#01-11
SINGAPORE 536560
TELEPHONE : HP +65 97602242
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100321087-06
VEHICLE NO : **SGQ 1414 K**
MODEL CODE : AUDI TTSC 2.0T FSI QU 8J3
MODEL YEAR : 13/1/2012
ENGINE NO : CDL 042227
CHASSIS NO : TRUZZZ8J2B1012054
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Dec-20
PLACE OF ACCIDENT : TRAFFIC JUNCTION AT 298 PUNGGOL
CENTRAL

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGQ 1414 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$	280.00	\$ 280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE- ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	\$ 500.00
3	TO RESPRAY REAR BUMPER.	\$	900.00	\$ 550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 2,422.00	\$ 1,522.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGQ 1414 K

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER		\$	3,102.00	
2	REAR BUMPER FIXING PARTS		\$	235.00	
3	REAR BUMPER LOWER COVER		\$	674.00	\$ 538.80
4	REAR REINFORCEMENT BEAM		\$	858.00	
5	REAR BUMPER SHOCK ABSORBER		\$	103.00	
6	REAR BUMPER GUIDE SECTION - LH/RH	2	\$	88.00	
7	REAR BUMPER COVER HOLDER	2	\$	111.00	
8	REAR BUMPER INNER COVER - LH/RH	2	\$	52.00	
9	UPPER REAR BUMPER COVER TRIM SPOILER - LOWER		\$	428.00	\$ 342.00
10	REAR FOG LIGHT		\$	166.00	
11	REAR SILENCER HEAT SHIELD		\$	216.00	
12	REAR PARKING AID SENSOR	2	\$	500.00	
13	SUNDRIES		\$	200.00	
TOTAL SPARE PARTS		:	\$	6,733.00	\$ 880.80
TOTAL LABOUR CHARGES		:	\$	2,422.00	\$ 1,522.00
GRAND TOTAL		:	\$	9,155.00	\$ 2,402.80

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bi-04/02/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT