

NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelyn1911ngsautomotive@gmail.com
Reg No.: 53405718K

QUOTATION

No. : AQT-0029

INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOU BLDG
SINGAPORE 049711

TEL : 6347 6100

FAX :

Your Ref. :

Our Ref : AQT-0029/SJQ9523

C. C. :

Date : 08-12-2020

Page : 1 of 3

Description	Qty	U/ Price S\$	Amount S\$
ACCIDENT ON 05/12/2020@10:40 INVOLVING SJQ9523R & SLH2515J			
ALONG ENTRANCE OF KPE TUNNEL (TOWARDS CITY)			
CLAIMS AGAINST SLH2515J (INDIA INT'L)			
REPLACEMENT PART: TY VIOS NCP93			
BONNET <i>Rx</i>	1	0.00	0.00
CLIPS, ROD <i>NNX</i>	1	0.00	0.00
FRT BUMPER <i>Bu</i>	1	0.00	0.00
REINFORCEMENT, FRT BUMPER <i>Bu</i>	1	0.00	0.00
COVER, FRT BUMPER HOLE RH/LH <i>SNX</i>	2	0.00	0.00
GRILLE, FRT BUMPER CTR LOWER <i>CM</i>	2	0.00	0.00
RETAINER, FRT BUMPER RH/LH <i>MSDj Lx</i>	2	0.00	0.00
HEADLAMP ASSY RH/LH <i>?</i>	2	0.00	0.00
BRACKET, HEADLAMP RH/LH <i>?</i>	2	0.00	0.00
RADIATOR GRILLE <i>CM</i>	1	0.00	0.00
MOULDING, RADIATOR GRILLE <i>me</i>	1	0.00	0.00
REAR BOOT LID <i>BT</i>	1	0.00	0.00
REAR BOOT HINGE RH/LH <i>Rx</i>	2	0.00	0.00
BAR, REAR BOOT RH/LH <i>RRY</i>	2	0.00	0.00
REAR BOOT INNER LOCK <i>Rd</i>	1	0.00	0.00
REAR BUMPER <i>Be</i>	1	0.00	0.00
REAR BUMPER RETAINER UPPER RH/LH <i>CM</i>	2	0.00	0.00
REAR BUMPER RETAINER LOWER RH/LH <i>CM</i>	2	0.00	0.00
REAR BUMPER SEAL RH/LH <i>me</i>	2	0.00	0.00
REAR BUMPER LOWER REFLECTOR RH/LH <i>MS SCLT</i>	2	0.00	0.00
REAR END PANEL <i>BT</i>	1	0.00	0.00
REAR END PANEL GARNISH <i>Dd</i>	1	0.00	0.00

Not Authorise
1/1 Sup &
Repair After Paint
7 days

NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelyn1911ngsautomotive@gmail.com
Reg No.: 53405718K

QUOTATION

No. : AQT-0029

INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOU BLDG
SINGAPORE 049711

TEL : 6347 6100

FAX :

Your Ref. :

Our Ref : AQT-0029/SJQ9523

C. C. :

Date : 08-12-2020

Page : 2 of 3

Description	Qty	U/ Price S\$	Amount S\$
LUGGAGE COMPARTMENT PANEL <i>Rx</i>	1	0.00	0.00
CARRIER ASSY, SPARE WHEEL <i>Rx</i>			
LUGGAGE COMPARTMENT BOARD <i>CR</i>	1	0.00	0.00
COVER, ROOM PARTITION <i>Rx</i>	1	0.00	0.00
BOARD, ROOM PARTITION RH/LH <i>Rx</i>	2	0.00	0.00
WEATHERSTRIP, TRUNK <i>pieces 500m</i>	1	0.00	0.00
STRIKER, LUGGAGE COMPARTMENT <i>Rx</i>	1	0.00	0.00
REAR EXHAUST <i>Rx</i>	1	0.00	0.00
TAILLAMP RH/LH <i>CR</i>	2	0.00	0.00
TAILLAMP GASKET RH/LH <i>CR</i>	2	0.00	0.00
TAILLAMP LOWER PANEL EXTENSION LH <i>BT</i>	1		0.00
REAR FENDER <i>Rx</i>			
SPARE TYRE BOLT <i>Rx</i>	1		0.00
SubTotal			0.00
Less 25%	1	0.00	0.00
EMBLEM, FRT BUMPER <i>new</i>	1	S.NETT 0.00	0.00
FRT ' BADGE' <i>X</i>	1	S.NETT 0.00	0.00
REAR BOOT 'BADGE' <i>new</i>	1	S.NETT 0.00	0.00
EMBLEM "E" <i>new</i>		S.NETT	
EMBLEM "VIOS" <i>new</i>	1	S.NETT 0.00	0.00
CLIPS, FRT BUMPER <i>new</i>	10	S.NETT 5.00	50.00
CLIPS, LUGGAGE COMPARTMENT TRIM	16	S.NETT 5.00	80.00
CLIPS, TAILLAMP <i>new</i>	2	S.NETT 8.00	16.00
FRT NO PLATE C/W CASING	1	<i>CR</i> 50.00 <i>45m</i>	50.00
REAR NO PLATE C/W CASING	1	<i>CR</i> 50.00 <i>45m</i>	50.00
PARKING SENSOR	1	<i>CR</i> 280.00 <i>200m</i>	280.00
TO REMOVE FRT DAMAGED PART WITH ALL NECESSARY COMPONENT/ATTACHMENT. STRAIGHTEN CHASSIS MEMBER,	1	800.00 <i>300m</i>	800.00

NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelyn191ngsautomotive@gmail.com
Reg No.: 53405718K

QUOTATION

No. : AQT-0029

INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOU BLDG
SINGAPORE 049711

TEL : 6347 6100

FAX :

Your Ref. :

Our Ref : AQT-0029/SJQ9523

C. C. :

Date : 08-12-2020

Page : 3 of 3

Description	Qty	U/ Price S\$	Amount S\$
REPAIR/RESHAPE DENTED BODY PANEL. REPLACE DAMAGED PART. REFIT INTO POSITION.			900
TO REMOVE REAR DAMAGED PART WITH ALL NECESSARY COMPONENT/ATTACHMENT. STRAIGHTEN CHASSIS MEMBER, REPAIR/RESHAPE DENTED BODY PANEL. REPLACE DAMAGED PART. REFIT INTO POSITION.	1	1,200.00	1,200.00
TO SPRAY FRT PORTION	1	600.00	600.00
TO SPRAY REAR PORTION	1	1,000.00	1,000.00
TO TRANSFER DOOR MECHANISM	2	150.00	300.00
CHECK WIRING & LIGHT FUNCTION	1	50.00	50.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

Any other parts which necessitate repair or renewal will incur additional charged.
Please contact our Ms Evelyn @ HP 96955547 to arrange for survey. Thank you.

Total

4,476.00

Yours faithfully,



NGS