

VEHICLE NO SHA4673G

DATE 08/11/20 12:00 AM

MAKE HYUNDAI

MVA CHIANG/ NTUC

MODEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT LH DOOR PANEL			\$2,256.40
1	FRONT LH INNER DOOR LOCK			\$490.80
1	FRT LH DOOR OUER HANDLE			\$36.30
LH 1	RH CENTER PILLAR OUTER			\$2,527.80
LH 1	RH ROCKER GARNISH			\$732.80
1	REAR LH DOOR PANEL			\$2,201.10
1	REAR DOOR CHECK LH			\$92.90
1	REAR DOOR LH HINGE TOP/LOWER		\$53.40	\$106.80
	SUB TOTAL		5190.30	\$8,444.90
	20.00%		4152.24	\$1,688.98
	DISCOUNTED TOTAL			\$6,755.92
1	FRONT FENDER LH ADVERTISEMENT			\$100.00
1	FRONT DOOR LH ADVERTISEMENT			\$100.00
1	REAR DOOR LH ADVERTISEMENT			\$100.00
1	FRONT DOOR COMFORT STICKER			\$75.00
1	REAR DOOR COMFORT APP STICKER			\$80.00
				\$439.50
	Labour Charge			
	Panel Beating		560	\$750.00
	Spray Painting Charge		700	\$800.00
	Remove/refix door parts			\$120.00
	Tuff coat		40	\$120.00
	Check Lighting		1420	\$60.00
	TOTAL LABOUR			\$1,850.00
	ESTIMATE TOTAL		6011.74	\$9,045.20
			4154800	
			4 days	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfer 97491749 worther.
 WP' 2/12/20 c/s
 c/s Resurvey after repair
 Tanfer c/s
 04 days