



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III20009410/Eqf3s2-1		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 10-12-2020		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 5765T	Veh. Inspected	SMN 5492C	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.	MCT20090009	Excess (\$)	0.00	
Assign From	CARINE KEK PHER SER	Assign Date	08/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT	c.c	1317	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GK33422546	Colour	BLUE	
Odometer	020341	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R14	DUNLOP	5 mm	
L/H Front Tyre	185/60 R14	DUNLOP	5 mm	
R/H Rear Tyre	185/60 R14	DUNLOP	5 mm	
L/H Rear Tyre	185/60 R14	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/09/2020	Inspection Date	04/09/2020	
Survey held at	BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @ KAKI BUKIT			
Repairer	XIN YUN AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		