



CARS FOR RENT (2016) PTE LTD

10 Kaki Bukit Ave 4 #09-60 Premier @ Kaki Bukit Singapore 415874

Tel: 6970 9119 Fax: 6970 9991

Website: www.carsforrent2016.com

No: E 16839

ROC/GST No: 201609732N

VEHICLE RENTAL AGREEMENT

Xin Yun Ant

HIRER'S PARTICULAR

Name: (as in I/C) ANG JUN SIONG

NRIC/PASSPORT No: S8520010J

Date of Birth: 12 Jul 1985

Address (Res):

Driving Licence No: S8520010J D/L Type: Local / International

Issue Date:

Tel: (O) HP

Company Name:

Company UEN:

Company Address:

ADDITIONAL DRIVER'S PARTICULARS

Name: (as in I/C)

NRIC/PASSPORT No:

Date of Birth:

Address (Res):

Driving Licence No: D/L Type: Local / International

Issue Date:

Tel: (O) HP

VEHICLE CHECK LIST

INDICATE:
D - DENTS
S - SCRATCHES
A - ACCIDENTS




RIGHT



BACK



FRONT



TOP



LEFT

Vehicle No: S1D4875R Replace Veh No: SMN5492C

Mileage out:

Make & Model: TOYOTA ALTIS Auto / Manual

OUT: Date 02/09/20 Time: 15:00 PM

HIRE PERIOD

OWN DAMAGE CLAIM Excess S\$

2000

THIRD PARTY CLAIM Excess S\$

1500

CHARGES

Daily 10 @ \$ 120 per day \$ 1200 00

Weekly @ \$ per week

Monthly @ \$ per month

Others @ \$

Delivery Service

GST

SUB-TOTAL \$

PETROL LEVEL

Out	E	1/4	1/2	3/4	F
In	E	1/4	1/2	3/4	F

EXTENSION

Misc.

GST

TOTAL CHARGES 1200 00

Rented out by:

Hirer's Signature

Addition Driver's Signature

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/ credit card for payment, I agree that all amount payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given CARS FOR RENT (2016) PTE LTD in connection with this agreement is true.

* IMPORTANT

1. ONLY PERSON ABOVE 22 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
2. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
3. THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN ABOVE.
4. IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
5. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY CARS FOR RENT (2016) PTE LTD

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVE" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO CARDS FOR RENT (2016) PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	HIRER'S SIGNATURE
<u>12/9</u>	<u>13:00 PM</u>				

Invoice



Date: 2020/09/01
Invoice No.: 202009180
Due Date: 2020/09/13

KAOLIN MOTOR TRADING CO.
71 UBI ROAD 1#05-35 OXLEY BIZHUB SINGAPORE
408732 TEL:+65 88009090
EMAIL:KAOLIN2020HQ@GMAIL.COM

Bill To:
XIN YUN AUTO PRIVATE
LIMITED

Date	Item	Description	Unit Price	Total
1	SMN5492C	TO WORKSHOP XIN YUN AUTO #05-23 PREMIER KAKI BUKIT	\$60	\$60

Total \$60.00
Balance Due \$60.00

Please contact us for more information about payment options.

Thank you for your business.

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189
Email: mirage1195@gmail.com Mobile: 9061 0543

Ang Jun Siong
Blk 348A Yishun Ave 11
#15-545
Singapore 761348

Invoice no:	POS0249/20
Date:	14 October 2020
Report no:	249M0920.XY
Vehicle :	SMN5492C

INVOICE

No	Item Description	Qty	Unit Price	Total Amount(\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			907.00
SGD(\$): Nine Hundred and Seven only			Payable Amount:	907.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES



.....
Authorised Signature

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Email: mirage1195@gmail.com Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 249M0920.XY
Vehicle no : SMN5492C

1 REFERENCE

Date of inspection : 4 September 2020
Requested by : Ang Jun Siong
Blk 348A Yishun Ave 11
#15-545
Singapore 761348
Type of survey : Independent
Repairer : Xin Yun Auto Pte Ltd
Blk 8 Kaki Bukit Avenue 4, #05-23 Premier@Kaki Bukit, Singapore 415875
Date of accident : 1 September 2020

2 VEHICLE DATA

Make/Model : **HONDA FIT 1.3GF CVT**
Chassis no : GK33422546
Engine no : L13B3937036
Date of registration : 16 August 2019
Engine capacity : 1317 cc
Odometer reading : 020341 km
Colour : Black

3 STATIC CONDITION CHECK

Steering : Serviceable
Foot brakes : Serviceable
Hand brakes : Serviceable
Paintwork : Good
General Condition : Good

4 TIRE CONDITION CHECK

	<u>RH/MAKE</u>	<u>LH/MAKE</u>	<u>SIZE</u>
Front tread	: 8 mm/Yokohama	8 mm/Yokohama	175/7014
Rear tread	: 8 mm/Yokohama	8 mm/Yokohama	175/7014

5 BRIEF DESCRIPTION OF DAMAGE

Rear bumper dented/torn/deformed, rear end panel dented/bent/distorted, spare tyre panel crumpled, rear LH fender buckled, taillamp base panels bent, rear LH door edge paintwork damaged, rear boot lid dented/bent/distorted, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : \$10,132.82
No. of days taken : Eight (8)

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 249M0920.XY

Vehicle no: SMN5492C

A SPARE PARTS

<u>Description</u>	<u>Qty</u>	<u>Assessed</u> <u>Condition</u>	<u>Repairer's</u> <u>Amount</u>	<u>Revised</u> <u>Amount</u>	
Rear bumper	1	torn/grazed/deformed	742.31	742.31	
Rear bumper spacer/side retainer LH/RH	2	end broken/necessary	64.20	64.20	
Rear bumper side retainer RH	1	serviceable	32.20	0.00	
Rear bumper side cover, left & right	2	bent/deformed	105.94	105.94	
Rear bumper centre garnish	1	dented/bent/distorted	90.95	90.95	
Rear bumper clip	8	necessary	31.20	31.20	
Rear end panel/RR panel	1	dented/bent/distorted	550.00	550.00	
Rear end panel garnish c/w clip set	1	bent/distorted	96.00	96.00	
Spare tyre panel	1	to repair	1,135.80	0.00	
Spare tyre top board	1	to reuse	299.76	0.00	
Tail gate assy	1	dented/bent/distorted	989.20	989.20	
Tail gate inner lock assy	1	bent/distorted	188.20	188.20	
Tail gate absorber/gas shock stay LH/RH	2	bent/stiffened	470.00	470.00	
Tail gate trim board c/w clip	1	clip brackets squashed/fractured	358.00	358.00	
Tail gate outer garnish	1	mount bent/cracked	250.80	250.80	
Tail gate outer garnish "H" logo	1	necessary	30.00	30.00	
Tail gate "FIT" emblem	1	necessary	40.13	40.13	
Tail gate outer garnish clip	6	necessary	23.40	23.40	
Rear windscreen moulding set	1	necessary	320.00	320.00	
Rear boot weatherstrip	1	pinched/bent/deformed	220.00	220.00	
Tail gate side reflector LH	1	to reuse	351.00	0.00	
Tail gate side reflector RH	1	to reuse	351.00	0.00	
Rear windscreen wiper motor assy	1	shaft bent	274.40	274.40	
LH taillamp assy	1	side scraped	500.00	500.00	
RH taillamp assy	1	serviceable	500.00	0.00	
Taillamp base panel	2	to repair/repaint	256.60	0.00	
Gutter panel LH	1	bent/distorted	123.05	123.05	
Rear fender trim LH	1	bent/deformed	333.84	333.84	
LH rear fender	1	to repair/repaint	726.90	726.90	
		Subtotal of the above	9,454.88	6,528.52	
		Discount	20% / 20%	1,890.98	1,305.70
<u>(Special nett)</u>		Subtotal 1:	7,563.90	5,222.82	
Reverse sensor set	1	dented/shorted	280.00	280.00	
Rear windscreen sealant	1	necessary	80.00	80.00	
Rear parking camera set	1	shorted	580.00	580.00	
		Subtotal 2:	940.00	940.00	
		Total cost of parts:	8,503.90	6,162.82	

B LABOUR

To remove and refit rear fender inner cover and attachments, rear passenger set, floor covering and upholstery, etc to facilitate the necessary repairs.	450.00	300.00
To remove and reinstall reverse sensors on the rear bumper and check for sensing functions.	80.00	60.00
To check wire condition and rectify fault where necessary.	45.00	30.00

To apply rustproofing for the accident affected areas.

200.00 120.00

Report no: 249M0920.XY

Vehicle no: SMN5492C

Labour charges to dismantle and remove damaged parts, and to install new parts; to cut out and remove damaged panels and to install new panels and weld; to knock, straighten and align affected areas.

2,100.00 1,500.00

Labour and materials charges for spray painting rear bumper, rear LH fender, rear end panel, spare tyre panel, taillamp base panels, Tail gate, rear LH door and necessary areas.

2,000.00 1,750.00

To remove, transfer and install Tail gate electrical wiring, fittings and attachments to new boot lid.

120.00 90.00

To remove, transfer and install rear windscreen glass.

150.00 120.00

Total cost of labour:

5,145.00 3,970.00

Total cost of repair:

13,648.90 10,132.82

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is

\$10,132.82

(a) The recommended cost of repair would be

\$10,132.82

(b) The number of days taken by the repairs would be

Eight (8)

(1st Reinspection conducted on 4 September 2020)

(2nd Reinspection conducted on 8 September 2020)


(Post Repair Inspection conducted on 11 September 2020)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Note: Lump Sum Repair Basis

This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.

Prepared by:



Liaw Leong San

Licensed Automotive Appraiser

Dated: 14 October 2020



Report no: 249M0920.XY

Vehicle no: SMN5492C



Report no: 249M0920.XY

Vehicle no: SMN5492C



Report no: 249M0920.XY

Vehicle no: SMN5492C

