



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: AUTO & GENERAL INSURANCE (SINGAPORE)

190 CLEMENCEAU AVENUE

#03-01 SINGAPORE SHOPPING CENTRE

SINGAPORE 239924

TEL: 6221 2111

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 07/12/2020

TP Veh Reg No: SKF4292K

Estimate No: ES2000111

Date: 14 Dec 2020

Policy No:

Veh Reg No: SKR3665L

Make/Model: TOYOTA HARRIER 2.4G A

Chassis No: ACU300108942

Engine No: 2AZB428010

Reg. Date: 18/03/2011

Estimate Repair Cost to Vehicle No :SKR3665L

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Spare Parts				
1 REAR BUMPER <i>860.40</i>	1,438.00	1 PC	<i>Av</i> 1,438.00	<i>✓</i>
2 REAR BUMPER BUZZER SENSOR	198.00	1 PC	<i>Sm</i> 198.00	<i>X</i>
3 REAR BUMPER CLIPS	60.00	1 SET	<i>Sm</i> 60.00	<i>✓</i>
4 REAR BUMPER REFLECTOR - LH	124.00	1 PC	<i>Sm</i> 124.00	<i>X</i>
5 REAR BUMPER REFLECTOR - RH	124.00	1 PC	<i>Sm</i> 124.00	<i>X</i>
6 REAR BUMPER REINFORCEMENT <i>329.30</i>	525.30	1 PC	<i>Av</i> 525.30	<i>✓</i>
7 REAR BUMPER SIDE RETAINER - LH	98.00	1 PC	<i>Sm</i> 98.00	<i>X</i>
8 REAR BUMPER SIDE RETAINER - RH	98.00	1 PC	<i>Sm</i> 98.00	<i>X</i>
9 REAR BUMPER SPONGE <i>118</i>	281.00	1 PC	<i>CM</i> 281.00	<i>✓</i>
10 REAR END PANEL	698.50	1 PC	<i>R</i> 698.50	<i>X</i>
11 REAR EXHAUST MOUNTINGS	82.10	1 PC	<i>Sm</i> 82.10	<i>X</i>
12 REAR EXHAUST MUFFLER	980.00	1 PC	<i>R</i> 980.00	<i>X</i>
13 REAR NUMBER PLATE	60.00	1 PC	<i>Sm</i> 60.00	<i>X</i>
14 REAR TAILGATE	1,821.00	1 PC	<i>R</i> 1,821.00	<i>X</i>
15 REAR TAILGATE 'LOGO'	81.00	1 PC	<i>Sm</i> 81.00	<i>X</i>
16 REVERSE SENSORS <i>258</i>	350.00	1 PC	<i>CM</i> 350.00	<i>200.00</i>
			7,018.90	7,018.90
Labour				
17 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,200.00	1 JOB	1,200.00	<i>400.00</i>
18 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,200.00	1 JOB	1,200.00	<i>420.00</i>
19 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	<i>na</i> 200.00	<i>X</i>
20 TO REMOVE/TRANSFER TAILGATE COMPONENTS.	120.00	1 PC	<i>na</i> 120.00	<i>X</i>
21 TO CHECK WIRING FUNCTIONS.	100.00	1 JOB	100.00	<i>100.00</i>
22 TO REMOVE/REFIT REAR WINDSCREEN LABOUR	220.00	1 JOB	<i>na</i> 220.00	<i>X</i>
			3,040.00	3,040.00

LKK Auto Consultants hence notify
Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : AUTO & GENERAL INSURANCE (SINGAPORE)

190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2111

ATTN: Motor Claim Department

Estimate No: **ES2000111**

Date: 14 Dec 2020

Policy No:

Veh Reg No: **SKR3665L**

Make/Model: TOYOTA HARRIER 2.4G
A

Chassis No: ACU300108942

Engine No: 2AZB428010

Reg. Date: 18/03/2011

Your Ref No: -

Claim Type: Third Party

Accident Date: 07/12/2020

TP Veh Reg No: SKF4292K

Estimate Repair Cost to Vehicle No :SKR3665L

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 10,058.90
			Add GST @ 7%	704.12
			Total Amount Payable	<u>S\$ 10,763.02</u>

TOTAL: SINGAPORE DOLLAR TEN THOUSAND SEVEN HUNDRED SIXTY THREE AND CENTS TWO ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE