

Our Job Ref No : 305437872

Date : 23.12.20

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. : SHD7243D CTPL

08.12.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **NTUC** **FBJ7050H**

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%

\$1,900.00

**Final Lumpsum Repair cost**

**\$1,900.00**

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.


We confirm the estimates and  
finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Taufikh

Date : 28/12/20

### For Official Use Only

| Item                                                 | Amount          | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|------------------------------------------------------|-----------------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |                 | YES                         |                        |         |
| 2. Loss of Income Paid                               |                 | NO                          |                        |         |
| 3. Survey Fees                                       |                 |                             |                        |         |
| 4. LTA Search Fee                                    | \$7.49 / \$2.00 |                             |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |                 |                             |                        |         |
| 6. Overrun                                           |                 |                             |                        |         |

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305437872  
 REGN NO : SHD7243D  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G2)  
 DATE OF REGN : 22.11.2018  
 DATE/TIME IN : 08.12.2020 11:05  
 ACCIDENT DATE : 08.12.2020

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

|      |                   |                           |      |        |       |        |         |
|------|-------------------|---------------------------|------|--------|-------|--------|---------|
| 0001 | 04-01-0104-2282-G | IONIQVC COVER-RR BUMPER#  | 1 L  | 459.40 | 20.00 | 367.52 | inc ✓   |
| 0002 | 04-01-0101-0111-G | HYUNDAI BUMPER COVER CLIP | 10 L | 22.00  | 20.00 | 17.60  | net ✓   |
| 0003 | 04-01-0104-2533-G | MOULDING ASSY-RR BUMPER C | 1 L  | 451.25 | 20.00 | 361.00 | inc ✓   |
| 0004 | 09-01-9999-0068-A | HYUNDAI REVERSE SENSOR AS | 1 N  | 180.00 | 10.00 | 162.00 | net ✓   |
| 0005 | 04-01-0104-1150-A | IONIQVC PROTECTOR MAT     | 1 N  | 50.00  | 1.00  | 50.00  | net ✓   |
| 0006 | FNPS              | NO PLATE(S) WITH TRIM COV | 1 N  | 55.00  | 10.00 | 49.50  | net ✓   |
| 0007 | 04-01-0104-2370-G | IONIQVC LAMP ASSY-REAR FO | 1 L  | 201.50 | 20.00 | 161.20 | X       |
| 0008 | 04-01-0104-2545-G | MOULDING-REAR BUMPER LWR  | 1 L  | 155.50 | 20.00 | 124.40 | Ry      |
| 0009 | 04-01-0104-2270-G | IONIQVC EMBLEM-HYBRID     | 1 L  | 24.30  | 20.00 | 19.44  | net ✓   |
| 0010 | 04-01-0104-2271-G | IONIQVC EMBLEM-IONIQ      | 1 L  | 31.30  | 20.00 | 25.04  | net ✓   |
| 0011 | 28-01-9999-2025-A | APP LOGO REAR BONNET CTPL | 1 N  | 40.00  | 10.00 | 36.00  | net ✓ + |
| 0012 | 28-01-0103-0005-A | (I40)REAR BOOT LOGO CTPL  | 1 N  | 30.00  | 10.00 | 27.00  | net ✓   |
| 0013 | 28-01-0103-0006-A | (I40)REAR BOOT TEL NUMBER | 1 N  | 30.00  | 10.00 | 27.00  | net ✓   |

Nett \$335  
 = 10%  
 301.50  
 + 30  
 Nett \$351.50

988.25  
 -20%

790.60  
 351.50

\$1,142.10

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305437872  
 REGN NO : SHD7243D  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G2)  
 DATE OF REGN : 22.11.2018  
 DATE/TIME IN : 08.12.2020 11:0  
 ACCIDENT DATE : 08.12.2020

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,427.70

1,142.10

## B NATURE

|                      |                                  |        |     |            |
|----------------------|----------------------------------|--------|-----|------------|
| 0000 20-05           | REAR BUMPER ADVERTISMENT LOGO    | 50.00  | cut |            |
| 0001 20-05           | BOOTLID ADVERTISMENT LOGO        | 50.00  | cut |            |
| 0002 20-05           | REAR FENDER ADVERTISMENT LOGO RH | 100.00 | cut |            |
| 0003 20-05           | REAR FENDER ADVERTISMENT LOGO LH | 100.00 | cut |            |
| 0004 L               | PANEL BEATING(repair Spoiler)    | 700.00 | 480 | 300<br>940 |
| 0005 23-502          | SPRAYPAINT ON AFFECTED AREA      | 500.00 | 400 | 1,240      |
| 0006 17-01           | CHECK ALL LIGHTING               | 50.00  | 30  | 2,382.10   |
| 0007 20-22           | REMOVE/REFIX REVERSE SENSOR      | 120.00 | 30  | -20%       |
| SUB-TOTAL : 1,670.00 |                                  |        |     | 1,905.68   |

Tanpin 9745 5749 Davant  
 WP' 8/12/20 24pm

C/S Resumy after repair \$1,900/-

3days

Tanpin C Phamkum.