

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 08.12.2020
Time: 14:06:12
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305437872
REGN NO : SHD7243D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 22.11.2018
DATE/TIME IN : 08.12.2020 11:05
ACCIDENT DATE : 08.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52	inc ✓
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	nei ✓
0003	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1 L	451.25	20.00	361.00	ana ✓
0004	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	180.00	10.00	162.00	nn ✓
0005	04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1 N	50.00	1.00-	50.00	nei ✓
0006	FNPS	NO PLATE(S) WITH TRIM COV	1 N	55.00	10.00	49.50	cut ✓
0007	04-01-0104-2370-G	IONIQVC LAMP ASSY-REAR FO	1 L	201.50	20.00	161.20	x nn ✓
0008	04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1 L	155.50	20.00	124.40	Ry ✓
0009	04-01-0104-2270-G	IONIQVC EMBLEM-HYBRID	1 L	24.30	20.00	19.44	nei ✓
0010	04-01-0104-2271-G	IONIQVC EMBLEM-IONIQ	1 L	31.30	20.00	25.04	nei ✓
0011	28-01-9999-2025-A	APP LOGO REAR BONNET CTPL	1 N	40.00	10.00	36.00	nn ✓
0012	28-01-0103-0005-A	(I40)REAR BOOT LOGO CTPL	1 N	30.00	10.00	27.00	nei ✓
0013	28-01-0103-0006-A	(I40)REAR BOOT TEL NUMBER	1 N	30.00	10.00	27.00	nei ✓

988.25
20% - 795.60
335
10% - 39.50
SN - 50
1142.10

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305437872
 REGN NO : SHD7243D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 22.11.2018
 DATE/TIME IN : 08.12.2020 11:0
 ACCIDENT DATE : 08.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,427.70

JOB NATURE

0000 20-05	REAR BUMPER ADVERTISMENT LOGO	50.00	cut ✓
0001 20-05	BOOTLID ADVERTISMENT LOGO	50.00	cut ✓
0002 20-05	REAR FENDER ADVERTISMENT LOGO RH	100.00	cut ✓
0003 20-05	REAR FENDER ADVERTISMENT LOGO LH	100.00	cut ✓
0004 L	PANEL BEATING(repair Spoiler)	700.00	480
0005 23-502	SPRAYPAINT ON AFFECTED AREA	500.00	400
0006 17-01	CHECK ALL LIGHTING	50.00	30
0007 20-22	REMOVE/REFIX REVERSE SENSOR	120.00	30

SUB-TOTAL : 1,670.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 9749 5749
 'UP' 8/12/20 24pm

C/S Resurvey after repair
 3 days

Tanpin C P Khaw

Davant

1142.10

1240

2382.10

1/5 @ 1900

- 3 days #