

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/198R GST Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL		Ref:	CS/AGI20013561/Aqf3q2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE		Date:	01/03/2021	
				Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMP 8550M	Veh. Inspected		SKP 46D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10008246/LA	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		08/12/2020	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA CHR HYBRID	c.c		1797	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	ZYX102017036	Colour		WHITE	
	Odometer	98574 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/50 R18	YOKOHAMA		6 mm	
	L/H Front Tyre	225/50 R18	YOKOHAMA		6 mm	
	R/H Rear Tyre	225/50 R18	YOKOHAMA		6 mm	
	L/H Rear Tyre	225/50 R18	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	05/12/2020	Inspection Date)	10/12/2020	
	Survey held at	SIN FATT DIESEL MOTOR COMPANY				
		BLK 3020A UBI ROAD 1 #01-38 . SINGAPORE 408714				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR:

13 Working Days