



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

07/12/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 07/12/2020

Estimated repair cost for vehicle no: SLR7394E TOYOTA WISH 1.8 CVT A '17

CHASSIS: ZGE206037020

TP111

Cecilia

S/n	Qty	Items	U/price	Amount	
1	1	Rear Bumper <i>Dented.</i>		\$481.90	✓
2	1	Rear L/H Bumper Side Retainer <i>Crackd</i>		\$121.25	65
3	8	Rear Bumper Clip <i>Ne</i>	\$6.50	\$52.00	30
4	1	Rear L/H Bumper Side Reflector <i>xtb new</i>		\$131.35	x
5	1	Rear Bumper Bracket <i>Not new</i>		\$131.35	x
6	1	Rear L/H Fender <i>Dented.</i>		\$1,217.30	✓
7	1	Rear L/H Fender Glass <i>3x4</i>		\$561.60	x
8	1	Rear R/H Fender Glass Seal <i>1 new</i>		\$50.00	x
9	1	Rear L/H Fender Inner Trim Board <i>3x4</i>		\$781.40	x
10	8	Rear L/H Fender Inner Trim Board Clip <i>1 new</i>	\$6.50	\$52.00	x
11	1	Rear L/H Fender Lower Mud Flap <i>xtb new</i>		\$87.80	x
12	1	Rear L/H Fender Air-Duct <i>xtb new</i>		\$92.20	x
13	1	Rear L/H Door <i>Dented.</i>		\$1,217.10	✓
14	2	Rear L/H Door Frame Sticker <i>new</i>	\$172.25	\$344.50	60
15	1	Front L/H Door Inner Trim Board <i>3x4 new</i>		\$781.10	x
16	1	Front L/H Door Gear Motor Assy <i>1</i>		\$987.30	x
17	1	Rear L/H Tyre <i>xtb new</i>		\$350.00	x
18	1	Rear L/H Rim <i>at</i>		\$680.00	400(50)
19	1	Rear L/H Shock Absorber <i>Best.</i>		\$231.20	✓
20	1	Rear L/H Axle Bearing <i>Dayd</i>		\$689.30	561
21	1	Rear Axle <i>Best</i>		\$2,721.20	2318.40
22	1	L/H Side Skirt <i>Dekend</i>		\$485.60	✓
23	1	L/H Rocker Panel Skirt <i>xtb new</i>		\$987.30	x
24	10	L/H Rocker Panel Skirt Clip <i>xtb new</i>	\$6.50	\$65.00	x

6867.80

Subtotal :- \$13,299.75

5150.62 S.N. 400

Labour charges

To remove & refit cushion & trim board	\$280.00 80
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear fender glass	\$120.00 60
To remove & refit axle & bearing	\$380.00 300
To check wheel alignment	\$150.00 80
To remove & refit rear L/H door, gear motor, trim board, glass, lock, rubber & frame sticker	\$180.00 80
Gum	\$60.00 40
To check wiring	\$100.00 30
Tuff kote	\$150.00 60
Towing	\$150.00 x
Panel beating	2380 \$1,800.00 80
Spray painting	\$1,600.00 800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$5,070.00
Total:- \$18,369.75

Total: 793062
L/s: 6.3K
07 Days

6.3K