


Section A - Accident Details

Registration Number	SHB5218B
Case Reference Number	TAX/12/20/2007
Registration Date	26/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	YEO SIEW FATT
Type of Accident	Head To Side
Accident Date and Time	4/12/2020 2:00 PM
Accident Reported Date and Time	5/12/2020 9:29 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109050
Special Instruction to ARC, if any	TP / REAR LEFT PORTION
Prepared Date and Time	6/12/2020 6:37 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$854.00	\$300.00
Total Spray Cost	\$1,854.00	\$380.00
Total Spare Part Cost	\$9,669.56	\$1,881.46
Total Other Cost	\$600.00	\$30.00
TOTAL COST	\$12,977.56	\$2,591.46 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	GUO QIANG (LKK) / China Taiping
ARC / Surveyor Sign Off Date	08/12/2020 3:53 PM	08/12/2020 4:12 PM
Signature		
Remarks	Total number of repair days = 3 days SUP = 0 day	part by part repair / before paint photo / FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR quogiang (LKK) & Email

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2012-0213	Invoice Number	
Quotation Date	16.12.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	\$854.00	\$300.00
Total Labour	\$854.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR BUMPER REINFORCEMENT	\$180.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY REAR SPOILER	\$180.00	\$80.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,854.00	\$380.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO WASH AND VACUUM	\$80.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$600.00	\$30.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$485.60	25.00	\$364.20	Replace	Replace
		52599-68030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.50	0.00	\$0.00	Replace	Not Given
		52462-47020	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.00	25.00	\$6.00	Replace	Replace
		52462-47030	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.00	25.00	\$6.00	Replace	Replace
		52462-47130	PAD, RR BUMPER, RH & LH, 3	2.00	\$11.00	25.00	\$16.50	Replace	Replace
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.30	25.00	\$16.95	Replace	Replace
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace
		52576-47060	RETAINER, RR BUMPER, LH	0.00	\$132.60	0.00	\$0.00	Replace	Check
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$374.50	25.00	\$280.88	Replace	Replace
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$11.00	25.00	\$24.75	Replace	Replace
		52592-47080	SEAL, RR BUMPER, LH	0.00	\$118.30	0.00	\$0.00	Replace	Not Given

PE
 NN
 NEC
 NN
 Cut
 Nec
 NN

	52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$332.70	0.00	\$0.00	Replace	Check X	NN
		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	NEC
	76801-47170-A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$913.60	100.00	\$0.00	Replace	Repair	
	75403-48010	EMBLEM SUB-ASSY REAR	1.00	\$47.90	25.00	\$35.92	Replace	Replace	
	75441-47220	NAME PLATE (HYBRID) LUGGAGE COMPARTMENT	1.00	\$54.60	25.00	\$40.95	Replace	Replace	
	75442-47200	NAME PLATE (PRIUS) LUGGAGE COMPARTMENT	1.00	\$54.60	25.00	\$40.95	Replace	Replace	
		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	
	76085-47916	SPOILER SUB-ASSY, REAR	1.00	\$1,575.40	100.00	\$0.00	Replace	Repair	
	67005-47530	TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$1,147.80	0.00	\$0.00	Replace	Not Given X	
	TMKONG-TAILG	AUTO TAILGATE SYSTEM	0.00	\$2,520.00	0.00	\$0.00	Replace	Not Given X	
	68810-47061	TAIL GATE BACK DOOR HINGE ASSY, LH	0.00	\$61.00	0.00	\$0.00	Replace	Not Given X	
	68810-47061	TAIL GATE BACK DOOR HINGE ASSY, RH	0.00	\$61.00	0.00	\$0.00	Replace	Not Given X	
	69350-47050	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$467.00	0.00	\$0.00	Replace	Not Given X	
	69321-47010	TAIL GATE LOCK COVER, BACK DOOR	0.00	\$30.20	0.00	\$0.00	Replace	Not Given X	
	69430-52050	TAIL GATE STRIKER ASSY, BACK DOOR	0.00	\$25.80	0.00	\$0.00	Replace	Not Given X	
	81920-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	0.00	\$39.00	0.00	\$0.00	Replace	Check X	
		REVERSE SENSOR, REAR BUMPER	0.00	\$180.00	0.00	\$0.00	Replace	Check X	
	81561-47471	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$339.60	0.00	\$0.00	Replace	Check X	
	81498-47040	COVER, REAR COMBINATION LAMP, LH	0.00	\$69.90	0.00	\$0.00	Replace	Check X	
	81456-47020	LENS & BODY, REAR COMBINATION LAMP, NO 2	0.00	\$261.00	0.00	\$0.00	Replace	Check X	
	81590-47070	LAMP ASSY, REAR, LH	0.00	\$293.60	0.00	\$0.00	Replace	Not Given X	
	61602-47180	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$871.50	0.00	\$0.00	Replace	Not Given X	
	61622-47060	TROUGH, BACK DOOR, LH	0.00	\$103.40	0.00	\$0.00	Replace	Not Given X	
Total				\$10,700.30		\$1,016.25			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		76801-47170-A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$913.60	25.00	\$685.20	Replace	Replace
			REVERSE SENSOR, REAR BUMPER	1.00	\$180.00	0.00	\$180.00	Replace	Replace
Total					1,093.60		865.20		

1281.46
+ 300.00
+ 410.00

2591.46

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: