

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

9-Dec-20

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1514 L

1 pc	Front n/s door	\$ 1,723.60 <i>Rp</i>
2 pcs	Front n/s door hinges @ \$36.10	\$ 72.20 <i>Rp</i>
1 pc	Rear n/s door	\$ 2,017.48 <i>hf</i>
2 pcs	Rear n/s door hinges @ \$36.10	\$ 72.20 <i>Rp</i>
1 pc	Rear n/s fender	\$ 1,525.73 <i>Rp</i>
1 pc	Rear n/s rim	\$ 246.00 <i>cut</i>
1 pc	Rear bumper n/s & o/s side bracket @ \$32.50	\$ 65.00 <i>Dr un</i>
1 pc	Rear bumper	\$ 811.11 <i>Rp</i>
<i>Supp</i>	<i>Frt n/s door handle outer 105.50 cut</i>	\$ 6,533.32 <i>2416.89</i>
	<i>Frt n/s door handle cover 47.91 cut</i>	\$ 1,306.66
	Less 20%	\$ 5,226.66 <i>2416.89</i>

S/NETT

1 set	n/s door sticker
1 pc	Rear n/s fender sticker
1 set	Rear n/s fender inner shield clips
1 set	Rear bumper clips

Sundry

To check rear n/s wheel alignment

To dismantle and refit the inner components of the front & rear n/s doors into new shell door

To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the same etc

To putty and spray painting on front n/s door, rear n/s door, n/s rocker panel, rear n/s fender, rear bumper

To apply rustproofing on the repaired and replaced panels.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 100.00 <i>60</i>
\$ 60.00 <i>40</i>
\$ 28.00 <i>unx</i>
\$ 48.00 <i>unx</i>
\$ 50.00 <i>20</i>
\$ 80.00 <i>✓</i>
\$ 300.00 <i>60</i>

\$ 1,200.00 <i>100</i>
\$ 1,000.00 <i>3723.51</i>
\$ 200.00 <i>1620</i>
\$ 8,292.66 <i>30</i>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanphie 97495749 WP
9/12/20 e 12pm
4/s Resurvey after repair
Tanphie 1/11/20 e 12pm
05 days