

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

9-Dec-20

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1514 L

1 pc	Front n/s door	\$	1,723.60	Ry
2 pcs	Front n/s door hinges @ \$36.10	\$	72.20	Ry
1 pc	Rear n/s door	\$	2,017.48	hf
2 pcs	Rear n/s door hinges @ \$36.10	\$	72.20	Ry
1 pc	Rear n/s fender	\$	1,525.73	Ry
1 pc	Rear n/s rim	\$	246.00	amb
1 pc	Rear bumper n/s & o/s side bracket @ \$32.50	\$	65.00	Ry
1 pc	Rear bumper	\$	811.11	Ry
		\$	6,533.32	
Less 20%		\$	1,306.66	
		\$	5,226.66	

S/NETT

1 set	n/s door sticker
1 pc	Rear n/s fender sticker
1 set	Rear n/s fender inner shield clips
1 set	Rear bumper clips
Sundry	
To check rear n/s wheel alignment	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	100.00	60	new
\$	60.00	40	new
\$	28.00		2X
\$	48.00		1
\$	50.00		20.
\$	80.00		✓
\$	300.00		60
\$	1,200.00		700
\$	1,000.00		800
\$	200.00		
\$	8,292.66		

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanpin 97495744 WP
9/12/20 @ 12pm
L/S Resurvey after repair
Tanpin 11/12/20 @ 5days