



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

2/12/2020

Survey Details:

| | |
|---------------------|-----------------------|
| Date of loss | 7-Dec-20 |
| Date of appointment | 9-Dec-20 |
| Date of survey | 9-Dec-20 |
| Location of survey | PAUL HO ENTERPRISE PL |

Vehicle Details:

| | |
|----------------------|--------------------------|
| Claim Type: | Third Party Claim |
| Vehicle number | GBJ 6396S |
| Make and Model | TOYOTA HIACE DX 2.8 AUTO |
| Date of registration | 26/6/2019 |
| Excess | - |
| Market Value | \$ 65,000.00 |
| Parf Rebate | \$ 19,898.00 |
| Nett Loss | \$ 45,102.00 |

Repair details:

| | |
|------------------|------|
| Initial Estimate | \$ - |
|------------------|------|

Proposed/Revised repair cost:

| | |
|--------------------------------|------|
| Parts | |
| Check items (estimate) | |
| Labour | |
| Total | \$ - |
| Lump Sum(if applicable) | |

| | |
|----------------------------------|------------------|
| Number of days for repair | <u>12</u> |
|----------------------------------|------------------|



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

The estimate repair cost of the damaged vehicle is in the region of \$11,000.00 - \$12,000.00.

Mandate:

| Liability(TP) | % | |
|-----------------------|----------------|-------------|
| Proposed repair cost | \$ | |
| Loss of use | \$ | no. of days |
| Loss of rental | \$ | no. of days |
| Loss of income | \$ | no. of days |
| LTA search fees | \$ | |
| Others | \$ | |
| Proposed Total | #VALUE! | |