

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM20013570/T1qf3e2 8 SHENTON WAY #24-01 AXA Date: 29/01/2021 **TOWERSINGAPORE 068811** ATTN: YVONNE ANG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHB 7670P** Veh. Inspected **GBJ 6396S** Policy No. Coverage (\$) 0.00 Claim No. S0M02YHK Excess (\$) 0.00 YVONNE ANG **Assign Date** 09/12/2020 Assign From **Vehicle Particulars & Condition** 2. TOYOTA HIACE Make & Model 2754 C.C HIDDEN 2019 Year of Reg. Engine No. GDH2012005138 SILVER Chassis No. Colour Odometer 34084 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/80 R15 DUNLOP 6 mm DUNLOP L/H Front Tyre 195/80 R15 6 mm 195/80 R15 DUNLOP R/H Rear Tyre 6 mm **DUNLOP** L/H Rear Tyre 195/80 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. **General Information** 07/12/2020 Inspect Date / Time 09/12/2020 (11:20 AM) Accident Date PAUL HOE BATTERIES & MOTOR SERVICES Survey held at BLK 1 KAKI BUKIT AVE 6 #01-109 AUTOBAY SINGAPORE 417833 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$11,000.00-\$12,000.00 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM20013570/T1qf3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

ESTIMATED NORMAL PERIOD FOR REPAIR:

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

12 Working Days

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.