

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20013576/T1TF3E2
Date: 04/01/2021

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	ML000257	
Claimant Vehicle No :	SHA5092B	Insured Vehicle No :	SGW9993X	
Date of Loss:	05/12/2020	Nature of Claim:	TP	Claim No: M2006057

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA5092B		
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Engine No:	D4FDGU693736
Reg. Date:	15/12/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMHU097089
Colour:	Blue	Odometer:	496002 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,744.88	6,244.68	1,500.20	19.37
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,600.00	1,360.00	240.00	15.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,355.88	7,615.68	1,740.20	18.60
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	9,355.88	6,100.00	3,255.88	34.80
+ GST 7.00/7.00% (S\$)	654.91	427.00	227.91	34.80
Nett Amount (S\$)	10,010.79	6,527.00	3,483.79	34.80

INSPECTION

Date of Assignment:	09/12/2020	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
---------------------	------------	-------------------	--

Date Inspected: 08/12/2020
Estimated Period of Repair: 4.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	MRM-SG Version: 1.0 (Last Synchronised: 04 Jan 2021)
Parts:	143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA5092B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER COVER	Cracked	1,025.25 FL	-	*1,025.20 FL
2	1		*FRT BUMPER REINFORCEMENT	Not Necessary	588.40 FL	-	*- FL
3	1		*FRT BUMPER BRACKET UPPER RH	Not Necessary	44.80 FL	-	*- FL
4	1		*FRT BUMPER BRACKET SIDE RH	Cracked	24.60 FL	-	*24.60 FL
5	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
6	1		*FRT BUMPER LIP	Torn	152.00 FL	-	*152.00 FL
7	1		*FRT SUPPORT PANEL ASSY	Not Necessary	907.40 FL	-	*- FL
8	1		*BONNET	Bent	2,265.90 FL	-	*2,265.90 FL
9	1		*FRT RADIATOR GRILLE	Cracked	1,480.00 FL	-	*1,480.00 FL
10	1		*FRT RADIATOR GRILLE EMBLEM H	Necessary	129.50 FL	-	*129.50 FL
11	1		*FRT FENDER RH	Bent	663.00 FL	-	*663.00 FL
12	1		*FRT FENDER SHIELD RH	Deformed	174.90 FL	-	*174.90 FL
13	1		*HEADLAMP ASSY RH	Cracked	1,800.00 FL	-	*1,800.00 FL
14	1		*FRT UNDER COVER	Not Necessary	334.60 FL	-	*- FL
15	1		*FRT NUMBER PLATE WITH TRIM COVER	Bent	55.00 F	-	*55.00 F
					Sub Total (S\$)	9,667.35	7,792.10
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,922.47	1,547.42
					Total Parts (S\$)	7,744.88	6,244.68

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	850.00	700.00
2	SPRAYPAINT PAINTING CHARGE	New	650.00	600.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	30.00
Gross Labour Cost (\$\$)			1,600.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >