

Our Job Ref No : 305437742
Date : 19.12.20

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. : SHA5092B CTPL

05.12.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SGW9993X

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%

\$6,100.00

Final Lumpsum Repair cost

\$6,100.00

3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Taufikh

Date : 28/12/20

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Like

Tokio Marine

Date: 08.12.2020

Time: 12:28:02

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305437742
 REGN NO : SHA5092B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 15.12.2016
 DATE/TIME IN : 05.12.2020 15:05
 ACCIDENT DATE : 05.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	1,025.20	20.00	820.16	one ✓
0002	04-01-0103-2296-A	I40VC RAIL ASSY-FR BUMPER	1	588.40	20.00	470.72	?
0003	04-01-0103-0638-G	I40VC BRKT ASSY-FR BPR UP	1	44.80	20.00	35.84	?
0004	04-01-0103-0640-G	I40VC BRACKET-FR BUMPER S	1	24.60	20.00	19.68	one ✓
0005	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	22.00	20.00	17.60	one ✓
0006	04-01-0103-2295-G	I40V3 LIP-FRONT BUMPER	1	152.00	20.00	121.60	ht ✓
0007	04-01-0103-0641-G	I40VC CARRIER ASSY-FR END	1	907.40	20.00	725.92	?
0008	04-01-0103-0572-A	I40VC PANEL ASSY-HOOD+	1	2,265.90	20.00	1,812.72	ht ✓
0009	04-01-0103-2164-A	I40V3 GRILLE ASSY-RADIATO	1	1,480.00	20.00	1,184.00	one ✓
0010	04-01-0103-2175-G	I40V3 SYMBOL MARK-H	1	129.50	20.00	103.60	one ✓
0011	04-01-0103-0573-A	I40VC PANEL-FENDER RH+	1	663.00	20.00	530.40	ht ✓
0012	04-01-0103-2934-A	I40V3 GUARD ASSY-FRONT WH	1	174.90	20.00	139.92	de ✓
0013	04-01-0103-0782-A	I40VC LAMP ASSY-HEAD RH#	1	1,800.00	20.00	1,440.00	one ✓

7,737.10
 -20%
 6,189.68

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 08.12.2020

Time: 12:28:02

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305437742
REGN NO : SHA5092B
MILEAGE : 000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 15.12.2016
DATE/TIME IN : 05.12.2020 15:0
ACCIDENT DATE : 05.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 10-01-0103-2126-G I40V3 PANEL ASSY-UNDER CO 1 334.60 20.00 267.68 7

0015 FNPS NO PLATE(S) WITH TRIM COV 1 N 55.00 2.00- 55.00 BA

SUB-TOTAL : 7,744.84

6,189.68
+ 55 Net
6,244.68

JOB NATURE

0000 L PANEL BEATING

850.00

0001 23-502 SPRAYPAINT ON AFFECTED AREA

650.00

0002 17-01 CHECK ALL LIGHTING

50.00

0003 20-00 TUFF COAT ON AFFECTED PARTS.

50.00

SUB-TOTAL : 1,600.00

1,360
7,604.68
- 20%
6,083.74

Tamplin 92495749
wp 2/12/20 C 4pm

4/5 Resumy after repair \$6,100/-
tamplin C/M and com.

04 days