

• 9/4/2020

RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBF4624T AND SMJ8722R ON 25/08/2020

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-20-106284

Date of Request: 07/09/2020

Your Ref No: DY.08.0036.2020

YONG, SEOW & LIM LEGAL LLP
83 Kim Yam Road
#03-01
Singapore 239378

Dear Sir/Madam,

Date of Accident: 25/08/2020
Vehicle No: SMJ8722R
Place of Accident: BLK 292 YISHUN ST 22 CARPARK
Involving Vehicle No: GBF4624T

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
GBF4624T	BLK 292 YISHUN ST 22 CARPARK	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBF4624T AND SMJ8722R ON 25/08/2020

admin admin <admin@ysllegal.com>

Tue 8/9/2020 9:42 PM

To: Teo, Ericweihong <Ericweihong.Teo@aig.com>

Cc: David Yong <dy@ysllegal.com>; Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>

Dear Sirs,

We refer to your email of 4 September 2020.

Kindly be informed that our Client confirmed that he did not change workshop.

Hope this clarifies.

Best regards,

Rayna Tan

For and on behalf of Mr David Yong

T: +65 62922388 | F: +65 62922088

Website: www.yssllegal.com

YSL LEGAL

ADVOCATES & SOLICITORS

YONG, SEOW & LIM LEGAL LLP

Address: 83 Kim Yam Road #03-01, Singapore 239378 (Entrance via Tong Watt Road)

CONFIDENTIALITY NOTICE

This communication contains information that is intended for the individual or entity named as recipient. Such information may be confidential and/or protected by legal professional privilege. If you are not the intended recipient, please take notice that any disclosure, copying, distribution or use of any part of the contents of this communication is strictly prohibited by law. If you have received this communication in error, please notify us immediately by return email to admin@ysllegal.com and delete this communication wholly from any storage media.

From: Teo, Ericweihong <Ericweihong.Teo@aig.com>

Sent: Friday, 4 September 2020 3:07 PM

To: admin admin <admin@ysllegal.com>

Cc: David Yong <dy@ysllegal.com>; Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBF4624T AND SMJ8722R ON 25/08/2020



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2020-09-11 15:07 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2019 Proofpoint, Inc. All rights reserved.

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Billing To: Zulfadly Bin Mohmad Abu Bakar
 c/o D's Graffiti Concepts Pte Ltd
 10 ang mo kio ind park 2A
 Amk autopoint #03-13
 Singapore 568047

Invoice no.: TP20080028

Date: 15 OCT 2020

Vehicle no: SMJ8722R

Model : MERCEDES BENZ C180

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 28 AUG 2020 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 620.00
2	Photography Services Develop photographs Storage of digital photographs	
3	To submit report by hand.	
4	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
	TOTAL :	\$ 620.00

Notes :

All cheque payment should be "crossed" and made payable to "Automax Survey".
 Please contact us if there are further enquiries on the invoice.

Official Stamp

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP20080028

Date: 15 OCT 2020

*Zulfadly Bin Mohmad Abu Bakar
c/o D's Graffiti Concepts Pte Ltd
10 ang mo kio ind park 2A
Amk autopoint #03-13
Singapore 568047*

THIRD PARTY SURVEY ACCIDENT OCCURED ON 25 AUG 2020

Workshop Name and Address

D's Graffiti Concepts Pte Ltd
10 ang mo kio ind park 2A
Amk autopoint #03-13
Singapore 568047

As per your instruction dated 28 AUG 2020
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
SMJ8722R

1. VEHICLE PARTICULARS

Registration No : SMJ8722R
Model : MERCEDES BENZ C180
Year / Capacity : May 2013/ 1590 cc
Chassis No : WDD2040312A833022

Engine No : 27491030039879
Mileage : 195 688 km
Colour : Metallic Black

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	215/65/R17	Michelin	9.00 mm	Sport
REAR O/S :	215/65/R17	Michelin	9.00 mm	Sport
FRONT N/S :	215/65/R17	Michelin	9.00 mm	Sport
REAR N/S :	215/65/R17	Michelin	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front side portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 07 working days to complete
5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SMJ8722R

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
-----	-------------------	-----------	---------------------------------	------------------------------------

List Items

1 pc	Front bumper	bent	\$ 1,850.00	\$ 1,850.00
10 pcs	Front bumper clips	necessary	\$ 129.00	\$ 129.00
1 pc	Front bumper sponge	deformed	\$ 286.60	\$ 286.60
1 pc	Front bumper tow cover	deformed	\$ 143.50	\$ 143.50
1 pc	Front bumper side retainer	bent	\$ 88.00	\$ 88.00
1 pc	Front bumper side bracket	bent	\$ 64.50	\$ 64.50
1 pc	Head Lamp	bend/distorted	\$ 2,339.00	\$ 2,339.00

	Parts Sub-Total	\$ 4,900.60	\$ 4,900.60
Discount	10.00%	\$ 490.06	\$ 490.06
		\$ 4,410.54	\$ 4,410.54

Vehicle Number : SMJ8722R

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
-----	-------------------	-----------	---------------------------------	------------------------------------

Special Nett Items

1 pc	Front bumper daylight	electronically shocked	\$ 250.00	\$ 250.00
------	-----------------------	------------------------	-----------	-----------

Special Nett Sub-Total	\$ 250.00	\$ 250.00
------------------------	-----------	-----------

Spare Parts Total	\$ 4,660.54	\$ 4,660.54
-------------------	-------------	-------------

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare PartsTotal c/f	\$ 4,660.54	\$ 4,660.54
1	To check wiring system	\$ 180.00	\$ 150.00
2	To tuff coat affected areas	\$ 180.00	\$ 150.00
3	To respray affected areas	\$ 1,600.00	\$ 1,400.00
4	To renew damaged parts, straighten and repair front chassis member and aligned all parts	\$ 1,600.00	\$ 1,400.00
5	To polish and coating for new paint	\$ 1,400.00	\$ 1,400.00
	Total	\$ 9,620.54	\$ 9,160.54

The repairer has agreed to undertake the repair under a part by part
Sum Basis. We have further adjusted the amount to a part by part
Sum Repair of :

\$ 7,800.00


Fong Kok Heng
Qualified Appraiser



