

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

05/12/2020

Owner: VFM PTE LTD

ESTIMATE TO REPAIR HONDA FREED HYBRID - SME5204R

1pc	rear tailgate	R	\$ 1,207.90	✓
1pc	rear tailgate "H" logo	R	\$ 50.25	—
1pc	rear tailgate "FREED" emblem	R	\$ 48.20	—
1pc	rear tailgate "HYBRID" emblem	R	\$ 65.10	—
1pc	rear windscreen moulding	R	\$ 181.80	—
1pc	rear tailgate outer chrome	My CM	\$ 321.70	✓
1pc	rear tailgate inner garnish	My CM	\$ 265.30	✓
1pc	rear tailgate inner lock	R	\$ 187.50	—
1pc	rear tailgate inner rubber	DIS / DENTED NN R	\$ 168.50	30% SN * ✓
1pc	rear tailgate inner handle	Sn	\$ 27.50	X 50% SN
2pcs	rear taillamp lower bracket @\$85.50	Sn	\$ 171.00	X
1pc	rear bumper 828-90	R	\$ 991.20	—
2pcs	rear bumper side retainer 1 @\$121.25	Sn	\$ 242.50	X
2pcs	rear bumper side retainer 2 @\$181.25	Sn	\$ 362.50	X
1pc	rear bumper towing cover	Sn	\$ 23.80	X
1pc	rear bumper centre beam	DIS N/A	\$ 180.50	✓
1pc	rear end panel 507-20	R	\$ 623.70	—
1pc	rear end panel inner garnish	R	\$ 100.90	—
2pcs	rear end panel side panel @\$390.80	MTG CRA R My CM	\$ 781.60	✓
1pc	rear float panel	R	\$ 1,019.60	X
2pcs	rear fender inner garnish @\$1120.70 0476-00	My CM R	\$ 2,241.40	✓
			\$ 9,262.45	
less 20%			\$ 1,852.49	
			\$ 7,409.96	
1set	reverse sensor	Shen s.nett	\$ 280.00	2005N
1set	rear number plate & casing	Sn s.nett	\$ 50.00	X
remove & refix rear windscreen glass			\$ 120.00	✓
tuffkote			\$ 180.00	600 80
sealant			\$ 80.00	400
wiring			\$ 150.00	200
spray painting			\$ 1,600.00	800 900
labour charges			\$ 1,600.00	900
Total			\$ 11,469.96	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____



India.
08/12/20
Kenneth.

Not Authorised
21 Sep 8 4900h
Recovery After Paint

6 days