

ComfortDelGro Engineering

205 Braddell Road S(579701)

	ACCIDENT F	REPAIR ESTIMATES	
Our Ref:			
Type of Claim	Third Party - GAS	Vehicle No.	SG5109B
à-		Make & Model	VOLVO B9TL 9.4L
		Year of Manufacture	2016
		Chassis No.	<u>YV3S4P926G178270</u>
Ins Company : _	CHINATAIPING INS	Engine No.	
Excess : _	NA	Policy No.	D-19094111MFBP
Date of Accident	30/11/2020	Time of Accident	17:10
Suggested Days of Rep	pair :	In-house Vehicle Ass	essor
Repair Estimate	s	Case Owner	Chan Foo Heng/Patrick
		Signature	*. *0
Parts (a) Cost / List Pri	ice Items \$-	Contact No	~ =
Less	10% \$-	Operations	
Total of Cost	t/List \$-	63837369 – Chan Foo l chanfh@cdge.com.sg	Heng / Sam Tan
		samtan@cdge.com.sg	
(b) Nett Price Ite	ms <u>\$-</u>	Patrick Tia – 6383744 patricktia@sparkcarca	
Less _			
Total of Nett	Item		
(c) Special Nett	Items \$-		
Total Parts Cost (App	endix A)\$-		
Labour (Appendix B)	\$1,420.00		
Total Repair Cost	<u>\$1,420.00</u>		
The above total will be	subjected to 7% G.S.T.		
Name of Course	AT-		
Name of Surveyor	(B)		

Name of Surveyor

Company
Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair

(c) Resurvey

Required / Not Required

(d) Excess

(e) Signature of surveyor

Date:

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

<u>Labour</u>

Vehicle No. :	SG5109B	Case Owner	: Chan Foo Heng/Patrick			
Make & Model :	VOLVO B9TL 9.4L	Year of Manufacture	2016			

Fact.	•		
S/No	Labour Description	Estimated Price	Adjusted Price
1	TO REMOVE /REPAIR AND REALIGN ON FRONT LH BUMPER,	\$500.00	- 11100
	CORNER REFLECTOR COVER AND REALIGN AFFECTED AREAS	4000.00	
2	TO PUTTY ,RESPRAY ON FRONT LH BUMPER COVER,REFLECTOR	\$800.00	
	LH ,LH SIDE DOME AND AFFECETD AREAS	700000	
	,		
3	CHECK LIGHTING AND WIRING	\$120.00	
		* 1.201.00	
		1	
-			
+			
-			
<u> </u>			
		-	
			-

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No	3	SG5109B	Case Owner	3	Chan Foo Heng/Patrick
Make & Model	:	VOLVO B9TL 9.4L	Year Manufactu	re :	2016
Chassis No	***	YV3S4P926G178270	Engine No	3	0
Sales Order	00520	 ,	Supplier	:	
Order By	8		Type of Claim	:	Third Party - GAS

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1			FIICE	Frice	Filce	3/14	Surveyor
2							-
3							-
4							
5							1
6							
7							
8							+
9		-1-1					
10							
11		1 1					
12		1 1					
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.