

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20013601/R1ES3Q2
Date: 07/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MPC0002902_02
Claimant Vehicle No :	SGT6446U	Insured Vehicle No :	SJL2866Z
Date of Loss:	06/12/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0002620

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGT6446U	Engine No:	1NZX871278
Make & Model:	TOYOTA VIOS, 1.5 J (A)	Chassis No:	MR053HY9305102233
Reg. Date:	10/02/2009 (Man. Year: 2009)	Odometer:	143879 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,021.25	3,974.70	-953.45	-31.56
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,075.00	1,075.00	0.00	0.00
Paintwork Labour	652.80	652.80	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,760.05	5,713.50	-953.45	-20.03
Approved Total (Overridden) (S\$)		4,500.00		

(S\$)	4,760.05	4,500.00	260.05	5.46
+ GST 7.00/7.00% (S\$)	333.20	315.00	18.20	5.46
Nett Amount (S\$)	5,093.25	4,815.00	278.25	5.46
+ Loss of Use (7.5 x S\$60.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		5,272.49		
Global Sum Settlement (S\$)		5,250.00		

INSPECTION

Date of Assignment:	08/12/2020	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	09/12/2020	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah)
Estimated Period of Repair:	7.0 days		Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3
			Singapore 159722

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2021)
Parts:	143	TOYOTA VIOS 1.5 J (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGT6446U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*CLIP FASTENING (NPA)	Not Necessary	0.00 FL	*- FL
2	1	NA	*CLIP FASTENING (NPA)	Not Necessary	0.00 FL	*- FL
3	1	NA	*L/R DOOR	Bent	967.40 FL	*967.40 FL
4	1	NA	*L/R DOOR SEAL	Necessary	195.20 FL	*195.20 FL
5	1	NA	*L/R DOOR TRIM FRONT	Necessary	67.50 FL	*67.50 FL
6	1	NA	*L/R SIDE PANEL	Repair	985.40 FL	*- FL
7	1	NA	*L/R SPRING LEG	Bent	332.10 FL	*332.10 FL
8	1	NA	*L/R WHEEL HUB/BRG	Bent	455.30 FL	*455.30 FL
9	1	NA	*LWR REAR WINDOW MLDG (NPA)	Not Necessary	0.00 FL	*- FL
10	1	NA	*R/R SPRING LEG	Not Necessary	332.10 FL	*- FL
11	1	NA	*R/R WHEEL HUB/BRG (NPA)	Not Necessary	0.00 FL	*- FL
12	1	NA	*REAR AXLE SUBFRAME	Bent	0.00 FL	*2,882.10 FL
13	1	NA	*REAR SCREEN FIX SET (NPA)	Not Necessary	0.00 FL	*- FL
14	1	NA	*REAR WINDOW MOULDING (NPA)	Not Necessary	0.00 FL	*- FL
15	1	NA	*SUNDRY PARTS (NPA)	Not Necessary	0.00 FL	*- FL
16	1	NA	*L/R TYRE	Serviceable	220.00 FS	*- FS
17	1	NA	*L/R Wheel	Scratched	300.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,855.00	5,199.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	833.75	1,224.90
Total Parts (\$\$)	3,021.25	3,974.70

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	485.00	485.00
2	Total Paint Materials	New	167.80	167.80
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	1,075.00	1,075.00
Gross Labour Cost (S\$)			1,727.80	1,727.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >