

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618 Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO.: FBH 1669Z

DOA : 10/09/2020

MAKE/MODEL : YAMAHA JUPITER 135

S/No	DESCRIPTION	AMOUNT
1	CENTER COWLING <i>cut ✓</i>	\$95.00
2	FRONT COWLING LH <i>cut ✓</i>	\$130.00
3	L/H SIGNAL LIGHT <i>cut ✓</i>	\$65.00
4	COWLING BRACKET <i>bt ✓</i>	\$85.00
5	HANDLER BAR <i>bt ✓ ?</i>	\$95.00
6	HANDLER BRACKET <i>bt ✓ ?</i>	\$85.00
7	CLUTCH LEVER <i>cut ✓ ?</i>	\$25.00
8	UNDLER BRACKET <i>bt ✓ ?</i>	\$185.00
9	STEERING CON <i>nei ✓ ?</i>	\$130.00
10	FORK INNER TUBE X 2 <i>bt ✓ ?</i>	\$170.00
11	FORK OIL SEAL X 2 <i>nei ✓ ?</i>	\$40.00
12	FORK OIL <i>nei ✓ ?</i>	\$40.00
13	FRONT WHEEL SHAFT <i>bt ✓ ?</i>	\$30.00
14	FRONT WHEEL RIM <i>bt ✓ R</i>	\$285.00
15	FRONT BRAKE DISC <i>bt ✓ K</i>	\$165.00
16	GEAR PEDAL <i>bt ✓</i>	\$85.00
17	L/H FRONT FRONT REST <i>bt ✓</i>	\$48.00
18	FOOTREST BAR <i>bt ✓ ?</i>	\$85.00
19	L/H MIRROR <i>cut ✓</i>	\$35.00
20	REAR BOX <i>cut ✓</i>	\$285.00
21	BOX BRACKET <i>nn x</i>	\$150.00
22	IU <i>cut ✓</i>	\$170.00
23	IU BRACKET <i>bt ✓</i>	\$35.00
24	TRANSPORT <i>40</i>	\$60.00
25	LABOUR <i>250</i>	\$400.00
26		
27	<i>Tanji 97445749</i>	
28	<i>wp 10/12/2020 6pm</i>	
29	<i>4/5 Resurvey after repair</i>	
30	<i>Tanji 97445749</i>	
31	<i>04 days</i>	
32	<i>2368</i>	
33	<i>410 - 2131-20</i>	
34	<i>290</i>	
35	<i>2421.20</i>	
36	<i>4581950</i>	
37	<i>04 days</i>	
Total :		\$2,978.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: