

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 14 Dec 2020

Preliminary Advice

Insured Vehicle No	: SKB2771D		
TP Vehicle No	: SLU7435E	Accident Date	: 02/12/2020
Make	: MAZDA 3	Assignment Date	: 09/12/2020
Date of Inspection	: 11/12/2020	Est. Duration of Repair	: 11
Inspection At	: TRANS EUROKARS PTE LTD - TANJONG PENJURU (HQ) 27A TANJONG PENJURU SINGAPORE 609042		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,403.70
Revised Amount	:S\$	10,721.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,721.90
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :