



## Section A - Accident Details

Registration Number	SHC4574Z
Case Reference Number	TAX/12/20/2016
Registration Date	10/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	MAH HAN CHIEH
Type of Accident	Head To Side
Accident Date and Time	5/12/2020 2:15 PM
Accident Reported Date and Time	7/12/2020 2:18 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109066
Special Instruction to ARC, if any	TOWED \$60 / LEFT REAR PORTION
Prepared Date and Time	7/12/2020 4:35 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

## Section B - Summary of Repair Estimates

## Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$2,052.00	\$700.00
Total Spare Part Cost	\$6,623.81	\$2,828.58
Total Other Cost	\$1,896.20	\$963.76
<b>TOTAL COST</b>	<b>\$11,248.01</b>	<b>\$4,892.34</b>
<b>Lump Sum Total</b>	<b>\$11,250.00</b>	<b>\$4,900.00 (L/S)</b>
Number of Repair Days	6.0	5.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / China Taiping
ARC / Surveyor Sign Off Date	15/12/2020 2:05 PM	15/12/2020 9:55 AM
Signature		
Remarks	Total number of repair days = 5 days. SUP = +2 days.	L/S, after paint photo

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2101-0068	Invoice Number	
Quotation Date	07.01.2021	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	\$676.00	\$400.00 ✓
Total Labour	\$676.00	\$400.00

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00 ✓
TO REPSRAY REAR DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00 ✓
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
Total Spray Painting & Panel Beating	\$2,052.00	\$700.00 ✓

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX REAR UNDERCARRIAGE	\$350.00	\$200.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00 ✓
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$84.00	\$60.00 ✓
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$742.20	\$593.76 ✓
Total Other Costs	\$1,896.20	\$963.76

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	0.00	\$458.60	0.00	\$0.00	Replace	Not Given
		90467-07211	BUMPER CLIPS	0.00	\$2.10	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Not Given
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		89997-30070	ANTENNA ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63665592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 07/01/2021

User ID PohSuan

	52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X SUC
	52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given	X SUC
	76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X SUC
	76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	X SUC
	58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X SUC
	51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given	X SUC
	67004-47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair	X R
	68780-52031	HINGE LOWER LHR, DOOR	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X SUC
	68760-20122	HINGE UPPER LHR, DOOR	0.00	\$81.70	0.00	\$0.00	Replace	Not Given	X SUC
	68630-47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X SUC
	61602-47091	FENDER RR/LH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	X R
		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	/ NEC
		STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	/ NEC
	81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Not Given	X SUC
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X SUC
	42611-47140	WHEEL DISC	1.00	\$1,484.20	25.00	\$1,113.15	Replace	Replace	/ Cut
	42450-47040	WHEEL HUB REAR	0.00	\$489.40	0.00	\$0.00	Replace	Not Given	X SUC
	75852-47900	MOULDING BODY, LH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given	X SUC
Total				\$7,643.84		\$1,202.55			

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		42101-12171	REAR CROSS MEMBER	1.00	\$2,621.50	25.00	\$1,966.13	Replace	Replace
		42450-47040	WHEEL HUB REAR	1.00	\$489.40	25.00	\$367.05	Replace	Replace
Total					3,110.90		2,333.18		

BT  
Jam

3535.73 /  
- 20%  
2828.58 /  
+ 400.00 /  
+ 1663.76 /  
4892.34

215  
\$4,900

5 days