



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/12/2020

User ID : TuckFoo

Section A - Accident Details

Registration Number	SHC4574Z
Case Reference Number	TAX/12/20/2016
Registration Date	9/10/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	MAH HAN CHIEH
Type of Accident	Head To Side
Accident Date and Time	12/5/2020 2:15 PM
Accident Reported Date and Time	12/7/2020 2:18 PM
Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109066
Special Instruction to ARC, if any	TOWED \$60 / LEFT REAR PORTION
Prepared Date and Time	12/7/2020 4:35 PM
Chassis Number	
Fileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$1,674.00	\$500.00
Total Spare Part Cost	\$4,757.26	\$957.72
Total Other Cost	\$1,546.20	\$703.76
TOTAL COST	\$8,653.46	\$2,561.48
Lump Sum Total	\$8,650.00	\$2,800.00
Number of Repair Days	6.0	3.0 <i>3 days</i>
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	07/12/2020 4:50 PM	08/12/2020 4:45 PM
Signature	x	
Remarks		L/S, after paint photo

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/12/2020

User ID : TuckFoo

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR LH REAR PORTION	\$676.00	\$400.00
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY REAR BUMPER	\$378.00	\$0.00
O RESPRAY BUMPER BEAM	\$180.00	\$0.00
O RESPRAY REAR FENDER LH	\$378.00	\$200.00
O RESPRAY REAR DOOR LH	\$378.00	\$200.00
O RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
O RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,674.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
O DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
O REPLACE SUNDRY PARTS	\$100.00	\$0.00
O REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
O TRANSFER DOOR MECHANISM	\$120.00	\$0.00
O CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
O WASH AND VACUUM	\$60.00	\$0.00
OWING CHARGE	\$84.00	\$0.00
O PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET)	\$742.20	\$593.76
Total Other Costs	\$1,546.20	\$703.76

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	0.00	\$458.60	0.00	\$0.00	Replace	Not Given X Svc
		90467-07211	BUMPER CLIPS	0.00	\$2.10	0.00	\$0.00	Replace	Not Given X Svc
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace / Net
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Not Given X Svc
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X Svc
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given X Svc
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X Svc
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X Svc
		52582-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given X Svc
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given X Svc
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given X Svc
		58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given X Svc
		51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given X Svc
		67004-47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair X R
		68780-52031	HINGE LOWER LHR, DOOR	0.00	\$72.20	0.00	\$0.00	Replace	Not Given X Svc



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/12/2020

User ID : TuckFoo

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		68760-20122	HINGE UPPER LHR, DOOR	0.00	\$81.70	0.00	\$0.00	Replace	Not Given X Svc
		68630-47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given X Svc
		61602-47091	FENDER RR/LH	1.00	\$766.80	100.00	\$0.00	Replace	Repair X R
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace X / N-g
			STICKER DECAL 65558888	1.00	\$21.60	25.00	\$16.20	Replace	Replace / N-g
		81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Not Given X Svc
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X Svc
		42611-47140	WHEEL DISC	1.00	\$1,484.20	25.00	\$1,113.15	Replace	Replace / C/H
		42450-47040	WHEEL HUB REAR	0.00	\$489.40	0.00	\$0.00	Replace	Not Given X Svc
		75852-47900	MOULDING BODY, LH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given X R
total					\$7,643.84		\$1,197.15		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
total									