

Per 2 pm.

**Repair Estimate**

Date :03/12/2020

Reference: Hyundai

Make: Ioniq

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLS 5004P  
 CHASSIS NO. KMHC851CVHU041214  
 ENGINE NO.: G4LEHU425028

Name of insured : GOH SIEW CHOO

Date of accident.: 01/12/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

**Parts**

<u>No.</u>	<u>Qty</u>	<u>Part Description</u>	<u>Price (SGD)</u>
1	1	REAR BUMPER <i>del</i>	520.00 ✓
2	1	REAR BUMPE REINFORCEMENT <i>new</i>	350.00 X.
3	1	REAR BUMPE TOW COVER <i>new</i>	26.00 +
4	1	REAR BUMPER MOULDING <i>new</i>	30.00 +
5	1	GUIDE,RR BUMPER CTR <i>new</i>	60.00 X
6	1	GUIDE,RR BUMPER INR LH <i>new</i>	50.00 X
7	1	GUIDE,RR BUMPER INR RH <i>new</i>	50.00 X
8	1	REAR END PANEL <i>new</i>	540.00 +

Parts Total: 1,626.00

Less 20%: 325.20

Total : 1,300.80

**Labour**

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	950.00 <i>200</i>
2	Carry out spray painting on affected area rear portion (rear bumper, rear end panel & rear taillid)	800.00 <i>250</i>
3	To disconnect front & rear wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	80.00 <i>30</i> <i>530</i>
4	Carry out remove and reinstall rear reverse sensor (due to accident repair)	120.00 <i>50</i>

Labour Total : 1,950.00

*Admin*  
*P/P 10/12/20*  
*03 Dec*


**Others**

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	Rear Number Plate & holder <i>Dented</i>	45.00 ✓
2	Rear Bumper Clip Set <i>mc</i>	40.00 ✓
3	Reverse sensor set <i>mc</i>	350.00 +
<b>Other Total:</b>		<b>435.00</b>

**TOTAL:** 3,685.80  
**GST ( 7%):** 258.01  
**GRAND TOTAL :** 3,943.81

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

  
Service Advisor  
Ronnie Tan  
DID: 6844 1985 Fax:6844 5185

*Adham Lj*  
*P/P #12/20*

*03849*

*Supplementary : 320 x 80% = 256*

*total: 1287*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

## 1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 ( South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

### TAX INVOICE

China Taiping Insurance (Singapore) Pte. Ltd  
3 Anson Road #16-00 Springleaf Tower  
Singapore 038986

GST Ref. No M2-0111811-5

Vehicle No: SLS 5004P  
Chassis No : KMHC851CVHU041214  
Engine No:G4LEHU425028

Invoice No:

Invoice Date:

#### DESCRIPTION

#### AMOUNT

##### Parts

No.	Qty.	Description	Price (SGD)
1	1	REAR BUMPER	520.00

##### Supplementary Items

2	1	REAR BUMPER BLACK MOULDING	320.00
---	---	----------------------------	--------

Total: 840.00  
Less 20%: 168.00  
Parts Total : 672.00

##### Labour

No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair / replacement parts	200.00
2	Carry out spray painting on affect area rear portion (rear bumper)	250.00
3	To disconnect front wire harness of electrical component to facilitate repair, reconnect & check electrical function after repair	30.00
4	Carry out remove and reinstall rear reverse sensor (due to accident repair)	50.00

Labour Total : 530.00

##### Others

No.	Other Description	Price (SGD)
1	Rear Number Plate & holder	45.00
2	Rear Bumper Clip Set	40.00

Other Total: 85.00

Total : 1287.00  
GST (7%) 90.09  
Grand Total: 1377.09

Yours Faithfully,

Ronnie Tan  
Service Advisor  
Tel: 68441985 Fax:68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1 ST AUTOWORKS PTE LTD".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.