

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 10 Dec 2020

**Preliminary Advice**

Vehicle No	: SKB2771D	Accident Date	: 02/12/2020
Make	: MERCEDES-BENZ C200	Policy No.	: DMPCSNA00125642002
Assignment Date	: 09/12/2020	Excess	: S\$750.00
Date of Inspection	: 10/12/2020	Est. Duration of Repair	: 6
Inspection At	: KEE YONG AUTOMOBILE SERVICE (HQ) NO.160 SIN MING DRIVE #03-09 SIN MING AUTOCITY SINGAPORE 575722		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,163.00
Revised Amount	:S\$	7,401.73
Check Items (Estimated)	:S\$	2,070.57
Total	:S\$	9,472.30

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	32,002.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,998.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :