

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 31 Mar 2021

## **Preliminary Advice**

|                    |                                                                                                      |                         |              |
|--------------------|------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : XD8162H                                                                                            |                         |              |
| TP Vehicle No      | : SLT7494P                                                                                           | Accident Date           | : 07/12/2020 |
| Make               | : HONDA VEZEL                                                                                        | Assignment Date         | : 10/12/2020 |
| Date of Inspection | : 15/03/2021                                                                                         | Est. Duration of Repair | : 4          |
| Inspection At      | : N-51 AUTOMOTIVE PTE LTD (HQ)<br>BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |                         |              |

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 7,506.48 |
| Revised Amount              | :S\$ | 4,271.36 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 4,271.36 |
|                             |      |          |
| Lump Sum Repair             | :S\$ | 3,400.00 |

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Survey on WP