

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 88550267

TP Chinn
Denise

ESTIMATE

Repair Code : CLM16584

Date in : 07/12/2020

Vehicle Num. : SLT7494P

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31220213/LEB5920223

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehd</i>	1	762.70	✓ 762.70
REAR BUMPER REFLECTOR L/R <i>new</i>	2	141.10	✗ 282.20
REAR BUMPER SIDE RETAINER L/R <i>m</i>	2	23.00	✓ 46.00
REAR BUMPER UNDER COVER <i>Rehd</i>	1	250.00	✓ 250.00
REAR END PANEL <i>Repair</i>	1	415.60	✗ 415.60
REAR END PANEL BUZZLE SENSOR <i>Crashed</i>	1	85.20	✓ 85.20
REAR END PANEL INNER TOP GARNISH <i>new</i>	1	98.00	✗ 98.00
REAR TAILGATE <i>Dented</i>	1	953.30	✓ 953.30
REAR TAILGATE 'HYBRID' EMBLEM <i>2</i>	1	75.80	✓ 75.80
REAR TAILGATE 'LOGO' EMBLEM <i>1 new</i>	1	25.00	✓ 25.00
REAR TAILGATE 'VEZEL' EMBLEM <i>1 new</i>	1	56.20	✓ 56.20
REAR TAILGATE HINGES L/R <i>new</i>	2	50.00	✗ 100.00
REAR TAILGATE INNER PULL HANDLE <i>2 new</i>	1	27.50	✗ 27.50
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	2	18.50	✗ 37.00
REAR TAILGATE INNER TRIM BOARD <i>new</i>	1	153.40	✗ 153.40
REAR TAILGATE LOCK STRIKER <i>new</i>	1	27.50	✗ 27.50
REAR TAILGATE MECHANISM LOCK <i>Dented</i>	1	180.00	✓ 180.00
REAR TAILGATE OUTER GARNISH <i>Crashed</i>	1	220.00	✓ 220.00

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 88550267

ESTIMATE

Repair Code : CLM16584

Date in : 07/12/2020

Vehicle Num. : SLT7494P

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31220213/LEB5920223

REAR TAILGATE REFLECTOR INNER BLACK GASKET L/R	<i>neu</i>	2	38.50	+	77.00
REAR TAILGATE REFLECTOR L/R	<i>neu</i>	2	413.20	+	826.40
REAR TAILGATE WEATHER STRIP	<i>neu</i>	1	96.80	+	96.80
REAR TAILGATE WINDSCREEN MOULDING L/R	<i>neu</i>	2	50.00	<i>80</i>	100.00
REAR TAILGATE WINDSCREEN MOULDING T/L	<i>neu</i>	2	50.00	<i>80</i>	100.00
Subtotal before discount					4,995.60
Percentage discount 20%					999.12
Sub-total 1					3,996.48
REAR BUMPER CLIPS - SET	<i>neu</i>	1	50.00	<i>30</i>	50.00
REAR BUMPER REVERSE SENSOR	<i>damd</i>	1	280.00	<i>20</i>	280.00
REAR TAILGATE CAMERA	<i>cond</i>	1	800.00	<i>380</i>	800.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	<i>neu</i>	1	50.00	+	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	<i>neu</i>	1	40.00	<i>20</i>	40.00
REAR TAILGATE WINDSCREEN SEALANT	<i>neu</i>	1	80.00	<i>60</i>	80.00
Subtotal before discount					1,300.00
Percentage discount 0%					0.00
Sub-total 2					1,300.00
Parts-total					5,296.48

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 88550267

ESTIMATE

Repair Code : CLM16584

Date in : 07/12/2020

Vehicle Num. : SLT7494P

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31220213/LEB5920223

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

50 80.00

To remove, reinstall tailgate windscreen

120 150.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

40 100.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

400 900.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1330 600 800.00

To apply anti-rust chemical on repaired and replaced panel.

40 100.00

To remove, reinstall tailgate mechanism and check for function

✓ 80.00

Labour Total

2,210.00

Parts & Labour Total

7,506.48

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G
4/5 15/12/20 -
04 Days

Total: 4271.36

4/5: 341c ✓