


Section A - Accident Details

Registration Number	SHB5976X
Case Reference Number	TAX/12/20/2017
Registration Date	27/7/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	WONG LOONG HOI
Type of Accident	Side Swipe
Accident Date and Time	4/12/2020 2:00 PM
Accident Reported Date and Time	7/12/2020 3:03 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109067
Special Instruction to ARC, if any	LEFT PORTION
Prepared Date and Time	8/12/2020 8:48 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$200.00
Total Spray Cost	\$2,988.00	\$1,050.00
Total Spare Part Cost	\$6,866.33	\$150.66
Total Other Cost	\$920.00	\$120.00
TOTAL COST	\$11,788.33	\$1,520.66
Lump Sum Total	\$11,800.00	\$1,500.00 (L/S)
Number of Repair Days	7.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	08/12/2020 5:01 PM	08/12/2020 4:42 PM
Signature		
Remarks		L/S, after pant photo

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2012-0302	Invoice Number	
Quotation Date	24.12.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$200.00
Total Labour	\$1,014.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$2,988.00	\$1,050.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$920.00	\$120.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
		53802-47050	FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
		53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given
		53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Not Given
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63885592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 24/12/2020

User ID PohSuan

42611-- 47140	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	R
75852- 47900	MOULDING BODY, LH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given	X Svc
65632- 47041	SILL MEMBER PLATE RR/LH	0.00	\$57.50	0.00	\$0.00	Replace	Not Given	X Svc
67002- 47070	DOOR FRT/LH	1.00	\$894.40	100.00	\$0.00	Replace	Repair	R
	STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	Nec
68740- 12120	HINGE LOWER LHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Not Given	X Svc
68720- 15151	HINGE UPPER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given	X Svc
68610- 47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X Svc
67004- 47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair	R
	PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	Nec
68780- 52031	DOOR HINGE LOWER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X Svc
68760- 20122	DOOR HINGE UPPER RR/LH	0.00	\$81.70	0.00	\$0.00	Replace	Not Given	X Svc
68630- 47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X Svc
61602- 47091	FENDER RR/LH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	R
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	Nec
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	Nec
65638- 47021	FENDER LINER R/LH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given	X Svc
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X Svc
42611- 47140	WHEEL DISC	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X Svc
52159- 47905	BUMPER REAR	0.00	\$458.60	0.00	\$0.00	Replace	Not Given	X Svc
52576- 47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X Svc
52592- 47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given	X Svc
76088- 47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X Svc
	PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X Svc
87940- 47310	MIRROR ASSY, LH	1.00	\$1,224.90	100.00	\$0.00	Replace	Old Damage	X Svc
81740- 52040	MIRROR LAMP LH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given	X Svc
87945- 74010	COVER, OUTER MIRROR, LH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given	X Svc
Total			\$11,276.48		\$188.33			X Svc

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

188.33 ✓

- 20%

150.66 /
+ 200.00 /
+ 1170.00 /

1520.66 /

L/S \$1500 /- /
3 days