

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

Attn: Rasul

Final Bill

8 days.

**TOYOTA****TAX INVOICE**

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		M/S Uni-Crane Pte Ltd 29 Tuas Avenue 11 #02-03 Singapore 639089		
			Document No. 38053822				
			Document Date 22/01/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDY231R	TLMKY S5	20/08/2020	GBK5010G	10428	58685	65OD/GBK5010G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTFAT35YX0K215215		1KDB038786	60	Francis Cher T S	15/12/2020	15.27	23/12/2020 8.31
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMCVSNW00074792000 ACC DATE:04.12.20 DRIVE IN : 04.12.20 EXCESS:\$350 DATE-IN: DATE SURVEY:11.12.20 NO OF REPAIR DAYS:8 days BY:RASUL (LKK) AUTHORISED ON:15.12.20	*			50.00	
2	L	BP-LPO SUPPLY REGN PLATE (PO#)	0263			80.00	
3	S	BP-SUBLET SUPPLY SEALANT (NETT)	0742			100.00	
4	S	BP-SUBLET REPLACE AND REFOCUS HEADLAMP.	0742			180.00	
5	S	BP-SUBLET RESET AND REPROGRAMME ECU.	0742			180.00	
6	S	BP-SUBLET REMOVE AND REINSTALL FRT DASH BORAD ASSY TO ASSIST REPAIR.	0742			1296.00	
7	S	BP-SUBLET REMOVE AND REINSTALL FRT W/SCREEN TO ASSIST REPAIR.	0742			450.00	
8	S	BP-SUBLET REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, FRT PANEL ASSY, L/F MIRROR AND AFFECTED PORTION OF CAR.	0742			2880.00	
9	S	BP-SUBLET SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	0742			1770.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

**TOYOTA****TAX INVOICE**

Account Details		Account No.	Customer Details				
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	M/S Uni-Crane Pte Ltd 29 Tuas Avenue 11 #02-03 Singapore 639089				
		Document No. 38053822					
		Document Date 22/01/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDY231R	TLMKY S5	20/08/2020	GBK5010G	10428	58685	65OD/GBK5010G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTFAT35YX0K215215		1KDB038786	60	Francis Cher T S	15/12/2020	15.27	23/12/2020 8.31
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
10	V	EXC Excess element of insurance repair to be paidby the insured party	8888			-350.00	
11	1	T52101-37985 BUMPER SUB-ASSY, FR	1.00	748.90		748.90	
12	2	T53111-37A01 B1 GRILLE, RADIATOR	1.00	595.20		595.20	
13	3	T75311-25100 PLATE, FR NAME, NO.1	1.00	63.40		63.40	
14	4	T55700-37350 COWL ASSY	1.00	1194.30		1194.30	
15	5	T55078-37110 COVER SUB-ASSY, FR	1.00	311.80		311.80	
16	6	T81150-37660 HEADLAMP ASSY, LH	1.00	1178.70		1178.70	
17	7	T75315-37080 ORNAMENT, RADIATOR	1.00	70.50		70.50	
18	8	T87905-37122 ARM SUB-ASSY, OUTER	1.00	600.10		600.10	
19	9	T56121-25040 FRONT W/SCREEN MLDG,	1.00	369.40		369.40	
20	0	T52012-37170 ARM SUB-ASSY, FR	1.00	262.20		262.20	
21	1	T87968-0W010 HOLDER, MIRROR,	1.00	80.10		80.10	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		12,110.60		
			Labour		GST 7.00%		
			Sublet		847.74		
			Lubrication/Fluid		Less		
			Others		0.00		
				Amount Due		12,958.34	

Customer Copy