

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC6/AIG20013630/AGS3Q2

Date:

14/06/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100504866

Claimant Vehicle No : SLE3000L

Insured Vehicle No :

SLM2607B

Date of Loss: 09/12/2020

Nature of Claim:

TP

Claim No:

1847715885SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE3000L

Make & Model: KIA SORENTO, 2.4 GDI HID S/R (A)

Engine No:

G4KJFH752344

Reg. Date: 18/05/2016 (Man. Year: 2015)

Chassis No:

KNAPH813MG5165434

Colour: Brown

Odometer:

106320 km

Engine Capacity: 2359 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19

Rear Tyre Size:

235/55 R19

Front Left Side: Hankook 6 mm

Rear Left Side:

Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side:

Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	19,156.78	8,226.57	10,930.21	57.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,280.00	1,100.00	3,180.00	74.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,436.78	9,326.57	14,110.21	60.21
Approved Total (Overridden) (S\$)		7,400.00		

(S\$)	23,436.78	7,400.00	16,036.78	68.43
+ GST 7.00/7.00% (S\$)	1,640.57	518.00	1,122.57	68.43
Nett Amount (S\$)	25,077.35	7,918.00	17,159.35	68.43
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
Nett Liability (S\$)		8,518.00		

INSPECTION

Date of Assignment: 10/12/2020

Date Inspected: 10/12/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Cas Garage Pte Ltd (HQ)
No.1, Kaki Bukit Ave 6, #02-22 Autobay
Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	845.60 FL	*645.00 FL
2	1		*FRONT BUMPER LOWER	Deformed	825.70 FL	*618.00 FL
3	1		*FRONT BUMPER LOWER SKIRT	Repair	365.30 FL	*- FL
4	1		*FRONT BUMPER LIP	Repair	125.80 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Cracked	256.30 FL	*256.30 FL
6	2		*FRONT BUMPER RETAINERS	Necessary	171.40 FL	*171.40 FL
7	1		*FRONT BUMPER SPONGE	Cracked	285.60 FL	*137.00 FL
8	1		*FRONT BUMPER LOWER ARM	Bent	204.70 FL	*204.70 FL
9	1		*FRONT BUMPER REINFORCEMENT	Dented	589.60 FL	*589.60 FL
10	1		*FRONT BUMPER TOP GARNISH	Cracked	229.60 FL	*229.60 FL
11	2		*FRONT BUMPER SIDE BRACKETS	Not Necessary	173.80 FL	*- FL
12	1		*FRONT BUMPER TOW COVER	Not Necessary	68.70 FL	*- FL
13	1		*FRONT BUMPER FOGLAMPS	O/S Cracked	597.20 FL	*298.60 FL
14	1		*FRONT BUMPER FOGLAMPS COVERS	O/S Cracked	291.80 FL	*145.90 FL
15	2		*FRONT FENDER INNER COWLING	Not Necessary	331.60 FL	*- FL
16	1		*FRONT FOGLAMPS COVERS GARNISH	O/S Cracked	397.00 FL	*198.50 FL
17	1		*FRONT NUMBER PLATE BASE	Cracked	78.90 FL	*78.90 FL
18	1		*FRONT BUMPER SENSORS (4 PCS)	Damaged (1 PCS ONLY)	902.80 FL	*225.70 FL
19	4		*FRONT BUMPER SENSORS HOLDERS	Not Necessary	279.20 FL	*- FL
20	2		*FRONT BUMPER NOZZLE	Not Necessary	491.80 FL	*- FL
21	2		*FRONT BUMPER NOZZLE COVERS	Not Necessary	137.00 FL	*- FL
22	1		*FRONT BUMPER UNDERCOVER	Not Necessary	385.40 FL	*- FL
23	1		*FRONT GRILLE	Cracked	867.30 FL	*680.00 FL
24	1		*FRONT GRILLE LOGO	Necessary	95.60 FL	*95.60 FL
25	1		*HEADLAMPS	O/S Cracked	4,491.20 FL	*2,245.60 FL
26	2		*HEADLAMPS BRACKETS	Not Necessary	196.80 FL	*- FL
27	1		*FRONT SUPPORT PANEL	Not Necessary	897.60 FL	*- FL
28	1		*AIR CON CONDENSER	Dented	945.80 FL	*945.80 FL
29	2		*AIR CON PIPE	Not Necessary	593.60 FL	*- FL
30	1		*FRONT RADIATOR	Cracked	925.30 FL	*925.30 FL
31	1		*FRONT RADIATOR TOP HOSE	Not Necessary	185.60 FL	*- FL
32	1		*FRONT RADIATOR BOTTOM HOSE	Not Necessary	178.90 FL	*- FL
33	1		*FRONT RADIATOR FAN ASSY	Not Necessary	956.80 FL	*- FL
34	1		*FRONT RADIATOR SPARE TANK	Not Necessary	186.90 FL	*- FL
35	1		*FRONT WASHER TANK	Not Necessary	145.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT RESONATOR BOX	Not Necessary	225.30 FL	*- FL
37	1		*FRONT BONNET	Not Necessary	1,485.60 FL	*- FL
38	1		*FRONT BONNET LOCK	Not Necessary	245.60 FL	*- FL
39	1		*FRONT RADIATOR AIR GUIDES	Cracked	187.50 FL	*187.50 FL
40	1		*FRONT HORN	Damaged	128.30 FL	*128.30 FL
41	1		*SET FRONT NUMBER PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
42	1		*SET FRONT BUMPER TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
43	1		*SET FRONT FENDER INNER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
44	1		*SET FRONT BUMPER UNDERCOVER CLIPS	Not Necessary	30.00 FS	*- FS
45	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
46	1		*SET RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,254.20	9,127.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,097.42	900.73
Total Parts (\$\$)	19,156.78	8,226.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS ,REPLACE BEAT ,WELD ,REALIGN AND ALIGN ALL PARTS	New	1,800.00	500.00
2	TO RESPRAY AFFECTED AREAS	New	1,800.00	400.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	0.00
4	TO REMOVE/REPLACE FRONT SENSORS AND DISTANCE SETTLING	New	150.00	50.00
5	TO CONDUCT WIRING CHECK ON FRONT HEADLAMP AND SETTLING	New	180.00	30.00
6	TO REMOVE /REFIT /REPLACE FRONT CONDENSER AND TOP UP GAS	New	150.00	120.00
Gross Labour Cost (\$\$)			4,280.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >