



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20013632/AUvd3q2	
			Date: 18/02/2021	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	FBH 2967G	Veh. Inspected	SKA 1991Y	
Policy No.	D20MTMC01003018	Coverage (\$)	0.00	
Claim No.	CMTD2003591/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	09/12/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA ALPHARD	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	JTEGD21H808252871	Colour	BLACK	
Odometer	217772 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	WEST LAKE	6 mm	
L/H Front Tyre	215/60 R17	WEST LAKE	6 mm	
R/H Rear Tyre	215/60 R17	WEST LAKE	6 mm	
L/H Rear Tyre	215/60 R17	WEST LAKE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	05/12/2020	Inspection Date	10/12/2020	
Survey held at	GREEN FOREST AUTOMOBILE 8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	