

GREEN FOREST AUTOMOBILE PTE LTD

SYLL S AUTO PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @KB
Singapore 415875

TP Somp

09th December 2020

Veron

JTEGD21H808252871

Accident date: 05th DECEMBER 2020

Estimated repair cost for vehicle no: SKA1991Y TOYOTA ALPHARD '2012

S/n	Qty	Items	U/price	Amount
1	2	Front head lamp <i>LH cracked</i>	\$2,150.10	\$4,300.20 <i>2150.10</i>
2	2	Front head lamp lower bracket <i>NE NE</i>	\$112.20	\$224.40 <i>X</i>
3	1	Front bumper <i>Distorted</i>		\$1,968.20 <i>895.</i>
4	2	Front bumper side bracket <i>LH New</i>	\$135.20	\$270.40 <i>135.20</i>
5	10	Front bumper clips <i>New</i>	\$5.00	\$50.00 <i>30</i>
6	1	Front bumper number plate <i>NE NE</i>		\$50.00 <i>X</i>
7	1	Front bumper reinforcement <i>Not rec</i>		\$852.10 <i>X</i>
8	1	front bumper reinforcement inner sponge <i>NE rec</i>		\$255.20 <i>X</i>
9	1	Front bumper center lower cover <i>3 NP</i>		\$295.10 <i>X</i>
10	1	Front bumper centre top garnish <i>3 rec</i>		\$158.20 <i>X</i>
11	1	Front bumper grille <i>Cracked</i>		\$315.20 <i>X</i>
12	2	Front Bumper Fog lamp <i>2</i>	\$255.30	\$510.60 <i>X</i>
13	2	Front Bumper Fog lamp cover <i>2 NP</i>	\$168.20	\$336.40 <i>X</i>
14	2	Front fog lamp side chrome <i>2 NP</i>	\$112.00	\$224.00 <i>X</i>
15	1	Front bumper towing cover <i>1 NP</i>		\$68.00 <i>X</i>
16	1	Front Grille <i>Cracked</i>		\$558.10 <i>X</i>
17	1	Front Grille emble logo <i>rec</i>		\$95.00 <i>X</i>
18	10	Front Grille clips <i>New</i>	\$5.00	\$50.00 <i>30</i>
19	1	front fender -LH <i>Repis</i>		\$958.00 <i>X</i>
Subtotal :-				\$11,537.10

Labour charges

To Check Wiring System

Panel beating

Spray painting

4208.60

3156.45

830

~~\$60.00~~ *30*

~~\$600.00~~ *300*

~~\$600.00~~ *500*

Subtotal :- \$1,260.00

Total :- \$12,797.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3986.45

h/s: 3.1K

OADwp