

JIT SEN MOTOR ,
10, ADMIRALTY STREET,
#01-10, NORTHLINK BUILDING,
SINGAPORE 757695.
TEL: 62578404, FAX 67556214

FBL 5407 R

7-Aug-2020

TEL :

CS.0079


MAKE AND MODEL: HONDA NC750

LUMP SUM SUPPLY AND REPAIR

1	MIRROR	/ CRU	\$140
2	FRONT FENDER	/ SCR	\$200
3	LOWER COWLING	/ CRU	\$300
4	FRONT RIM	X SVC	\$280
5	HANDER BAR	/ BT	\$85
6	BRAKE LEVER	/ BT	\$55
7	CONE BEARING	/ Nec	\$25
8	CONE SEAL	/ Nec	
9	FRONT FORK	X SVC	
10	FORK BLACKET	X SVC	
11	UPPER BLACKET	X SVC	
12	LABOUR CHARGE		\$180
13	TOWING FEE		\$50

1,135
- 10%
1,021.50
230
1,251.50
- 20%
1,001.20

L/S
\$1,000
Repair day 2 days



AMOUNT \$1,680.00