



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0957/2020/NS
DATE	:	7-Dec-20
WIP	:	61400

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MS TEO KAH SAN EMILIA
ADDRESS	:	54 DALVEY ROAD SINGAPORE 259454
TELEPHONE	:	HP +65 97411420
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800079147-01
VEHICLE NO	:	EN 3589 R
MODEL CODE	:	AUDI A5 COUPE 2.0 TFSI
MODEL YEAR	:	12/6/2018
ENGINE NO	:	CVK 061971
CHASSIS NO	:	WAUZZZF57JA101095
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	4-Dec-20
PLACE OF ACCIDENT	:	PIE TUAS BEFORE KPE EXIT



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE EN 3589 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	280
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.	S/N \$ 800.00	X
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIOCTR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HADLIGHTS, TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	500
5	TO RESPRAY FRONT BUMPER, BONNET AND HINGES.	\$ 2,700.00	550
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,172.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EN 3589 R

S/N PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT BUMPER <i>Regis</i>		\$	2,251.00	<i>x</i>
2 FRONT BUMPER FIXING PARTS		\$	402.00	<i>+</i>
3 FRONT BUMPER SECURING STRIP <i>2 new</i>	2	\$	70.00	<i>+</i>
4 FRONT BUMPER GRILLE - CENTRE		\$	194.00	<i>+</i>
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>		\$	225.00	<i>+</i>
6 FRONT BUMPER SPOILER <i>new</i>		\$	529.00	<i>+</i>
7 RADIATOR GRILLE <i>cracked</i>		\$	2,300.00	<i>✓</i>
8 ULTRASOUND SENSOR SUPPORT - LH/RH <i>?</i>	2	\$	102.00	<i>?</i>
9 RADIATOR GRILLE COVER - UPPER <i>new</i>		\$	187.00	<i>+</i>
10 FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>new</i>	2	\$	936.00	<i>+</i>
11 FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>		\$	123.00	<i>✓</i>
12 FRONT BUMPER CARRIER <i>new</i>		\$	795.00	<i>x</i>
13 FRONT BUMPER GUIDE SECTION - LH/RH <i>new</i>	2	\$	72.00	<i>+</i>
14 FRONT BUMPER TOP COVER <i>new</i>		\$	126.00	<i>+</i>
15 FRONT BUMPER BRACKET - LH/RH <i>new</i>	2	\$	424.00	<i>+</i>
16 CAUTION SIGN STICKER <i>new</i>	NEC	\$	14.00	<i>+</i>
17 AIRCON STICKER <i>new</i>	NEC	\$	8.00	<i>+</i>
18 LOCK CARRIER BRACKET <i>new</i>		\$	136.00	<i>x</i>
19 LOCK CARRIER BRACKET SUPPORT - LH/RH <i>new</i>	2	\$	56.00	<i>x</i>
20 FRONT PARKING AID SENSOR - INNER <i>new</i>	2	\$	484.00	<i>x</i>
SUB TOTAL SPARE PARTS	:	\$	9,434.00	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EN 3589 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 FRONT PARKING AID SEAL RING ?	4	\$	14.00	?
22 BONNET <i>new</i>		\$	2,817.00	+
23 BONNET ATTACHMENT PARTS		\$	121.00	+
24 BONNET LID HINGE - LH/RH <i>new</i>	2	\$	830.00	+
25 BONNET IMPACT PROTECTION - CENTRE		\$	27.00	+
26 BONNET IMPACT PROTECTION - LH		\$	28.00	+
27 BONNET IMPACT PROTECTION - RH		\$	27.00	+
28 BONNET STRIKER - LH/RH <i>new</i>	2	\$	100.00	+
29 BONNET LID LOCK	2	\$	423.00	+
30 BONNET LOCK CABLE - CENTRE		\$	57.00	+
31 BONNET RELEASE CABLE - CENTRE		\$	57.00	+
32 BONNET RELEASE LEVER		\$	13.00	+
33 LED HEADLIGHT - LH/RH	2	\$	15,624.00	+
34 LIFT CYLINDER - LH/RH	2	\$	392.00	+
35 LIFT CYLINDER CORRUGATED PIPE		\$	85.00	+
36 LOCK CARRIER		\$	1,004.00	+
37 COOLANT REGULATOR SUPPORT <i>Not</i>	2	\$	75.00	+
38 AIRCON CONDENSER <i>new</i>		\$	615.00	+
39 TEMPERATURE SENSOR BRACKET		\$	18.00	+
40 CHARGE AIR COOLER		\$	580.00	+
SUB TOTAL SPARE PARTS	:	\$	22,907.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EN 3589 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
41 RADIATOR		\$	837.00	X
42 READY MIX COOLANT	4	\$	91.00	X
43 RADIATOR AIR GUIDE - LH / RH OUTER	2	\$	62.00	X
44 RADIATOR AIR GUIDE - LH / RH INNER	2	\$	32.00	X
45 RADIATOR AIR GUIDE - UPPER		\$	16.00	X
46 RADIATOR AIR GUIDE - LOWER		\$	22.00	X
47 FRONT NO PLATE	S/N	\$	60.00	✓
48 SUNDRIES		\$	300.00	?
TOTAL SPARE PARTS	:	\$	33,761.00	
TOTAL LABOUR CHARGES	:	\$	10,172.00	
GRAND TOTAL	:	\$	43,933.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME

:

Adrian Ling

SURVEYED DATE

:

09/12/20

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 03 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT