

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20013641/DQF3Q2

Date: 13/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00095792001

**Claimant
Vehicle No :** SJX8396K

**Insured
Vehicle No :** GBJ2T

Date of Loss: 08/12/2020

Nature of
Claim: TP

Claim
No: SNM20D204722/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX8396K**

Make & Model: TOYOTA VIOS, 1.5 (A)

Engine No: 1NZY122201

Reg. Date: 15/07/2010 (Man. Year: 2010)

Chassis No: MR053HY9305174554

Colour: Maroon

Odometer: 112418 km

Engine Capacity: 1497 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15

Rear Tyre Size: 185/60R15

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,085.15	2,838.81	7,246.34	71.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	1,770.00	2,270.00	56.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,125.15	4,608.81	9,516.34	67.37
Approved Total (Overridden) (S\$)		3,650.00		
(S\$)	14,125.15	3,650.00	10,475.15	74.16
+ GST 7.00/7.00% (S\$)	988.76	255.50	733.26	74.16
Nett Amount (S\$)	15,113.91	3,905.50	11,208.41	74.16

INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 10/12/2020 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-
08 AMK AutoPoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2021)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX8396K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented/Bent	1,258.70 FL	*687.65 FL
2	1		*BOOTLID VIOS EMBLEM	Necessary	64.20 FL	*64.20 FL
3	1		*BOOTLID E EMBLEM	Necessary	54.37 FL	*54.37 FL
4	1		*BOOTLID TOYOTA LOGO	Necessary	70.20 FL	*70.20 FL
5	1		*BOOTLID TOP NO PLATE GARNISH	Not Necessary	278.20 FL	*- FL
6	2		*BOOTLID NO PLATE LAMP L+R	Not Necessary	113.96 FL	*- FL
7	1		*BOOTLID LOCK	Damaged	189.95 FL	*189.95 FL
8	1		*BOOTLID INNER LOCK	Not Necessary	215.97 FL	*- FL
9	1		*BOOTLID WEATHER STRIP	Deformed	275.35 FL	*138.00 FL
10	1		*REAR BUMPER	Dented	807.50 FL	*427.71 FL
11	2		*REAR BUMPER SIDE RETAINER L+R	Serviceable	184.66 FL	*- FL
12	1		*REAR BUMPER REFLECTOR L+R	O/s Cut/N/s Not Necessary	165.62 FL	*82.81 FL
13	1		*TAIL LAMP L+R	O/s Cracked/N/s Not Necessary	1,355.24 FL	*471.60 FL
14	2		*TAIL LAMP PANEL L+R	Not Necessary	410.00 FL	*- FL
15	1		*REAR END PANEL	Dented	871.89 FL	*570.30 FL
16	1		*REAR END PANEL TOP GARNISH	Mounting Cracked	230.76 FL	*230.76 FL
17	1		*REAR FENDER INNER TRIM L+R	O/s Torn/N/s Not Necessary	648.40 FL	*324.20 FL
18	2		*REAR FENDER L+R	O/s Repair/N/s Not Necessary	1,609.70 FL	*- FL
19	1		*SPARE WHEEL PANEL	Not Necessary	837.85 FL	*- FL
20	2		*SPARE WHEEL QUARTER PANEL L+R	Not Necessary	598.60 FL	*- FL
21	1		*SPARE WHEEL PANEL STYROFOAM	Not Necessary	214.00 FL	*- FL
22	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	314.38 FL	*- FL
23	1		*REAR EXHAUST PIPE	Not Necessary	875.60 FL	*- FL
24	1		*REAR EXHAUST MOUNTING	Not Necessary	80.00 FL	*- FL
25	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	249.50 FL	*- FL
26	1		*REAR KEYLESS SENSOR	Not Necessary	295.60 FL	*- FL
27	2		*TAIL LAMP SPONGE L+R	Torn/Necessary	150.00 FL	*80.00 FL
28	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
29	1		*SET REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS
30	1		*REAR END PANEL SEALANT	Necessary	70.00 FS	*40.00 FS
31	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*20.00 FS
32	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
33	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
35	1		*REAR BOOTLID CENTER MOULDING CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 13,190.20 3,686.75
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,105.05 847.94

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	10,085.15 2,838.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	New	300.00	100.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,400.00	800.00
3	TO RESPRAY NEW PAINTWORK ALL DAMAGED AREAS	New	1,400.00	700.00
4	TO RNR REAR EXHAUST TO FACILITATE REPAIRS	New	120.00	40.00
5	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	120.00	60.00
6	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
7	TO APPLY ANTI-RUST COATINGS ON ALL AFFECTED AREAS	New	300.00	40.00
8	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	200.00	0.00
Gross Labour Cost (\$\$)			4,040.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >