

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 10/12/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : HASHIM BIN JAMID

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTPV01004394

Accident Date : 05/12/2020

Vehicle No : SLM-6627-S

Make & Model : MITSUBISHI LANCER EX 1.6 AT LED TAIL L

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Nett Item			
1	FRONT BUMPER <i>De-</i>	858.00	
2	FRONT BUMPER RETAINER <i>neu</i>	58.00	
10	FRONT BUMPER CLIPS <i>neu</i>	50.00	
1	FRONT BUMPER LOWER GRILLE <i>cm</i>	94.00	
2	FRONT BUMPER BRACKET <i>neu</i>	52.00	
1	FRONT BUMPER CENTRE BRACKET <i>bt</i>	92.00	
1	FRONT BUMPER REINFORCEMENT <i>bt</i>	421.00	
1	FRONT BUMPER BEAM <i>bt</i>		
1	FRONT SUPPORT TOP COVER GARNISH <i>cm</i>	75.00	

Date : 10/12/2020

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : HASHIM BIN JAMID

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTPV01004394

Accident Date : 05/12/2020

Vehicle No : SLM-6627-S

Make & Model : MITSUBISHI LANCER EX 1.6 AT LED TAIL L

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
10	FRONT TOP COVER GARNISH CLIPS <i>neu</i>	50.00	
1	FRONT GRILLE <i>cm</i>	264.00	
2	FRONT GRILLE SIDE COVER RH/LH <i>MIS</i>	16.00	
1	FRONT BUMPER TOW COVER <i>mu</i>	46.00	
2	FOGLAMP GARNISH RH/LH <i>MIS</i>	84.00	
2	HEADLAMP RH/LH <i>cm</i>	1,596.00	
1	BONNET <i>bt</i>	879.00	
1	BONNET LOCK <i>bt</i>	72.00	
1	BONNET INSULATOR <i>de</i>	105.00	
10	BONNET INSULATOR CLIPS <i>neu</i>	50.00	

Date : 10/12/2020

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : HASHIM BIN JAMID

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTPV01004394

Accident Date : 05/12/2020

Vehicle No : SLM-6627-S

Make & Model : MITSUBISHI LANCER EX 1.6 AT LED TAIL L

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
2	BONNET HINGE ?	134.00	
1	BONNET RUBBER SEAL FRONT <i>re /</i>	37.00	
2	BONNET RUBBER STOPPER RH/LH <i>re /</i>	16.00	
1	BONNET STAND GROMMET X	8.00	
1	FRONT FENDER LH <i>bt /</i>	588.00	
1	FRONT FENDER RH <i>repair</i>	588.00	
20	FRONT FENDER SHIELD CLIPS X	100.00	
1	FRONT WINDSCREEN GLASS <i>ca /</i>	986.00	
1	FRONT WINDSCREEN MOULDING TOP <i>re /</i>	137.00	
1	FRONT WINDSCREEN MOULDING LOWER <i>re /</i>	72.00	

Date : 10/12/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : HASHIM BIN JAMID

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTPV01004394

Accident Date : 05/12/2020

Vehicle No : SLM-6627-S

Make & Model : MITSUBISHI LANCER EX 1.6 AT LED TAIL L

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT SUPPORT TOP PANEL <i>bt</i>	287.00	
1	FRONT SUPPORT LOWER PANEL <i>?</i>	459.00	
2	FRONT SUPPORT RH/LH <i>bt</i>	94.00	
2	HEADLAMP TOP PANEL RH/LH <i>bt</i>	176.00	
2	HORN UNIT <i>?</i>	192.00	
1	WIPER WASHER TANK <i>?</i>	91.00	
1	WIPER WASHER TANK NECK <i>?</i>	41.00	
2	FRONT CHASSIS END BRACKET RH/LH <i>bt</i>	118.00	
1	AIRCON CONDENSER <i>bt</i>	1,123.00	
1	AIRCON DISCHARGE PIPE <i>?</i>	292.00	

Date : 10/12/2020

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : HASHIM BIN JAMID

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTPV01004394

Accident Date : 05/12/2020

Vehicle No : SLM-6627-S

Make & Model : MITSUBISHI LANCER EX 1.6 AT LED TAIL L

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	AIRCON SUCTION PIPE ?	398.00	
1	RADIATOR <i>bt</i>	1,161.00	
2	RADIATOR TOP MOUNTING <i>na</i>	42.00	
1	RADIATOR TOP HOSE X	78.00	
1	RADIATOR FAN COWLING <i>cm</i>	263.00	
1	RADIATOR FAN MOTOR ?	422.00	
1	RADIATOR FAN BLADE ?	78.00	
1	RADIATOR SPARE TANK X	61.00	
1	FRONT AIR INTAKE DUCT X	157.00	
1	REAR BUMPER <i>de</i>	815.00	

Date : 10/12/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : HASHIM BIN JAMID

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTPV01004394 Accident Date : 05/12/2020

Vehicle No : SLM-6627-S Make & Model : MITSUBISHI LANCER EX 1.6 AT LED TAIL L

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
2	REAR BUMPER RETAINER <i>ren</i> ✓	54.00	
10	REAR BUMPER CLIPS <i>ren</i> ✓	50.00	
1	REAR BUMPER TOW COVER. <i>cut</i> ✓	41.00	
1	REAR BUMPER BEAM <i>bt</i> ✓	82.00	
2	REAR BUMPER REFLECTOR <i>coa</i> ✓	76.00	
1	REAR NUMBER PLATE LAMP <i>coa</i> - (1pc) ✓	154.00	
1	END PANEL <i>bt</i> ✓	506.00	
1	END PANEL TOP GARNISH <i>de</i> ✓	159.00	
1	BOOT LID <i>bt</i> ✓	793.00	
1	BOOT LID WEATHERSTRIP <i>ren</i> ✓	216.00	

Date : 10/12/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : HASHIM BIN JAMID

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTPV01004394 Accident Date : 05/12/2020

Vehicle No : SLM-6627-S Make & Model : MITSUBISHI LANCER EX 1.6 AT LED TAIL L

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	BOOT LID LOCK <i>bt</i>	72.00	
2	BOOT LID HINGE <i>FX</i>	188.00	
1	BOOT LID LOGO <i>na</i>	76.00	
1	EMBLEM - LANCER <i>na</i>	79.00	
1	EMBLEM - MIVEC <i>na</i>	65.00	
2	BOOT LID LAMP RH/LH <i>?</i>	394.00	
2	TAILLAMP RH/LH <i>sc</i>	744.00	
1	SPARE TYRE PANEL <i>bu</i>	721.00	
1	SPARE TYRE BOARD <i>act</i>	215.00	
1	STEERING AIRBAG <i>act</i>	2,409.00	

Date : 10/12/2020

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : HASHIM BIN JAMID

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTPV01004394

Accident Date : 05/12/2020

Vehicle No : SLM-6627-S

Make & Model : MITSUBISHI LANCER EX 1.6 AT LED TAIL L

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	AIRBAG CLOCK SPRING <i>AC</i> ✓	316.00	
1	PASSENGER AIRBAG. <i>AC</i> ✓	3,292.00	
1	AIRBAG CONTROL UNIT <i>AC</i> ✓	1,018.00	
2	AIRBAG IMPACT SENSOR <i>AC</i> ✓	592.00	
1	SEAT BELT RH <i>AC</i> ✓	687.00	
1	SEAT BELT LH <i>AC</i> ✓	687.00	
1	DASHBOARD <i>TBR</i> ✓	1,104.00	
1	FRONT CHASSIS PANEL	RESTORE	
1	FRONT FENDER RH	RESTORE	
2	REAR FENDER RH/LH	RESTORE	

Date : 10/12/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : HASHIM BIN JAMID

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTPV01004394

Accident Date : 05/12/2020

Vehicle No : SLM-6627-S

Make & Model : MITSUBISHI LANCER EX 1.6 AT LED TAIL L

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	28666.00	
	Discount 10% On Parts	(2866.60)	
<u>Special Nett Item</u>			
1	FRONT NUMBER PLATE <i>bt</i> ✓	35.00	
1	REAR NUMBER PLATE <i>bt</i> ✓	35.00	
1	FRONT WINDSCREEN SEALANT <i>neu</i> ✓	50.00	
1	IU BRACKET <i>neu</i> ✓	15.00	
1	COOLANT <i>neu</i> ✓	30.00	
1	ATF OIL ?	50.00	
1	REVERSE SENSOR <i>neu</i> ✓	220.00	

Date : 10/12/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : HASHIM BIN JAMID

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTPV01004394 Accident Date : 05/12/2020

Vehicle No : SLM-6627-S Make & Model : MITSUBISHI LANCER EX 1.6 AT LED TAIL L

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	END PANEL SEALANT <i>nm /</i>	50.00	
	Sub Total	485.00	
<u>Labour & Misc</u>			
	LABOUR TO FACILITATE REPAIR	3,000.00	<i>2000</i>
	TO RESPRAY FRONT AND REAR AFFECTED PORTIONS	2,000.00	<i>1600</i>
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	<i>30</i>
	TO REMOVE AND REFIT AIRBAG ASSY	250.00	<i>200</i>
	TO REMOVE AND REFIT DASHBOARD ASSY	250.00	<i>150</i>
	TO REPROGRAMME AND RESET AIRBAG ASSY	300.00	<i>200</i>

Date : 10/12/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : HASHIM BIN JAMID

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTPV01004394

Accident Date : 05/12/2020

Vehicle No : SLM-6627-S

Make & Model : MITSUBISHI LANCER EX 1.6 AT LED TAIL L

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	150.00	120
	RUST PROOFING	100.00	80
	TOWING CHARGES	50.00	
	Sub Total	6150.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Remarks:

16 days / Lump sum

SUB-TOTAL

GST 7.0 %

TOTAL

32,434.40

2,270.41

34,704.81

Surveyor's name: RASUL - Hp 90010068

Principal's name: HASHIM BIN JAMID

Survey Date & Time: 10/12/2020 @ 1350