



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
-		Ref:	CS/TP20013660/Utf3e2
FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 ON BEHALF OF ER YI MING		Date:	08/01/2021
		Code:	TP130
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	Veh. Inspected		FBR 4411C
Policy No.	Coverage (\$)		0.00
Claim No.	Excess (\$)		0.00
Assign From	Assign Date		10/12/2020
2. Vehicle Particulars & Condition			
Make & Model	HONDA ADV150	c.c	149
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	MH1KF6118LK022879	Colour	RED / BLACK
Odometer	6473 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	110/80-14	PIRELLI	7 mm
L/H Front Tyre			mm
R/H Rear Tyre	130/70-13	PIRELLI	7 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/11/2020	Inspection Date	10/12/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	