

ASS. REC. BY:

REF: EQ /

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

02 days

Res.: Yes or No

Lum Sum: _____

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: S/HO 9534BYr Regn: 05, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: ToyPrins

c.c.

1798Colour: mp. white / R

A/C:

Insured / Std / NI / NA

Sp. Reading: 228976

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: JD KB3FU003080123Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rlm / STD / Rlm or

Tyre Size: F: _____

R: _____

195 / 65 R 15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Pailun

Front

Rear

R/Bal. 9 mmR/Bal. 8 mmL/Bal. 9 mmL/Bal. 8 mmD.O.A. 8/12/20D.O.I. 9/12/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Acc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 GIA not ready

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + R.S. \$ _____

Fees: _____

Others: _____

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9534B**AAD2012-059***Not Notified
Mummy Bepoint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

09 DEC 2020

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD9534B

JTDKB3FU003080123

TOYOTA

PRIUS

08/12/2020

EQ

24/05/2019

PART		LIST	
1	COVER, REAR BUMPER	\$ CM	442.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ N	332.70 X
1	GUARD, REAR BUMPER, CENTER	\$ SL	576.30 X
1	RETAINER, REAR BUMPER SIDE, LH	\$ OI	116.50 ✓
1	FILLER, REAR BUMPER EXTENSION, LH	\$ SL	123.70
1	SEAL, REAR BUMPER SIDE, LH	\$ SL	88.50
1	LENS & BODY, REAR COMBINATION LAMP, LH	\$ SL	443.30
1	LENS AND BODY, REAR LAMP, LH	\$ SL	502.00
1	PANEL SUB-ASSY, BODY LOWER BACK	\$ N	651.00
1	PANEL SUB-ASSY, QUARTER, LH	\$ N	871.50
1	LINER, REAR WHEEL HOUSE, LH	\$ SL	139.80
1	PANEL SUB-ASSY, BACK DOOR	\$ N	1,147.80
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$ SL	925.60
1	WEATHERSTRIP, BACK DOOR	\$ SL	372.30
1	SPOILER, SUB ASSY, REAR	\$ SL	1,575.40
1	STAY ASSY, BACK DOOR, LH	\$ SL	242.50
1	STAY ASSY, BACK DOOR, RH	\$ SL	242.50
1	HINGE ASSY, BACK DOOR, LH	\$ N	61.00
1	HINGE ASSY, BACK DOOR, RH	\$ N	61.00
1	COVER, FLOOR UNDER, NO.1 (LH)	\$ SL	175.10
1	COVER, FLOOR UNDER, NO.2 (RH)	\$ SL	241.90
1	COVER, REAR FLOOR (CTR)	\$ SL	229.90
TOTAL		\$	8,916.00
25%		\$	2,229.00
		\$	6,687.00

Special Nett

1SET PARKING AID

\$ SL 700.00 X

Trans-cab Auto Services Pte Ltd

AAD2012-059

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9534B

1SET REAR BUMPER CLIP	\$	na	95.00	6612
2 WINDSCREEN SEALANT	\$	na	150.00	
1 WINDSCREEN MOULDING	\$	na	200.00	
1 WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	
1 REAR TAILGATE TOYOTA LOGO	\$	na	47.90	
1 REAR TAILGATE WORDING 'PRIUS'	\$	na	54.60	
1 REAR TAILGATE WORDING 'HYBRID'	\$	na	54.60	
1 REAR TAILGATE STICKER "Trans-Cab"	\$	na	80.00	
1 REAR TAILGATE STICKER "6555-3333"	\$	na	80.00	
1 REAR BUMPER PROTECTOR	\$	na	180.00	X
1SET REAR FENDER LINER CLIP	\$	na	85.00	
1SET REAR BUMPER RETAINER CLIP	\$	na	85.00	
1 REAR NUMBER PLATE WITH HOLDER	\$	na	140.00	
1SET TAILLAMP LOWER CLIP	\$	na	55.00	
1SET TAILLAMP UPPER CLIP	\$	na	55.00	
1 END PANEL TRIM CLIP	\$	na	65.00	
1 REAR SPOILER CLIP	\$	na	70.00	
TOTAL	\$		2,327.10	

TOTAL PARTS	\$	9,014.10
--------------------	-----------	-----------------

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	na	300.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	2001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	na	180.00	X

Trans-cab Auto Services Pte Ltd

AAD2012-059

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9534B

To conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators.

\$ *nn* 380.00 X
TOTAL \$ 10,290.00

Over All Total \$ 19,304.10

(PART-BY-PART) Repair Days***25 DAYS******2 days*****For Official Use**

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: