

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9534B**AAD2012-059***Not Authorised
Penny Bepoint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

09 DEC 2020

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD9534B

JTDKB3FU003080123

TOYOTA

PRIUS

08/12/2020

EQ

24/05/2019

PART		LIST	
1 COVER, REAR BUMPER	\$	<i>CM</i> 442.60	✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>N</i> 332.70	X
1 GUARD, REAR BUMPER, CENTER	\$	<i>SL</i> 576.30	X
1 RETAINER, REAR BUMPER SIDE, LH	\$	<i>SL</i> 116.50	✓
1 FILLER, REAR BUMPER EXTENSION, LH	\$	<i>SL</i> 123.70	} X
1 SEAL, REAR BUMPER SIDE, LH	\$	<i>SL</i> 88.50	
1 LENS & BODY, REAR COMBINATION LAMP, LH	\$	<i>SL</i> 443.30	
1 LENS AND BODY, REAR LAMP, LH	\$	<i>SL</i> 502.00	
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>N</i> 651.00	
1 PANEL SUB-ASSY, QUARTER, LH	\$	<i>N</i> 871.50	
1 LINER, REAR WHEEL HOUSE, LH	\$	<i>SL</i> 139.80	
1 PANEL SUB-ASSY, BACK DOOR	\$	<i>N</i> 1,147.80	
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>SL</i> 925.60	
1 WEATHERSTRIP, BACK DOOR	\$	<i>SL</i> 372.30	
1 SPOILER, SUB ASSY, REAR	\$	<i>SL</i> 1,575.40	
1 STAY ASSY, BACK DOOR, LH	\$	<i>SL</i> 242.50	
1 STAY ASSY, BACK DOOR, RH	\$	<i>SL</i> 242.50	
1 HINGE ASSY, BACK DOOR, LH	\$	<i>N</i> 61.00	
1 HINGE ASSY, BACK DOOR, RH	\$	<i>N</i> 61.00	
1 COVER, FLOOR UNDER, NO.1 (LH)	\$	<i>SL</i> 175.10	} X
1 COVER, FLOOR UNDER, NO.2 (RH)	\$	<i>SL</i> 241.90	
1 COVER, REAR FLOOR (CTR)	\$	<i>SL</i> 229.90	
TOTAL	\$	8,916.00	
25%	\$	2,229.00	
	\$	6,687.00	

Special Nett

1SET PARKING AID

\$ *SL* 700.00 X

Trans-cab Auto Services Pte Ltd**AAD2012-059**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9534B

1SET REAR BUMPER CLIP	\$	nn	95.00	66sa
2 WINDSCREEN SEALANT	\$	nn	150.00	} X
1 WINDSCREEN MOULDING	\$	nn	200.00	
1 WINDSCREEN INNER SPONGE SEAL	\$	nn	130.00	
1 REAR TAILGATE TOYOTA LOGO	\$	nn	47.90	
1 REAR TAILGATE WORDING 'PRIUS'	\$	nn	54.60	
1 REAR TAILGATE WORDING 'HYBRID'	\$	nn	54.60	
1 REAR TAILGATE STICKER "Trans-Cab"	\$	nn	80.00	
1 REAR TAILGATE STICKER "6555-3333"	\$	nn	80.00	
1 REAR BUMPER PROTECTOR	\$	nlp	180.00	
1SET REAR FENDER LINER CLIP	\$	nn	85.00	
1SET REAR BUMPER RETAINER CLIP	\$	nn	85.00	}
1 REAR NUMBER PLATE WITH HOLDER	\$	nn	140.00	
1SET TAILLAMP LOWER CLIP	\$	nn	55.00	
1SET TAILLAMP UPPER CLIP	\$	nn	55.00	
1 END PANEL TRIM CLIP	\$	nn	65.00	}
1 REAR SPOILER CLIP	\$	nn	70.00	
TOTAL	\$		2,327.10	
TOTAL PARTS	\$		9,014.10	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ nn 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 4 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 2000

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 4 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 4 180.00 X

Trans-cab Auto Services Pte Ltd**AAD2012-059**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9534B

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	102
To transfer of Fender fittings, attachments and perform water seepage test.	\$	ur 480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	4 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	4 250.00	X
Towing Fees	\$	4 150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	2201
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	4 170.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	4 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 220.00	X
To replace, refix and top up coolant for radiator	\$	4 170.00	X
To lift-up / out engine with gear box and refit.	\$	4 440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	4 380.00	X

Trans-cab Auto Services Pte Ltd

AAD2012-059

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9534B

To conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators.

	\$	<i>nn</i> 380.00	X
TOTAL	\$	10,290.00	

Over All Total	\$	19,304.10
-----------------------	----	------------------

(PART-BY-PART) Repair Days~~25 DAYS~~*2 days***For Official Use**

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)