



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC20013670/Gqd3n2 Date: 26/07/2021 Code: LPC2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	<b>Insured Veh.</b>		<b>Veh. Inspected</b>	SDQ 407Z
	<b>Policy No.</b>	Z20VP05026342	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	20/20/20/VP05/023991	<b>Excess (\$)</b>	500.00
	<b>Assign From</b>	GERALD POH	<b>Assign Date</b>	10/12/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	SUBARU OUTBACK 2.5	<b>c.c</b>	2498
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
	<b>Chassis No.</b>	JF1BS9KC2HG058767	<b>Colour</b>	WHITE
	<b>Odometer</b>	138843 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	225/60 R18	FALKEN	6 mm
	<b>L/H Front Tyre</b>	225/60 R18	FALKEN	6 mm
	<b>R/H Rear Tyre</b>	225/60 R18	FALKEN	6 mm
	<b>L/H Rear Tyre</b>	225/60 R18	FALKEN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	08/12/2020	<b>Inspection Date</b>	10/12/2020
	<b>Survey held at</b>	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147		
<b>5a. Remarks</b>				
	A) THE MARKET VALUE IS S\$76,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	