



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

LONPAC INSURANCE BHD

300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555

VEHICLE NO. : SDQ407Z

ACCIDENT DATE : 08-12-2020 18:15

THIRD PARTY REF. : SJN9965P

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SDQ407Z SUBARU OUTBACK

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT BONNET / BUC	490.00
2	1	FRONT BONNET LOCK / BT	80.00
3	2	FRONT BONNET HINGES@25.00 x repair ✓ BT	50.00
4	1	FRONT SUPPORT PANEL / BT	280.00
5	1	FRONT FENDER LH x repair ✓ BUC	145.00
6	1	FRONT FENDER SHIELD LH x repair	65.00
7	1	FRONT GRILLE / BR	360.00
8	1	FRONT GRILLE TOP GARNISH / CRA	30.00
9	4	FRONT GRILLE TOP GARNISH CLIP@2.00 / ncc	8.00
10	1	FRONT GRILLE EMBLEM / ncc	45.00
11	1	FRONT HEADLAMP LH / BR	1350.00
12	1	FRONT HEADLAMP LOWER BRACKET LH / BR	25.00
13	1	FRONT BUMPER / DE DE	300.00
14	1	FRONT BUMPER FOAM ? / BT (photo)	40.00
15	1	FRONT BUMPER REINFORCEMENT / Cut	190.00
16	1	FRONT BUMPER SIDE RETAINER LH / DE	10.00
17	1	FRONT BUMPER LOWER GRILLE / DE	35.00
18	1	FRONT BUMPER NOZZLE COVER LH / mis	35.00
19	1	FRONT BUMPER NOZZLE JET LH / mis	55.00
20	1	FRONT BUMPER TOP BEAM ?	15.00
21	1	FRONT BUMPER TOP RUBBER / SCR	18.00
22	1	FRONT BUMPER LOWER SKIRT / TN	120.00
23	10	FRONT BUMPER CLIP@2.00 / ncc	20.00
24	1	AIR CON CONDENSER ?	420.00
25	1	AIR CON FAN ASSY ?	260.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 51 Cooch Lane 12 Singapore 599547
Tel: (65) 6747 9540; 6473 5044 Fax: (65) 6748 1004; 6281 8022
E-mail: kyan@kfs.net; patrick@kfs.net
Branch: 1 Kaki Bukit Avenue 6 #01 308 Singapore 417881
Tel: (65) 6481 5150 Fax: (65) 6481 8681

VEHICLE NO. : SDQ407Z
ACCIDENT DATE : 08-12-2020 18:15
THIRD PARTY REF. : SJN9965P

#	QTY	PARTS DESCRIPTION	AMOUNT (SGD)
26	1	RADIATOR <i>2 / ceta</i>	44.00
27	1	RADIATOR TOP HOSE	22.00
28	2	RADIATOR TOP BRACKET@S15.00 ?	30.00
29	1	RADIATOR FAN COWLING ?	35.00
30	1	RADIATOR FAN BLADE ?	22.00
31	1	RADIATOR FAN MOTOR ?	140.00
			5,173.00
ADD 15 %			
TOTAL (A)			5,348.95

SPECIAL NETT ITEMS

1	1	FRONT NUMBER PLATE <i>/ BT</i>	31.00
TOTAL (C)			30.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	31.00	✓
2	1	TO REMOVE/REFIT/REFILL AIR CON GAS	30.00	✓
3	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	780.00	680
4	1	SPRAYPAINTING CHARGES	820.00	780
TOTAL (D)			1,710.00	

ESTIMATE TOTAL

7,688.95

Excess \$500

Not Authorised

Guo Qiang

8288 0282

10/12/2020.

5 Days.

part by mt.

before part photo