



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

LONPAC INSURANCE BHD

300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555

VEHICLE NO. : SDQ407Z

ACCIDENT DATE : 08-12-2020 18:15

THIRD PARTY REF. : SJN9965P

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SDQ407Z SUBARU OUTBACK

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT BONNET / <i>Buc</i>	490.00 ✓
2	1	FRONT BONNET LOCK / <i>BT</i>	80.00 ✓
3	2	FRONT BONNET HINGES@25.00 x repair ✓ <i>BT</i>	50.00 ✓
4	1	FRONT SUPPORT PANEL / <i>BT</i>	280.00 ✓
5	1	FRONT FENDER LH x repair ✓ <i>Buc</i>	145.00 ✓
6	1	FRONT FENDER SHIELD LH x repair ✓ <i>CRA</i>	65.00 ✓
7	1	FRONT GRILLE / <i>BR</i>	360.00 ✓
8	1	FRONT GRILLE TOP GARNISH x CRA X NN	30.00
9	4	FRONT GRILLE TOP GARNISH CLIP@2.00 / <i>nc</i>	8.00 ✓
10	1	FRONT GRILLE EMBLEM / <i>nc</i>	45.00 ✓
11	1	FRONT HEADLAMP LH / <i>BR</i>	1350.00 ✓
12	1	FRONT HEADLAMP LOWER BRACKET LH / <i>BR</i>	25.00 ✓
13	1	FRONT BUMPER / DE ✓ <i>DE</i>	300.00 ✓
14	1	FRONT BUMPER FOAM ✓ <i>CRA</i> <i>x BT (photo)</i>	40.00 ✓
15	1	FRONT BUMPER REINFORCEMENT	190.00 ✓
16	1	FRONT BUMPER SIDE RETAINER LH / <i>Cut</i>	10.00 ✓
17	1	FRONT BUMPER LOWER GRILLE / <i>DE</i>	35.00 ✓
18	1	FRONT BUMPER NOZZLE COVER LH / <i>mis</i>	35.00 ✓
19	1	FRONT BUMPER NOZZLE JET LH <i>x mis</i>	55.00 ✓
20	1	FRONT BUMPER TOP BEAM ✓ <i>CRA</i>	15.00 ✓
21	1	FRONT BUMPER TOP RUBBER / <i>SCR</i>	18.00 ✓
22	1	FRONT BUMPER LOWER SKIRT / <i>TN</i>	120.00 ✓
23	10	FRONT BUMPER CLIP@2.00 / <i>nc</i>	20.00 ✓
24	1	AIR CON CONDENSER ✓ <i>CUT</i>	420.00 180
25	1	AIR CON FAN ASSY <i>x NN</i>	260.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 51 Cooch Lane 12 Singapore 599547
Tel: (65) 6747 9540; 6473 5044 Fax: (65) 6748 1004; 6281 8022
E-mail: kyan@kfs.net; patrick@kfs.net
Branch: 1 Kaki Bukit Avenue 6 #01 Singapore 417881
Tel: (65) 6481 5150 Fax: (65) 6481 8681

VEHICLE NO. : SDQ407Z
ACCIDENT DATE : 08-12-2020 18:15
THIRD PARTY REF. : SJN9965P

#	QTY	PARTS DESCRIPTION	AMOUNT (SGD)
26	1	RADIATOR <i>2 / cef</i>	450.00 150
27	1	RADIATOR TOP HOSE <i>X NN</i>	22.00
28	2	RADIATOR TOP BRACKET @ \$15.00 <i>X NN</i>	30.00
29	1	RADIATOR FAN COWLING <i>X NN</i>	50.00
30	1	RADIATOR FAN BLADE <i>X NN</i>	35.00
31	1	RADIATOR FAN MOTOR <i>X NN</i>	140.00
			5,173.00 4066
			ADD 15 %
			775.95
			TOTAL (A)
			5,948.95 4675.9

SPECIAL NETT ITEMS

1	1	FRONT NUMBER PLATE <i>/ BT</i>	30.00
			TOTAL (C)
			30.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00 ✓
2	1	TO REMOVE/REFIT/REFILL AIR CON GAS	80.00 ✓
3	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	780.00 <i>680</i>
4	1	SPRAYPAINTING CHARGES	820.00 <i>780</i>

TOTAL (D)

1,710.00

ESTIMATE TOTAL

7,688.95

6872.65

Excess \$500

Not Authorised

Lim Qiang

8288 0282

10/12/2020.

5 Days.

part by mt.

before part photo