



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6743 5344 Fax: (65) 6748 1006, 6281 8428

Branch: 1 Kaki Bukit Avenue 6 #01-13 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

E-mail: ryan@kanfs.net/ patricia@kanfs.net

SOMPO INSURANCE (S) PTE LTD
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWER
SINGAPORE 048623

DATE: 13/4/2021

VEHICLE NO. : SDQ407Z
ACCIDENT DATE : 08-12-2020 18:15
THIRD PARTY REF. : SJN9965P

ATTN: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEHICLE SDQ407Z SUBARU OUTBACK

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT BUMPER REINFORCEMENT OUTER CRA	20.00 ✓
2	1	FRONT BUMPER ACTIVE GRILLE LOWER BR	280.00 ✓
3	1	FRONT BUMPER LOWER BRACKET BT	40.00 ✓
4	1	FRONT BUMPER NOZZLE PIPE BR	55.00 ✓
5	1	FRONT GRILLE BRACKET BT	40.00 ✓
6	1	FRONT UNDER COVER BR	110.00 ✓
			545.00
ADD 15%			81.75
TOTAL (A)			626.75 ✓
SUPPLEMENTARY TOTAL			626.75